

# **PRODUCT ADVISORY**

## **Data Sheet Specification Change for Intersil Product ISLA112P50\***

**Refer to:  
PA10063**

**Date: June 17, 2010**

June 17, 2010

To: Our Valued Intersil Customers

Subject: **Data Sheet Specification Change for Intersil Product ISLA112P50\***

This advisory is to inform you that Intersil has updated the data sheet specification for the ISLA112P50\* product. The changes remove the *Selectable Clock Divider* functionality provided by pin 16 (CLKDIV) of the device. The device pin configuration and pin descriptions have been updated to define pin 16 as a do no connect (DNC). All electrical tests, conditions, block diagrams, and verbiage associated with the clock divider functions have been removed. Modifications to the data sheet specification are complete. The updated data sheet is available on the Intersil web site at <http://www.intersil.com/data/fn/fn7604.pdf>.

Product affected: **ISLA112P50IRZ**

There have been no changes to the design (silicon) or the device itself. There will be no change in external marking of the packaged product.

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product manufactured to the same conditions used for material supplied today.

If you have concerns with this change notice, Intersil must hear from you immediately. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

A handwritten signature in blue ink that reads "Jon Brewster".

Jon Brewster  
Intersil Corporation

PA10063

CC: J. Touvell W. Choroco J. Messier M. Matta