

---

# **PRODUCT ADVISORY**

## **Data Sheet Specification Update for Intersil Product ISL34341\***

**Refer to:  
PA10106**

**Date: October 8, 2010**

October 8, 2010

To: Our Valued Intersil Customers

Subject: **Data Sheet Specification Update for Intersil Product ISL34341\***

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL34341\* products. The changes to the  $\theta_{JA}$  and  $\theta_{JC}$  values in the Thermal Information section align the data sheet with the product characteristics. Modifications to the data sheet specification incorporating the changes are complete. The updated data sheet is available on the Intersil web site at <http://www.intersil.com/data/fn/fn6827.pdf>.

Products affected: **ISL34341INZ ISL34341INZ-T13**

Data sheet specification changes are as follows:

Thermal Resistance	Current Value	New Value	Units
EPTQFP $\theta_{JA}$	33	<b>40</b>	°C/W
EPTQFP - $\theta_{JC}$	4.5	<b>12</b>	

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for screening of material supplied today.

If you have concerns with this change notice, Intersil must hear from you immediately. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

*Jon Brewster*

Jon Brewster  
Intersil Corporation

PA10106

CC: J. Touvell E. Lee K. Tucker