

PRODUCT ADVISORY

Bar Code Label Change for Intersil's UL Recognized Components

**Refer to:
PA12047**

Date: June 21, 2012

June 21, 2012

To: Our Valued Intersil Customers

Subject: **Bar Code Label Change for Intersil's UL Recognized Components**

This advisory is to inform you that Intersil has implemented the use of a new inner/intermediate bar code label for the packing/shipping of its UL (Underwriters Laboratory) recognized components. The inner/intermediate bar code label has been updated to include the electrical rating and UL recognized component mark. Examples of the current and new bar code labels are included on the next page for reference. Implementation of the new bar code label for packing/shipping began in May 2012.

Products affected:

| | | | |
|----------------|----------------|----------------|----------------|
| ISL61851ACBZ | ISL61851DCBZ | ISL61851GCBZ | ISL61851JCBZ |
| ISL61851ACBZ-T | ISL61851DCBZ-T | ISL61851GCBZ-T | ISL61851JCBZ-T |
| ISL61851AIBZ | ISL61851DIBZ | ISL61851GIBZ | ISL61851JIBZ |
| ISL61851AIBZ-T | ISL61851DIBZ-T | ISL61851GIBZ-T | ISL61851JIBZ-T |
| ISL61851BCBZ | ISL61851ECBZ | ISL61851HCBZ | ISL61851KCBZ |
| ISL61851BCBZ-T | ISL61851ECBZ-T | ISL61851HCBZ-T | ISL61851KCBZ-T |
| ISL61851BIBZ | ISL61851EIBZ | ISL61851HIBZ | ISL61851KIBZ |
| ISL61851BIBZ-T | ISL61851EIBZ-T | ISL61851HIBZ-T | ISL61851KIBZ-T |
| ISL61851CCBZ | ISL61851FCBZ | ISL61851ICBZ | ISL61851LCBZ |
| ISL61851CCBZ-T | ISL61851FCBZ-T | ISL61851ICBZ-T | ISL61851LCBZ-T |
| ISL61851CIBZ | ISL61851FIBZ | ISL61851IIBZ | ISL61851LIBZ |
| ISL61851CIBZ-T | ISL61851FIBZ-T | ISL61851IIBZ-T | ISL61851LIBZ-T |

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products. Customers may expect to receive shipments of product using either the current or new bar code labels until the depletion of existing inventory.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,




Jon Brewster
Intersil Corporation

PA12047

CC: J. Touvell G. Liang

PA12047 – Inner/Intermediate Bar Code Label

Current – Standard Label



New – Label (changed areas circled in red)

