

Product Advisory (PA)

Subject: Label correction for the listed Intersil HSYE-117* / DLA Standard Microcircuit Drawing (SMD) 5962-99547 products

Publication Date: 3/28/2017

Effective Date: 3/28/2017

Revision Description:

Initial Release

Description of Change:

This advisory is to inform you that Intersil has made corrections to the shipping labels for the following Intersil / DLA SMD Products:

| <u>Intersil Part Number</u> | <u>Standard Microcircuit Drawing</u> | <u>Intersil Part Number</u> | <u>Standard Microcircuit Drawing</u> |
|-----------------------------|--------------------------------------|-----------------------------|--------------------------------------|
| HSYE-117-8 | 5962-9954703QYC | HSYE-117RH-8 | 5962F9954701QYC |
| HSYE-117EH-Q | 5962F9954702VYC | HSYE-117RH-Q | 5962F9954701VYC |
| HSYE-117RH/PROTO | | | |

The update only pertains to the correction of the label, there is no change to the product.

Reason for Change:

The labels that have been affixed to the packaging for the listed products have shown the products to be Pb-Free, this is an error. The die attach for this package uses a solder based pre-form. Label change is detailed in appendix A.

Impact on fit, form, function, quality & reliability:

The change will have no impact on the form, fit, function, quality, or reliability of the devices.

Product Identification:

Product affected by this change is identifiable via Intersil's internal traceability system.

Qualification status: Not Applicable

Sample availability: 3/28/2017

Device material declaration: Available upon request

Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Intersil within 30 days of the publication date.

| For additional information regarding this notice, please contact your regional change coordinator (below) | | | |
|---|--|---|--|
| Americas: PCN-US@INTERSIL.COM | Europe: PCN-EU@INTERSIL.COM | Japan: PCN-JP@INTERSIL.COM | Asia Pac: PCN-APAC@INTERSIL.COM |

Appendix A:

{P}CUST P/N: 5962F9954701VYC



{1P}INTERSIL P/N: IISYE-117R11-Q



{1T}LOT NBR: G3W7CHF



Product of: UNITED STATES Chips From: UNITED STATES

{1D}:1705 {2D}: {Q}QTY:90 EA LLQ:90

MSL: PBT: (V)SUPPLIER:INTERSIL



Error in label, correct labeling below.

{P}CUST P/N: 5962F9954701VYC



{1P}INTERSIL P/N: HSYE-117RH-Q



{1T}LOT NBR: G3W7CHF



Product of: UNITED STATES Chips From: UNITED STATES

{1D}:1705 {2D}: {Q}QTY:90 EA LLQ:90

MSL: PBT: (V)SUPPLIER:INTERSIL

