

RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RZ*-A024A/E	Rev.	1.00
Title	Correction for incorrect description notice of GPTa external trigger input interrupt in RZ/T1 Group User's Manual Hardware.		Information Category	Technical Notification		
Applicable Product	RZ/T1 Group	Lot No.	Reference Document	RZ/T1 Group User's Manual Hardware Rev1.2 R01UH0483EJ0120 Rev.1.20		
		All lots				

Incorrect description of GPTa external trigger input interrupt in the RZ/T1 Group User's Manual Hardware Rev1.2. have been found. This document describes corrections for the incorrect description.

1. Detail of a correction

Page	Objects	Before correction	After correction
362	Table 12.3 Cortex-R4F/DMAC Interrupt Vector Table (7/9) Vector Number:214	ETGIP External trigger input (rising edge detection) interrupt	ETGIN External trigger input (falling edge detection) interrupt
	Table 12.3 Cortex-R4F/DMAC Interrupt Vector Table (7/9) Vector Number:215	ETGIN External trigger input (falling edge detection) interrupt	ETGIP External trigger input (rising edge detection) interrupt