

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
RenesasTechnology Corp.

Product Category	User Development Environment		Document No.	TN-EML-116A/EA	Rev.	1.0
Title	Limitation on Connecting the E6000/E8000 LAN Adapter (HS6000ELN01H) for E6000H Emulator		Information Category	Usage Limitation		
Applicable Product	HS6000ELN01H	Lot No.	Reference Document	E6000/E8000 LAN Adapter User's Manual (ADE-702-326 : Rev.1.0)		
		Serial No. 0001 to 0262				

Thank you for using our product.

Note that there is the following limitation on connecting the LAN adapter (HS6000ELN01H) to the E6000H emulator.

[Limitation]

When the E6000H series emulator is connected to the LAN adapter, the revision of the firmware written on the LAN adapter must be updated.

Serial numbers of the LAN adapter: 0001 to 0262

Note: The serial number is written on the label on the back of the product.

Updated revision: 'I' or later




Figure 1 Label on the Back of the Product

For serial numbers above, if the LAN adapter is connected to the emulator without upgrading the revision of the firmware, HEW will not be activated correctly.

The firmware of the current version operates normally with the E6000 or E8000 emulator.

When you need to update the revision, please contact the Renesas sales office.