Date: Feb. 21, 2024

RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RZ*-A0129A/E	Rev.	1.00
Title	RZ/G2L, RZ/G2LC Carton Label Correction of Packing Specifications, MSL code number is corrected.		Information Category	Technical Notification		
Applicable Product	RZ/G Series, RZ/G2L, RZ/G2LC Group R9A07G044LxxGBG R9A07G044CxxGBG	Lot No.	Reference Document			
		Before week code 2415		_		

This technical update describes MSL code number correction of Carton Label for RZ/G2L, RZ/G2LC Group.

[Summary]

MSL code number correction for Carton Label of RZ/G Series, RZ/G2L, RZ/G2LC Group products.

Carton Label is a label attached to the packing material of the products.

[Priority level]

Importance: "Normal"
Urgency: "Normal"

[Products]


RZ/G2L (R9A07G044LxxGBG)

RZ/G2LC (R9A07G044CxxGBG)




[Correction]

Current (from):



Correction (to):



[Description]

Corrected MSL code number of Carton Label.

 $\ensuremath{\mathsf{MSL}}$ code number is changed from MSL4 to MSL3.

Countermeasure lots are applicable from week code 2416.

[Reason for Correction]

General error correction.

- End of Document -