

RENESAS TOOL NEWS on February 1, 2005: RSO-E7_2-050201D

A Correction to Tiny/SLP E7 Emulator Additional Document for User's Manual

--Renesas Microcomputer Development Environment System H8 Family /
H8/300H Super Low Power Series Notes on Connecting the H8/38076RF

We notify a correction to Tiny/SLP E7 Emulator Additional Document for User's Manual as stated below.

1. Document Concerned

Tiny/SLP E7 Emulator Additional Document for User's Manual --Renesas Microcomputer Development Environment System H8 Family / H8/300H Super Low Power Series Notes on Connecting the H8/38076RF--(Document number REJ10B0125-0200H) included with the following product:

The E7 emulator HS0007TCU01H
(for the H8/300H Tiny, H8/300H SLP, H8/300L SLP, and R8C/Tiny series)

NOTE: the MCU concerned to this additional document are H8/38076RF and H8/38086RF.

2. Correction

Page 10, the second line in Table 4.2
Read Flash Memory H'C000 to H'CFFF for Flash Memory H'D000 to H'DFFF

NOTE:

The addresses H'C000--H'CFFF are reserved for the E7; the user is not allowed to use them.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be

included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.