

RENESAS TOOL NEWS on May 1, 2004: RSO-M3T-MR32R-040501D

Corrections to the Reference Manuals of Real-Time OSes M3T-MR32R

We notify corrections to the reference manuals of the M3T-MR32R real-time OSes for the M32R family MCUs as stated below.

1. Documents Concerned

The reference manuals included with the M3T-MR32R V.3.00 Release 1 through V.3.50 Release 2

2. Corrections

(1) Section 2.11.2, "ref_sys(Refer System Status)"

In the TSS_LOC row of the Value column in the sysstat table, read 3 for 2

(2) Section 3.6, "Common Constants and Packet Format of Structure"

For the statements from the beginning of the typedef struct t_regs definition up to the end of the typedef struct t_exc one (before the comment "Related to Implementation-Dependent System Call (Mailbox)," read as follows:

```
/* Register Information Packets
    when forced exception has occurred */
typedef struct t_regs {
    VW r0; /* Contents of R0 register at that time */
    VW r1; /* Contents of R1 register at that time */
    VW r2; /* Contents of R2 register at that time */
    VW r3; /* Contents of R3 register at that time */
    VW r4; /* Contents of R4 register at that time */
    VW r5; /* Contents of R5 register at that time */
    VW r6; /* Contents of R6 register at that time */
    VW r7; /* Contents of R7 register at that time */
    VW r8; /* Contents of R8 register at that time */
    VW r9; /* Contents of R9 register at that time */
    VW r10; /* Contents of R10 register at that time */
```

```

VW r11; /* Contents of R11 register at that time */
VW r12; /* Contents of R12 register at that time */
VW r13; /* Contents of R13 register at that time */
VW r14; /* Contents of R14 register at that time */
VW sp; /* Contents of SP register at that time */
VW accl; /* Contents of ACCL register at that time */
VW acch; /* Contents of ACCH register at that time */
VW acc1l; /* Contents of ACC1L register at that time
           (the value of FPSR when kernel for FPU used;
            indefinite except when kernels for FPU
              and M32Rx/D used) */
VW acc1h; /* Contents of ACC1H register at that time
           (indefinite except when kernel for M32Rx/D used) */
} T_REGS;

/* EIT Information Packets */
typedef struct t_reit {
    PSW psw; /* Contents of PSW register at that time */
    FP pc; /* Contents of PC at that time */
} T_EIT;

/* Exception Information Packets */
typedef struct t_exc {
    W exckind; /* kind of exception: always set to EXK_TER=2
              (forced exception) */
    UW exccd; /* exception code */
    ID tskid; /* task ID */
    UW exeenv; /* system status where exception has occurred:
              always set to TTE_TSK=0
              (task is under execution) */
} T_EXC;

```

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.