

RENESAS TOOL NEWS on September 1, 2004: RSO-E7-040901D

A Note on Using E7 Emulator Software

Please take note of the following problem in using the E7 emulator software:

- On debugging the R8C/Tiny MCU series (except the 16-KB ROM version)
-

1. Versions Concerned

E7 emulator software V.2.0.01, V.2.0.02, and V.2.1.00

2. Description

At debugging any MCU in the R8C/Tiny series (except the 16-KB ROM version), if the R5F21102, R5F21103, R5F21112, or R5F21113 is selected after establishing the communication between the E7 emulator and the E7 emulator software, the following problem occurs:

After writes to the flash memory for downloading a user program have started, a timeout error will arise in the High-performance Embedded Workshop, and the High-performance Embedded Workshop will become unmanageable.

3. Solution

This problem has already been resolved in the E7 emulator software V.2.3.01 or later. To update the E7 emulator software, please download its update program from **HERE**.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.