

RENESAS TOOL NEWS on September 1, 2005: RSO-E7_2-050901D

A Note on Using the E7 Emulator Software V.3.00 Release 00

Please take note of the following problem in using the emulator software for the E7 on-chip debugging emulator (the E7 emulator is used for the H8/300H Tiny, H8/300H Super Low Power, and H8/300L Super Low Power Series of MCUs):

- On Debugging Programs for the H8/300H Tiny, H8/300H Super Low Power, and H8/300L Super Low Power Series of MCUs
-

1. Product and Version Concerned

The E7 emulator software V.3.00 Release 00

2. Problem

The MCU names of the support MCU series (H8/300H Tiny, H8/300H Super Low Power, and H8/300L Super Low Power Series) added to those in V.2.0.01 cannot be displayed in the Device dropdown list in the Select Emulator Mode dialog box.*

- * To open this dialog box, click the Debug menu name and select the Connect command in the High-performance Embedded Workshop.

3. Condition

This problem occurs if the emulator software V.3.00 Release 00 is installed in the PC where V.2.0.00 or earlier resides.

4. Solution

This problem has already been resolved in the emulator software V.3.00 Release 01. So download the update program from Software Download Site and install it.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.