

RENESAS TOOL NEWS on August 3, 2006: 060803/tn1

A Note on Using the Real-Time OS HI1000/4 V.1.04 Release 00

We inform you of a problem found in the real-time OS HI1000/4 V.1.04 Release 00 and its solution. This product, used for the AE-5 series, H8SX family and the H8S family of MCUs, was revised on July 16, 2006.

1. Problem

If you type a correct serial number into the Confirm Serial Number page displayed during execution of the update program shown below, an error arises and you will not be able to update the program.

- HI1000/4 V.1.04 Release 00 Update (Source Code attached)
File name: hi1000_4_v10400_src_update.exe

2. Solution

The above update program has been rectified. So download the problem- fixed one from the download site.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.