

[Notes]

R20TS0651EJ0100

Rev.1.00

Jan. 16, 2021

Renesas Flash Programmer

Overview

When using the Renesas Flash Programmer, a software tool for programming flash memory, note the following.

1. Caution regarding an RPI file

1. Caution regarding an RPI file

1.1 Applicable Products

Renesas Flash Programmer V3.08.00

1.2 Applicable Devices

- RL78 family (excluding RL78/G10, RL78/G1M, and RL78/G1N)
- Power Management (battery management ICs)
- Renesas USB Power Delivery family (C30 group)
- Motor Driver/Actuator Driver ICs (motor control ICs)

1.3 Details

If you execute the [Program] or [Verify Flash Options] command using an RPI file on which no flash option is set, the command does not end normally and returns the following error:

"Error (E3000108): There is no data in the operation range."

1.4 Schedule for fixing the problem

This problem will be fixed in V3.08.01. This program will be available from January 20, 2021.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jan.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,
Koto-ku, Tokyo 135- 0061, Japan

www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.