[Notes]RX Family

R20TS0989EJ0100 Rev.1.00

Dec.16.23

Notes on using data flash with firmware update FIT

Outline

We are contacting you of the precautions to be taken when the firmware update FIT includes the data flash area as the target of the update.

1. Notes on using data flash with firmware update FIT

1.1 Outline

When the firmware update FIT includes the data flash area as the update target, the data flash area is not updated correctly.

1.2 Applicable Products

RX Family Firmware Update Module Firmware Integration Technology Rev.2.00 (R01AN6850xJ0200) is the target.

1.3 Applicable Devices

RX24T Group RX26T Group RX65N, RX651 Group

1.4 Details and Conditions

RX24T:

There is a problem with the RX24T demo program and the Renesas Image Generator parameter file for the RX24T included in the firmware update FIT. When using them, the data flash area cannot be included in the update target.

RX26T, RX65N, RX651:

There is a problem in the address calculation process of the data flash area in the firmware update FIT. As a result, the data flash area is not written or erased correctly.

1.5 Workaround

RX Family Firmware Update Module Firmware Integration Technology Rev. 2.01 (R01AN6850xJ0201) addresses this issue, so please use this product.

1.6 Schedule for Fixing the Problem

The countermeasures have been taken in Rev. 2.01.

R20TS0989EJ0100 Rev.1.00 Page 1 of 2
Dec.16.23

Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Dec.16.23	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061, Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

 $\hbox{@\,}2023$ Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.3