

RENESAS TOOL NEWS on October 1, 2014: 141001/tn11

Application Leading Tool for RX and Application Leading Tool for RL78 Revised

We have revised the Application Leading Tool for RX and the Application Leading Tool for RL78.

1. Products and Versions Concerned

The two Application Leading Tools have been revised as follows:

- (1) Application Leading Tool for RX
from V1.02.01 to V1.03.00
- (2) Application Leading Tool for RL78
from V1.03.00 to V1.04.00

2. Description of Revision

2.1 Application Leading Tool for RX

We have revised the common program of Applilet3 and according to this revision, we have given a new version to the product.

This updating has associated with the updating to CS+ from CubeSuite+, there is no change in the function.

2.2 Application Leading Tool for RL78

(1) Updating

We have revised the common program of Applilet3 and according to this revision, we have given a new version to the product.

This updating has associated with the updating to CS+ from CubeSuite+, there is no change in the function.

(2) A Problem Fixed

The following problem, of which we informed you in RENESAS TOOL NEWS Document No. 140816/tn1, has been fixed:

- With setting of P20 and P21 of port 2 (target: RL78/L1C group)

For details of the problem, see the following page:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=140816tn1>

3. Updating Your Product

Download the installer of the product from the following URL:

https://www.renesas.com/applilet_download

The installer will be available on this site from October 6.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.