

RENESAS TOOL NEWS on April 1, 2006: RSO-E6000-060401D

Four Emulator Software Packages for E6000 Emulators Revised

We have revised four emulator software packages for these E6000 emulators: HS2678REPI61H, HS2678EPI61H, HS3664EPI61H, HS3664EPI62H, HS3064BEPI61H, HS2214EPI61H, and HS2214EPI62H.

1. Summary

Four emulator software packages have been revised. The revised products, their versions to be updated, and descriptions of revision are explained below.

1.1 For the H8S/2300 and H8S/2600 MCU Series

Revised product:

The emulator software for the HS2678REPI61H and HS2678EPI61H emulators (spare and repair) revised to V.6.01 Release 00.

Versions to be updated:

V3.0.00--V.6.00 Release 00 (See Section 2.)

Descriptions of revision:

- (1) The High-performance Embedded Workshop included in the product updated to V.4.00.03.
- (2) The H8S/2362F MCU added to the support line.
- (3) Fixed the problem that the SDRAM interface cannot be used when the H8S/2373 or H8S/2373R MCU is targeted for debugging.

1.2 For the H8/300H Tiny MCU Series

Revised product:

The emulator software for the HS3664EPI61H (spare and repair) and HS3664EPI62H emulators revised to V.6.01

Release 00.

Versions to be updated:

V2.0.00--V.6.00 Release 00 (See Section 2.)

Descriptions of revision:

- (1) The High-performance Embedded Workshop included in the product updated to V.4.00.03.
- (2) The following MCUs added to the support line.
H8/36077, H8/36087F, H8/36087, H8/36086,
H8/36085, H8/36084, H8/36083, H8/36082,
H8/36109F, H8/36109, H8/36108, H8/36107,
H8/36064, H8/3687N, H8/3694N, H8/36094F,
H8/36094, H8/36093, H8/36092, H8/36091, and
H8/36090

1.3 For the H8/300H MCU Series

Revised product:

The emulator software for the HS3064BEPI61H emulator revised to V.6.00 Release 00.

Versions to be updated:

V2.0.00 (See Section 2.)

Description of revision:

- (1) The High-performance Embedded Workshop included in the product updated to V.4.00.03.

1.4 For the H8S/2200 MCU Series

Revised product:

The emulator software for the HS2214EPI61H (spare and repair) and HS2214EPI62H emulators revised to V.6.01 Release 00.

Versions to be updated:

V2.0.01--V.6.00 Release 00 (See Section 2.)

Description of revision:

- (1) The H8S/2215R MCU added to the support line

2. **A Note on Versions to Be Updated**

All the versions to be updated are supported by the High-performance Embedded Workshop, and the versions earlier than those are the products of the HDI edition. Though they can also be updated, note that if updated, they will only be managed by the High-performance Embedded Workshop.

How to check for the version number of your emulator software

In the High-performance Embedded Workshop, open the Tool menu and select the Administration command. The Administration dialog box appears, and you see the Registered Components list box.

Then read the version number of E6000 Target Platform in the Debugger Components folder, which is displayed in the list box.

The version numbers of the four products concerned are provided as follows (examples):

H8S/2678 E6000 Target Platform V3.0.00

H8/3664 E6000 Target Platform V2.0.00

H8/3064B E6000 Target Platform V2.0.00

H8S/2214 E6000 Target Platform V2.0.01

3. **How to Update Your Product**

Free-of-charge update is available. If you are using the product concerned, update it online as follows:

- (1) Download the update program from Download site.
- (2) Then execute the downloaded executable file.

4. **Notice**

If the executable file is executed in the system where the High-performance Embedded Workshop V.4.00.02 or earlier resides, it will be upgraded to V.4.00.03.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.