
[Upgrade to revision]

R20TS0566EJ0100

Rev.1.00

CS+ Device Information for RH850 Family V8.03.01

Apr. 16, 2020

Outline

CS+ Device Information for RH850 family has been updated from V8.03.00 to V8.03.01.

1. Products and Versions to Be Updated

- CS+ Device Information for RH850 V3.00.00 or later
- CubeSuite+ Device Information for RH850 (CubeSuite+ DevInfo_RH850) V1.00.04 or earlier

To check the version of "CS+ Device Information for RH850" or "CubeSuite+ DevInfo_RH850", follow the instructions under "Components" at the URL below.

<https://www.renesas.com/cs+ ver>

2. Description of the Update

The main features of the update are described in the following sections. See more details at the URL below.

(Scheduled to be released on April 20.)

https://www.renesas.com/cs+/eng/CSPlus_DevInfo_RH850.html

2.1 Correction of Device Information

Part of device information for the following MCU group has been corrected.

- RH850/E2M group

3. Updating Your Product

Online update is available free of charge. The updating method varies depending on the version of CS+.

Note: A license for C Compiler Package for RH850 Family V1 (CC-RH) cannot remove the restrictions on the evaluation edition of C Compiler Package for RH850 Family V2 (CC-RH).

To use the C Compiler Package for RH850 Family V2 (CC-RH) without restrictions, you will need to purchase the commercial edition of C Compiler Package for RH850 Family V2 (CC-RH).

3.1 For CS+ V3.00.00 or Later

Update your program in either of the following methods.

- (1) On the Start menu, select Programs > Renesas Electronics CS+ and then start the Update Manager to install the update. (This service will be available from April 20.)

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

- (2) Download and install the desired software tools from the URL below.

(Download will be available as of April 20.)

<https://www.renesas.com/cs+ download>

3.2 For CubeSuite+ V2.00.00 to 2.02.00

Update your program in the same way as section 3.1.

(Substitute the term "Renesas Electronics CS+" with "Renesas Electronics CubeSuite+").

3.3 For CubeSuite+ V1.03.00 or Earlier

The Update Manager is not supported in CubeSuite+ V1.03.00 or earlier. You will need to install the evaluation edition of the Update Manager. Download and install the evaluation edition of CS+ for CC V8.03.00 from the URL below.

Then, update your program in the same way as section 3.1.

(Download will be available as of April 20.)

<https://www.renesas.com/cs+ download>

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Apr.16.20	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/