
[Upgrade to revision]

R20TS0493EJ0100

Rev.1.00

CS+ Device Information for RL78 V8.02.01

Oct. 01, 2019

Outline

CS+ Device Information for RL78 family has been updated from V8.02.00 to V8.02.01.

1. Products and Versions to Be Updated

- CS+ for CC Device Information for RL78 V3.00.00 or later
- CS+ for CA,CX Device Information for RL78 V3.00.00 or later
- CubeSuite+ Device Information for RL78 (CubeSuite+ DevInfo_RL78_78K) V1.00.18 or earlier

To check the version number of "CS+ Device Information for RL78" or "CubeSuite+ DevInfo_RL78_78K", follow the instructions under "Components" at the URL below.

<https://www.renesas.com/cs+ ver>

2. Description of the Update

The main features of the update are described in the following sections. For details, see the URL below.

(Scheduled to be released on October 8.)

https://www.renesas.com/cs+/eng/CSPlus_DevInfo_RL78.html

2.1 Addition of Supported Devices

Supported devices have been added to the following group.

- RL78/F1E group
R5F11KLF, R5F11KLG, R5F11LLE, R5F11LLF

2.2 Correction of Device Information

The device information of the following MCU group has been corrected.

- RL78/F1E group
R5F11KLE, R5F11LLG

3. Updating Your Product

Online update is available free of charge. The update method varies depending on the version of CS+.

Note: When you update CubeSuite+ to CS+ V3.01.00 or later, the build tool CC-RL will be included as an evaluation edition.

However, the license for earlier version of RL78, 78K family C Compiler Package (CA78K0R, CA78K0) cannot remove the restrictions on the CC-RL evaluation edition.

To use it without restrictions, you will need to purchase the commercial edition of C Compiler Package for RL78 family (with IDE) V1 (CC-RL).

3.1 For CS+ V3.00.00 or Later

Update your program in either of the following methods.

- (1) On the Start menu, select Programs > Renesas Electronics CS+ and then start the Update Manager to install the update. (This service will be available from October 8.)

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

- (2) Download the desired software tools from the following URL.
(Download will be available as of October 8.)

3.2 For CubeSuite+ V2.00.00 to 2.02.00

Update this in the same way as section 3.1.

3.3 For CubeSuite+ V1.03.00 or Earlier

The Update Manager is not supported in CubeSuite+ V1.03.00 or earlier. You will need to install the evaluation edition of the Update Manager. Download the evaluation edition of CS+ for CC V8.02.00 or CS+ for CA,CX V4.03.00 from the URL below. Then, update your program in the same way as section 3.1. (Download will be available as of October 8.)

https://www.renesas.com/cs+_download

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Oct.01.19	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

URLs in Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan
www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.