
[Upgrade to revision]
e² studio Smart Configurator Plug-in V2.5.0,
Smart Configurator for RX V2.5.0

R20TS0567EJ0100
Rev.1.00
Apr. 16, 2020

Outline

The products in the title have been updated as follows.

- (1) e² studio Smart Configurator Plug-in: V2.4.0 to V2.5.0
- (2) Smart Configurator for RX: V2.4.0 to V2.5.0

1. Products and Versions to Be Updated

- e² studio V7.7.0 (Smart Configurator Plug-in V2.4.0) and earlier versions
- Smart Configurator for RX V2.4.0 and earlier versions

2. Description of the Update

The main features of the update are described in the following sections. Refer to the following release note for details.

- Smart Configurator for RX
Smart Configurator for RX V2.5.0 Release Note (Scheduled to be released on April 20.)
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4487>

2.1 Issues Fixed

The following issues have been fixed.

(1) RENESAS TOOL NEWS Document number R20TS0546ES0100

1. When using the PLL frequency synthesizer of the clock
Applicable Devices: RX64M RX651, RX65N, RX66T, RX71M and RX72T groups
For details about this issue, refer to the URL below.
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0546>

(2) RENESAS TOOL NEWS Document number R20TS0555ES0100

1. When using the TGIC7 and TGID7 interrupts in Normal Mode Timer or PWM Mode Timer
Applicable Devices: RX24T and RX24U groups
2. When creating a project with RX24T 64-pin FK packages
Applicable Devices: RX24T group
3. When using compare level of AN109 in Single Scan Mode S12AD
Applicable Devices: RX71M group
For details about these issues, refer to the URL below.
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0555>

3. Updating Your Product

The update method varies depending on the product you are using.

Refer to the following for more information. The updates are available free of charge.

3.1 For e² studio

For how to update e² studio, refer to "3. Updating Your Product" in RENESAS TOOL NEWS Document number R20TS0558EJ0100. (Scheduled to be released on April 20.)

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0558>

Note that the Smart Configurator Plug-in cannot be updated by itself.

3.2 For CS+

Update your program in either of the following methods.

- (1) Download and install Smart Configurator for RX from the following URL.

(Download will be available as of April 20.)

<https://www.renesas.com/smart-configurator#downloads>

Smart Configurator for RX V2.5.0

- (2) From the Windows Start menu, select Programs > Renesas Electronics CS+, and then start the Update Manager to install the update. (This service will be available from April 20.)

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Apr.16.20	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.