

RENESAS TOOL NEWS on March 28, 2013: 130328/tn1

Renesas Flash Programmer Revised to V2.01.00

We have revised Renesas Flash Programmer from V2.00.01 to V2.01.00.
For an overview of this flash-memory-programming software tool, go to:
<https://www.renesas.com/rfp>
The above URL is one of our global sites.

1. Descriptions of Revision

1.1 Device Support

The following MCUs have been added to the support line:

(1) In RL78 family

R5F10Y14 and R5F10Y16 (RL78/G10 group)

R5F104JF, R5F104JG and R5F104JH (RL78/G14 group)

R5F10KBC and R5F10KGC (RL78/G1C group)

(2) In RX family

R5F52107B, R5F52108B, R5F5210AB and R5F5210BB (RX210 group)

R5F56316, R5F56317 and R5F56318 (RX631 group)

(3) In V850 family

UPD70F3552, UPD70F4003, UPD70F4004, UPD70F4005 and UPD70F3555
(V850E2/Fx4)

UPD70F3570, UPD70F3571, UPD70F3572, UPD70F3573, UPD70F3574,
UPD70F3575, UPD70F3576, UPD70F3577, UPD70F3578, UPD70F3579,
and UPD70F3585 (V850E2/Fx4-L)

UPD70F3544 (V850E2/Fx4-M)

1.2 Compatibility with Host OSes Modified

The revised product has become compatible with the following OSes:

- 32-bit and 64-bit editions of Windows(R) 8

1.3 Function Added

The following functions have been added:

- (1) When using RX200 series, Renesas Flash Programmer became applicable

to the programming function via the FINE port on your target MCU and E1 or E20 emulator.

- (2) When using the RX family, even if a workspace file saved in any folder is moved to another folder, it can be opened.

1.4 Problems Fixed

The following problems have been fixed:

- (1) With connecting any emulator except E1 and E20 to host PC while using RX family

Description:

Suppose that any emulator, except E1 and E20, that uses the USB driver for E1 (for example, E10A-USB, E10T-USB, E7 or E200F) is connected to the host PC by using a USB cable.

If you open the "Select Emulator" dialog box in the programmer, two or more "The parameter is incorrect." dialog boxes are displayed.

Product Versions Concerned:

Renesas Flash Programmer V1.03.00, V1.03.01, V2.00.00 and V2.00.01

- (2) Problem with reading data from MCUs of RX family

For details, see RENESAS TOOL NEWS Document No. 130201/tn9 on the Web page at:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=130201tn9>

- (3) Problem with errors arising during command execution

For details, see RENESAS TOOL NEWS Document No. 130206/tn1 on the Web page at:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=130206tn1>

2. Updating Your Product

Online update is available free of charge. Download the installer of the product from:

https://www.renesas.com/rfp_download

The installer will be published on this site on March 29, 2013.

The above URL is one of our global sites.

3. How to Purchase the Product

When you place an order for the product, supply the following items of information to your local Renesas Electronics marketing office or distributor:

Product type: Flash memory programming software

Renesas Flash Programmer

Type name: R0C00000FDW12R

For the price of the product, contact the above marketing office or distributor.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.