



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

PRODUCT DISCONTINUANCE NOTICE# CQ-13-01

ISSUE DATE: July 26, 2013

LAST BUY DATE: July 26, 2014

LAST SHIP DATE: October 26, 2014

REASON FOR DISCONTINUANCE:

The sales activity has declined to a level that warrants the discontinuance of these products. Some of these devices may have an alternate standard device or a suggested functional replacement.

Attached is a list of affected parts with any potential drop in replacement parts or suggested functional replacement parts.

Customers should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuance Notice. You may contact your local IDT Sales office listed on our web site at www.IDT.com or the marketing contact listed below:

FCM srio@idt.com

MIP Paul Barton
408-284-8306
paul.barton@idt.com

TPC,TCS,NCS,NET clocks@idt.com

Final orders may be submitted at any time prior to the last buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and condition.



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

| Device to be Discontinued | Drop in Replacement | Functional Replacement | Replacement Part Availability | Product Group |
|---------------------------|---------------------|------------------------|-------------------------------|---------------|
| 80HVPS1432HMI | None | 80HCPS1432CHMI | Available now | FCM |
| 80HVPS1432HMI8 | None | 80HCPS1432CHMI8 | Available now | FCM |
| 80HVPS1432RMI | None | 80HCPS1432CRMI | Available now | FCM |
| 80HVPS1432RMI8 | None | 80HCPS1432CRMI8 | Available now | FCM |
| 80HVPS1848CRM | None | 80HCPS1848CRM | Available now | FCM |
| 80HVPS1848CRM8 | None | 80HCPS1848CRM8 | Available now | FCM |
| 80HVPS1848CRMI | None | 80HCPS1848CRMI | Available now | FCM |
| 80HVPS1848CRMI8 | None | 80HCPS1848CRMI8 | Available now | FCM |
| 80HVPS1848HM | None | 80HCPS1848CHM | Available now | FCM |
| 80HVPS1848HM8 | None | 80HCPS1848CHM8 | Available now | FCM |
| 80HVPS1848HMI | None | 80HCPS1848CHMI | Available now | FCM |
| 80HVPS1848HMI8 | None | 80HCPS1848CHMI8 | Available now | FCM |
| 80HVPS1848RM | None | 80HCPS1848CRM | Available now | FCM |
| 80HVPS1848RM8 | None | 80HCPS1848CRM8 | Available now | FCM |
| 80HVPS1848RMI | None | 80HCPS1848CRMI | Available now | FCM |
| 80HVPS1848RMI8 | None | 80HCPS1848CRMI8 | Available now | FCM |
| 74ALVCHS162830DFG | None | None | N/A | MIP |
| 74ALVCHS162830DFG8 | None | None | N/A | MIP |
| 74SSTUAE32864ABFG | None | None | N/A | MIP |
| 74SSTUAE32864ABFG8 | None | None | N/A | MIP |
| 74SSTUBH32868ABKG | None | None | N/A | MIP |
| 74SSTUBH32868ABKG8 | None | None | N/A | MIP |
| 97ULPA877AHLF | 98ULPA877AHLF | None | Available now | MIP |
| 97ULPA877AHLFT | 98ULPA877AHLFT | None | Available now | MIP |
| SSTE32882HLBBKG | None | SSTE32882HLBAKG | Available now | MIP |
| SSTE32882HLBBKG8 | None | SSTE32882HLBAKG8 | Available now | MIP |
| SSTUB32864AHLF | None | None | N/A | MIP |
| SSTUB32864AHLFT | None | None | N/A | MIP |
| SSTUBV32866BHLF | 74SSTUBF32866BBFG | None | Available now | MIP |
| SSTUBV32866BHLFT | 74SSTUBF32866BBFG8 | None | Available now | MIP |
| 728981DB | 728981DBG | None | Available now | NCS |
| 728981J | 728981JG | None | Available now | NCS |
| 728981J8 | 728981JG8 | None | Available now | NCS |
| 728985J | 728985JG | None | Available now | NCS |
| 728985J8 | 728985JG8 | None | Available now | NCS |
| 7290820J | 7290820JG | None | Available now | NCS |
| 7290820J8 | 7290820JG8 | None | Available now | NCS |
| 72V70800TF | 72V70800TFG | None | Available now | NCS |
| 72V70800TF8 | 72V70800TFG8 | None | Available now | NCS |
| 72V70810PF | 72V70810PFG | None | Available now | NCS |
| 72V70810PF8 | 72V70810PFG8 | None | Available now | NCS |
| 72V70810TF | 72V70810TFG | None | Available now | NCS |
| 72V70810TF8 | 72V70810TFG8 | None | Available now | NCS |
| 72V71623BC | None | 72V71623DAG | Available now | NCS |
| 72V71623BC8 | None | 72V71623DAG | Available now | NCS |
| 72V71623BCG | None | 72V71623DAG | Available now | NCS |
| 72V71623BCG8 | None | 72V71623DAG | Available now | NCS |
| 72V71623DA | 72V71623DAG | None | Available now | NCS |
| 72V73250BB | 72V73250BBG | None | Available now | NCS |



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

| Device to be Discontinued | Drop in Replacement | Functional Replacement | Replacement Part Availability | Product Group |
|---------------------------|---------------------|---|-------------------------------|---------------|
| 72V73260BB | 72V73260BBG | None | Available now | NCS |
| 72V73260DA | 72V73260DAG | None | Available now | NCS |
| 72V73260DA8 | 72V73260DAG | None | Available now | NCS |
| 72V8980J | 72V8980JG | None | Available now | NCS |
| 72V8980J8 | 72V8980JG8 | None | Available now | NCS |
| 72V8981J | 72V8981JG | None | Available now | NCS |
| 72V8981J8 | 72V8981JG8 | None | Available now | NCS |
| 72V90823BC | 72V90823BCG | None | Available now | NCS |
| 72V90823BC8 | 72V90823BCG8 | None | Available now | NCS |
| 72V90823J | None | 72V90823BCG or 72V90823PFG or 72V90823PQFG | Available now | NCS |
| 72V90823J8 | None | 72V90823BCG8 or 72V90823PFG8 | Available now | NCS |
| 72V90823JG | None | 72V90823BCG or 72V90823PFG or 72V90823PQFG | Available now | NCS |
| 72V90823JG8 | None | 72V90823BCG8 or 72V90823PFG8 | Available now | NCS |
| 821004J | 821004JG | None | Available now | NCS |
| 821004J8 | 821004JG8 | None | Available now | NCS |
| 821024PP | 821024PPG | None | Available now | NCS |
| 821034DN | 821034DNG | None | Available now | NCS |
| 821054PQF | 821054PQFG | None | Available now | NCS |
| 82V3001APV | 82V3001APVG | None | Available now | NCS |
| 82V3001APV8 | 82V3001APVG8 | None | Available now | NCS |
| 82V3002APV | 82V3002APVG | None | Available now | NCS |
| 82V3002APV8 | 82V3002APVG8 | None | Available now | NCS |
| 82V3010PV | 82V3010PVG | None | Available now | NCS |
| 82V3010PV8 | 82V3010PVG8 | None | Available now | NCS |
| 82V3203ANLG | None | 82V3203BNLG | Available now | NCS |
| 82V3203ANLG8 | None | 82V3203BNLG8 | Available now | NCS |
| 82V3355TF | 82V3355TFG | None | Available now | NCS |
| 82V3355TF8 | 82V3355TFG8 | None | Available now | NCS |
| 82V3380PF | 82V3380PFG | None | Available now | NCS |
| 82V3380PF8 | 82V3380PFG8 | None | Available now | NCS |
| 82V3380PFGI | None | 82V3380PFG | Available now | NCS |
| 82V3380PFGI8 | None | 82V3380PFG8 | Available now | NCS |
| 5V7855DCG | None | None | N/A | NET |
| 5V7855-DPK | None | None | N/A | NET |
| 5V7855SWFR | None | None | N/A | NET |
| 8343AYI-01LF | None | 8343AY-01LF | N/A | NET |
| 8343AYI-01LFT | None | 8343AY-01LFT | N/A | NET |
| 8431AM-21LF | None | 84314AY-02LF | Available now | NET |
| 8431AM-21LFT | None | 84314AY-02LF | Available now | NET |
| 84329AVLF | None | 8T49N203A-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |
| 84329AVLFT | None | 8T49N203A-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |
| 84329AYLF | None | 8T49N203A-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |
| 84329AYLFT | None | 8T49N203A-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |
| 84329BM-01LF | None | 8T49N203A-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

| Device to be Discontinued | Drop in Replacement | Functional Replacement | Replacement Part Availability | Product Group |
|---------------------------|---------------------|---|-------------------------------|---------------|
| 84329BM-01LFT | None | 8T49N203A-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |
| 84329BV-01LF | None | 8T49N203A-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |
| 84329BV-01LFT | None | 8T49N203A-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |
| 8432CY-11LF | None | 8T49N222B-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |
| 8432CY-11LFT | None | 8T49N222B-dddNLGI (contact IDT for dash code 'ddd') | Available now | NET |
| 8733BY-01 | None | None | N/A | NET |
| 8733BY-01LF | None | None | N/A | NET |
| 8733BY-01LFT | None | None | N/A | NET |
| 8733BY-01T | None | None | N/A | NET |
| 87931AYI-147LF | None | None | N/A | NET |
| 87931AYI-147LFT | None | None | N/A | NET |
| 87931BYI | None | None | N/A | NET |
| 87931BYILF | None | None | N/A | NET |
| 87931BYILFT | None | None | N/A | NET |
| 87931BYIT | None | None | N/A | NET |
| 1337GDCGK | None | None | N/A | TCS |
| 1337GDCGK8 | None | None | N/A | TCS |
| 9LPRS509HGLF | None | None | N/A | TPC |
| 9LPRS509HGLFT | None | None | N/A | TPC |
| CV184-2APAG | None | 9LP525BG-2LF | Available now | TPC |
| CV184-2APAG8 | None | 9LP525BG-2LFT | Available now | TPC |