

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #:	N-12-48R2	Last Buy Deadline for Sub	mission of Order:	30-Jun-2014	
Issue Date:	14-Jun-2013	Last Eligible Ship Da	Last Eligible Ship Date:		
	SD Clock Team				
PRODUCT(S)	AFFECTED: nt Part #(s), if any)	ATTACHMENT	■ Yes	□ No	
Revision 2: The discontinued as	nis revised PDN notice is to up	odate discontinued part# and replaceme buy deadline for submission of order an	•		
•	asons for these End of Life No	for which there were retractions and arbtices were a shift from leaded to lead-f		•	
2. N-12-48R1 a 3. N-12-48R2 d list. 'Leaded' p REASON FOF Replace slov Obsolete Fal Obsolete As	luded both devices from the fradded some parts that were incorrects the errors in the previous	reescale fab and older 'at risk' fabs. itially missed and removed the 'at risk' ous revision which removed 'leaded' pa lead free parts will be supported for the ferings Other:	arts also from the pr	roducts being discontinued	
As a result of d through this Pr converting to e Last time buy of by IDT at its so	NOTIFICATION: liscontinuance reason(s) listed oduct Discontinuance Notice quivalent devices offered. Pleorders may be submitted any tiple discretion unless otherwise	above, IDT has decided to discontinue (PDN). We recommend you to check decase use acknowledgement below or Estime prior to the date indicated above. As agreed by IDT in writing.	etailed specification Mail to request add All orders shall be s	ns before itional information. ubject to acceptance	
Customer:		E-Mail Address:			
Name/Date: _		Phone#:			
Title:		Fax#:			
CUSTOMER	COMMENTS:				
IDT ACKNO	WLEDGEMENT:				
Received By:		Date:			



PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: N-12-48R2

Updated Affected Part Numbers

Discontinued Part#	Replacement Part#	Replacement Part Sample Availability Date If Not Ready Now
MC100ES6056DT	NONE	
MC100ES6056DTR2	NONE	
MC100ES6056EG	NONE	
MC100ES6056EGR2	NONE	
MC100ES6056EJ	NONE	
MC100ES6056EJR2	NONE	
MC100ES6111AC	8T33FS6111DXGI	Jan 2014
MC100ES6111ACR2	8T33FS6111DXGI8	Jan 2014
MC100ES6111FA	8T33FS6111DXGI	Jan 2014
MC100ES6111FAR2	8T33FS6111DXGI8	Jan 2014
MC100ES6210AC	NONE	
MC100ES6210ACR2	NONE	
MC100ES6210FA	NONE	
MC100ES6210FAR2	NONE	
MC100ES6210KLF	NONE	
MC100ES6210KLFR2	NONE	
MPC9653AAC	NONE	
MPC9653AACR2	NONE	
MPC9653AFA	NONE	
MPC9653AFAR2	NONE	
MC100ES6111AC/W	8T33FS6111DXGI	Jan 2014
MPC9109FA	MPC9109AC	
MPC9109FAR2	MPC9109ACR2	
MPC92432AE	8V43FS92432PRGI	Jan 2014
MPC92432AER2	8V43FS92432PRGI8	Jan 2014
MPC92432FA	8V43FS92432PRGI	Jan 2014
MPC92432FAR2	8V43FS92432PRGI8	Jan 2014
MPC9330FA	MPC9330AC	
MPC9330FAR2	MPC9330ACR2	
MPC9331FA	MPC9331AC	
MPC9331FAR2	MPC9331ACR2	
MPC9351FA	MPC9351AC	
MPC9351FAR2	MPC9351ACR2	
MPC9352FA	MPC9352AC	
MPC9352FAR2	MPC9352ACR2	
MPC93R51FA	MPC93R51AC	
MPC93R51FAR2	MPC93R51ACR2	
MPC93R52FA	MPC93R52AC	
MPC93R52FAR2	MPC93R52ACR2	
MPC940LFA	MPC940LAC	
MPC940LFAR2	MPC940LACR2	
MPC941FA	MPC941AC	
MPC941FAR2	MPC941ACR2	
MPC942PFA	MPC942PAC	



PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: N-12-48R2

Updated Affected Part Numbers

Discontinued Part#	Replacement Part#	Replacement Part Sample Availability Date If Not Ready Now
MPC942PFAR2	MPC942PACR2	
MPC9446FA	MPC9446AC	
MPC9446FAR2	MPC9446ACR2	
MPC9447FA	MPC9447AC	
MPC9447FAR2	MPC9447ACR2	
MPC9448FA	MPC9448AC	
MPC9448FAR2	MPC9448ACR2	
MPC9449FA	MPC9449AE	
MPC9449FAR2	MPC9449AER2	
MPC9600FA	MPC9600AE	
MPC9600FAR2	MPC9600AER2	
MPC9608FA	MPC9608AC	
MPC9608FAR2	MPC9608ACR2	
MPC961CFA	MPC961CAC	
MPC961CFAR2	MPC961CACR2	
MPC961PFA	MPC961PAC	
MPC961PFAR2	MPC961PACR2	
MPC962305D-1	MPC962305EF-1	
MPC962305D-1H	MPC962305EF-1H	
MPC962305D-1HR2	MPC962305EF-1HR2	
MPC962305D-1R2	MPC962305EF-1R2	
MPC962305DT-1	MPC962305EJ-1H	
MPC962305DT-1H	MPC962305EJ-1H	
MPC962305DT-1HR2	MPC962305EJ-1HR2	
MPC962305DT-1R2	MPC962305EJ-1HR2	
MPC962308D-1	MPC962308EF-1H	
MPC962308D-1H	MPC962308EF-1H	
MPC962308D-1HR2	MPC962308EF-1HR2	
MPC962308D-1R2	MPC962308EF-1HR2	
MPC962308DT-1H	MPC962308EJ-1H	
MPC962308DT-1HR2	MPC962308EJ-1HR2	
MPC962308DT-2	NONE	
MPC962308DT-2R2	NONE	
MPC962309D-1	MPC962309EF-1H	
MPC962309D-1H	MPC962309EF-1H	
MPC962309D-1HR2	MPC962309EF-1HR2	
MPC962309D-1R2	MPC962309EF-1HR2	
MPC962309DT-1H	MPC962309EJ-1H	
MPC962309DT-1HR2	MPC962309EJ-1HR2	
MPC9653AAC/W	NONE	
MPC9653AACR2/W	NONE	
MPC9653AFA/A	NONE	
MPC9653AFA/M	NONE	
MPC9653AFAR2/M	NONE	



PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: N-12-48R2

Updated Affected Part Numbers

Discontinued Part#	Replacement Part#	Replacement Part Sample Availability Date If Not Ready Now
MPC9658FA	MPC9658AC	
MPC9658FAR2	MPC9658ACR2	
MPC9772FA	MPC9772AE	
MPC9772FAR2	MPC9772AER2	
MPC9773FA	MPC9773AE	
MPC9773FAR2	MPC9773AER2	
MPC9774FA	MPC9774AE	
MPC9774FAR2	MPC9774AER2	
MPC97H73FA	MPC97H73AE	
MPC97H73FAR2	MPC97H73AER2	
MPC97H74FA	MPC97H74AE	
MPC97H74FAR2	MPC97H74AER2	
MPC9865VF	NONE	
MPC9865VFR2	NONE	
MPC9893FA	MPC9893AE	
MPC9893FAR2	MPC9893AER2	



PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT II - PDN #: N-12-48R2

Devices being discontinued that are listed on both N-12-22 (R2) and N-12-48 (R2) PDN's

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
MC100ES6111FA	8T33FS6111DXGI	MPC9448FAR2	MPC9448ACR2
MC100ES6111FAR2	8T33FS6111DXGI8	MPC9449FA	MPC9449AE
MC100ES6210FA	None	MPC9449FAR2	MPC9449AER2
MC100ES6210FAR2	None	MPC9600FA	MPC9600AE
MPC9109FA	MPC9109AC	MPC9600FAR2	MPC9600AER2
MPC9109FAR2	MPC9109ACR2	MPC961CFA	MPC961CAC
MPC9330FA	MPC9330AC	MPC961CFAR2	MPC961CACR2
MPC9330FAR2	MPC9330ACR2	MPC962305DT-1H	MPC962305EJ-1H
MPC9351FA	MPC9351AC	MPC962305DT-1HR2	MPC962305EJ-1HR2
MPC9351FAR2	MPC9351ACR2	MPC9772FA	MPC9772AE
MPC9352FA	MPC9352AC	MPC9772FAR2	MPC9772AER2
MPC9352FAR2	MPC9352ACR2	MPC9773FA	MPC9773AE
MPC940LFA	MPC940LAC	MPC9773FAR2	MPC9773AER2
MPC940LFAR2	MPC940LACR2	MPC9774FA	MPC9774AE
MPC941FA	MPC941AC	MPC9774FAR2	MPC9774AER2
MPC941FAR2	MPC941ACR2	MPC97H74FA	MPC97H74AE
MPC9446FA	MPC9446AC	MPC97H74FAR2	MPC97H74AER2
MPC9446FAR2	MPC9446ACR2	MPC9865VF	None
MPC9447FA	MPC9447AC	MPC9865VFR2	None
MPC9447FAR2	MPC9447ACR2	MPC9893FA	MPC9893AE
MPC9448FA	MPC9448AC	MPC9893FAR2	MPC9893AER2