

# **PRODUCT ADVISORY**

## **Data Sheet Specification Change for Intersil Product X60003\***

**Refer to:  
PA11031**

**Date: March 21, 2011**

March 21, 2011

To: Our Valued Intersil Customers

Subject: **Data Sheet Specification Change for Intersil Product X60003\***

This advisory is to inform you that Intersil has updated the data sheet specification for the listed X60003\* products. The change to the  $\theta_{JA}$  value for the SOT-23 package in the Thermal Information section aligns the data sheet with the product characteristics. The updated data sheet is available on the Intersil web site at <http://www.intersil.com/data/fn/fn8137.pdf>.

Products affected:

X60003BIG3Z-41	X60003CIG3Z-41	X60003DIG3Z-41	X60003DIG3Z41T1S2378
X60003BIG3Z-41T1	X60003CIG3Z-41T1	X60003DIG3Z-41T1	
X60003BIG3Z-50	X60003CIG3Z-50	X60003DIG3Z-50	
X60003BIG3Z-50T1	X60003CIG3Z-50T1	X60003DIG3Z-50T1	

Data sheet specification changes are as follows:

Thermal Resistance	Current Value	New Value	Units
3ld SOT-23 Package	202.7	375	°C/W

There will be no change in external marking of the packaged parts. There have been no changes made to the silicon or device itself.

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for manufacturing of material supplied today.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jon Brewster  
Intersil Corporation

PA11031

CC: J. Touvell Q. Harris P. Lee