## Old Company Name in Catalogs and Other Documents

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <a href="http://www.renesas.com">http://www.renesas.com</a>

April 1<sup>st</sup>, 2010 Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<a href="http://www.renesas.com">http://www.renesas.com</a>)

Send any inquiries to http://www.renesas.com/inquiry.



Date: Dec.14.2004

## **RENESAS TECHNICAL UPD**

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan Renesas Technology Corp.

Product Category	User Development Environment		Document No.	TN-EML-A125A/E	Rev.	1.0
Title	Note on Use of NQPACK120SE Attached with E6000H User System Interface Cable HS1582ECH61H		Information Category	Technical Notification		
Applicable Product	H8SX/1582 E6000H User System Interface Cable (HS1582ECH61H that applies NQPACK120SE)	Lot No.				
		All lots	Reference Document	H8SX/1582 E6000H User System Interface Cable User's Manual		

Thank you for using our product.

The note on installation shown below will be applied when you install the H8SX/1582 FP-120B package on the NQPACK120SE (manufactured by Tokyo Eletech Corporation) attached with the H8SX/1582 E6000H user system interface cable (HS1582ECH61H).

[Note on Installation]

Before installing the H8SX/1582 FP-120B-packaged IC on the NQPACK120SE attached with HS1582ECH61H, carefully remove burrs from the four corners of the IC. If the IC is forcibly installed without removing the burrs, the IC lead may be bent and remains of the burrs may cause a contact failure between the IC and the socket.

