

To our customers,

---

## Old Company Name in Catalogs and Other Documents

---

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1<sup>st</sup>, 2010  
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

MESC TECHNICAL NEWS

No.M7200-08-9811

Additional Information in Documents of Microcomputer for TV

– Slave address comparison flag (AAS) of I<sup>2</sup>C status register –

Errors exist in the following document. Please refer to the table below.

- M37280MF-XXXSP, M37280MK-XXXSP, M37280EKSP
- <CD-ROM>  
 • Sep.1998 CD-ROM  
 • Microcomputer for TV  
 Oct. 1998

Revised point	correction	error								
Structure of I <sup>2</sup> C status register  Slave address comparison flag (AAS) (b2 of I <sup>2</sup> C status register)  <280MF/MK/EK> (Body and appendix)	<table><tr><td>b</td><td>Functions</td></tr><tr><td>2</td><td>0: Address mismatch 1: Address match</td></tr></table>	b	Functions	2	0: Address mismatch 1: Address match	<table><tr><td>b</td><td>Functions</td></tr><tr><td>2</td><td>0: Address match 1: Address mismatch</td></tr></table>	b	Functions	2	0: Address match 1: Address mismatch
b	Functions									
2	0: Address mismatch 1: Address match									
b	Functions									
2	0: Address match 1: Address mismatch									