

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL UPD

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
RenesasTechnology Corp.

Product Category	MPU&MCU	Document No.	TN-SH7-A537A/E	Rev.	1.0
Title	Usage notice of port-F	Information Category	Technical Notification		
Applicable Product	HD6417706	Lot No.	Reference Document	SH7706 hardware manual (REJ09B0146-0400O Rev. 4.00)	
		All			

SH7706 has a followed usage notice.

1. Phenomenon

The user program may stop when the pin function of PTF1 is set to port output. (In this case the debug function in SH7706 is active)

2. Work around

Do not set PTF1 as port output.