

RENESAS TOOL NEWS on April 16, 2014: 140416/tn3

Note on Using Integrated Development Environment CubeSuite+ for RX Family V2.02.00

When using the CubeSuite+ for the RX Family V2.02.00, take note of the following problem:

- With timer measurement events for the RX64M group
-

1. Products Concerned

- C Compiler and IDE for RX Family
- Evaluation edition of CubeSuite+

This problem applies when either of the above products with CubeSuite+ common program V2.02.00 is used together with the E20 emulator.

To check to see the version number, refer to the following URL:

http://www.renesas.com/cubesuite+_ver

2. Description

When the user system incorporating an RX64M group MCU is debugged using the E20 emulator, if "Yes" is selected under Use code coverage function in the Coverage category under Debug Tool Settings tab in the debug tool property, timer measurement events cannot be used.

3. Workaround

To use timer measurement events, select "No" for Use code coverage function.

4. Schedule for Fixing the Problem

This problem will be fixed in the next version of the CubeSuite+ common program.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.