

---

[Notes]

R20TS1215EJ0100

Rev.1.00

Mar. 20, 2026

## CS+ and e<sup>2</sup> studio Integrated Development Environments

### (Note on debugging in user boot mode for the RX660 Group)

---

#### Outline

When using the CS+ or e<sup>2</sup> studio IDEs, note the following point.

1. Note on debugging in user boot mode for the RX660 Group

#### 1. Note on debugging in user boot mode for the RX660 Group

##### 1.1 Applicable Products

CS+ for CC V8.08.00 and later versions

e<sup>2</sup> studio 2022-07 and later versions

##### 1.2 Applicable Devices

RX Family: RX660 Group

##### 1.3 Details

When selecting the user boot mode for the applicable products and starting the debugger, the debugger does not operate properly even if the connection with the emulator is correct.

##### 1.4 Conditions

This error will occur when "User Boot Mode" is selected in the mode pin setting of the CPU's operation mode and the debugger is started.

##### 1.5 Workaround

There is no workaround.

##### 1.6 Schedule for Fixing the Problem

This problem will be fixed in the next version. (Scheduled to be released in April, 2026.)

**Revision History**

Rev.	Date	Description	
		Page	Summary
1.00	Mar.20.26	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

**Corporate Headquarters**

TOYOSU FORESIA, 3-2-24 Toyosu,  
Koto-ku, Tokyo 135-0061, Japan  
[www.renesas.com](http://www.renesas.com)

**Trademarks**

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

**Contact information**

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:  
[www.renesas.com/contact/](http://www.renesas.com/contact/)