

RENESAS TOOL NEWS on February 01, 2015: 150201/tn3

## Device Information (Managed by CS+) for RX Family Revised to V1.06.00

We will be revising the device information file (managed by CS+) for the RX family of MCUs and accordingly will change the version number from 1.05.00 to 1.06.00.

---

### 1. Product and Versions to Be Updated

- (1) Device information file managed by CubeSuite+ for the RX family of MCUs (CubeSuite+ DevInfo\_RX) V1.03.00 or earlier
- (2) Device information file managed by CS+ for the RX family of MCUs (CS+ Device Information for RX) V1.05.00 or earlier

Check your version number of "CubeSuite+ DevInfo\_RX" or "CS+ Device Information for RX" with reference to the procedure described under the heading "Components" at the URL below.

[https://www.renesas.com/cs+\\_ver](https://www.renesas.com/cs+_ver)

### 2. Description of Revision

#### (1) Addition of Supported MCUs

The following MCUs will be added to the supported line.

RX71M group

R5F571MFC, R5F571MFD, R5F571MGC, R5F571MGD, R5F571MJC, R5F571MJD, R5F571MLC, and R5F571MLD

Remarks:

For a sample of recommended connections for the RX71M group, refer to the example of recommended connections for the RX64x group in the following user's manual.

E1/E20 Emulator Additional Document for User's Manual  
(RX User System Design)

### 3. Updating Your Product

Online updating is available free of charge.

To update either your commercial edition or evaluation edition of CS+, use either of the following methods.

#### 3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

(1) On the Start menu, select Programs and then Renesas Electronics CS+ to start the Update Manager.

This service will be available from February 5.

Note: If your CS+ has been launched with rapid startup enabled, exit from CS+ and then run the Update Manager.

If CS+ is resident in the notification area of Windows (system tray) for rapid startup, an error occurs and the following message is produced.

-----

M0120001

Installation is suspended because "CubeSuite+W.exe" is running.

It will be resumed next time you start the tool.

-----

(2) Download and install V1.06.00 of device information file managed by CS+ for the RX family of MCUs from the following URL.

[https://www.renesas.com/cs+\\_download](https://www.renesas.com/cs+_download)

The above program will be available from February 5.

#### 3.2 For CubeSuite+ V2.02.01 and Earlier Versions

Please download and install the evaluation edition of CS+ V3.00.00 from the following URL:

[https://www.renesas.com/cs+\\_download](https://www.renesas.com/cs+_download)

After that, update your program by using the method in 3.1 (1) or (2) above.

---

#### [Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.