

RENESAS TOOL NEWS on May 16, 2006: RSO-E10A-USB-060516D

The Emulator Software for the E10A-USB Emulators Revised to V.2.04 Release 00

We have revised the emulator software for the E10A-USB emulators (HS0005KCU01H and HS0005KCU02H). The emulator software and the emulators are used for the SuperH RISC engine, H8S, and H8SX families of MCUs.

1. Products to Be Revised

Emulator software V1.0.00 through V.2.03 Release 00 for the E10A-USB emulators (HS0005KCU01H and HS0005KCU02H)

2. Descriptions of Revision

2.1 Supported MCUs Increased

The following member of the H8SX device group has been added to the support line:

- H8SX/1527RF

2.2 Function Introduced

Programs can be downloaded to external flash memory when any of the following devices of the H8SX device group is targeted for debugging:

H8SX/1653F, H8SX/1654F, H8SX/1663F, and H8SX/1664F

3. How to Update Your Product

Free-of-charge online update is available. If you are using the product concerned, go through the following steps:

- (1) Download the update program of the product from the Download site.
- (2) Decompress the downloaded ZIP file to obtain the install program (a setup.exe file); then execute it.

(3) Execute the Setup Tool for E10A-USB Emulator program to set up the emulator software for the E10A-USB.

4. Notices

- (1) The install program obtained in 3-(2) above cannot change the device group you are using to another one.
- (2) If the install program is executed in the system where the High-performance Embedded Workshop V.4.00.02 or earlier resides, it will be updated to V.4.00.03.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.