

[Upgrade to revision]

R20TS0156EJ0100

Rev.1.00

Device Information (Managed by CS+) for RX Family V2.01.00

Apr. 1, 2017

Outline

We will be revising the device information file (managed by CS+) for the RX family from V2.00.00 to V2.01.00.

1. Products and Versions to Be Updated

- Device information file managed by CS+ for the RX family (CS+ Device Information for RX) V1.04.00 or later
- Device information file managed by CubeSuite+ for the RX family (CubeSuite+ DevInfo_RX) V1.03.00 or earlier

Check the version number of your “CS+ Device Information for RX” or “CubeSuite+ DevInfo_RX” with reference to the procedure described under the heading “Components” at the URL below.

https://www.renesas.com/cs+_ver

2. Description of Revision

The major revision points are as follows. Refer to the page at the URL below for details.

The information will be available from April 5.

https://www.renesas.com/cs+/eng/CSPlus_DevInfo_RX.html

2.1 Addition of Supported MCUs

Support for the MCUs listed below has been newly added.

- RX24T group (RX family)
R5F524TBAXFP, R5F524TCAXFP, R5F524TEAXFP
- RX24U group (RX family)
R5F524UBAXFB, R5F524UBAXFP, R5F524UCAXFB
R5F524UCAXFP, R5F524UEAXFB, R5F524UEAXFP

3. Updating Your Product

Online updating is available free of charge. The method of updating depends on the edition of CS+.

3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

- (1) On the “Start” menu, select “Programs” and then “Renesas Electronics CS+” to start the Update Manager, and update your CS+ to V5.00.00. This service will be available from April 5.

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

Installation is suspended because “CubeSuiteW+.exe” is running.

It will be resumed next time you start the tool.

- (2) Download and install the “CS+ Device Information for RX V2.01.00” from the web site at the URL below. The program will be available from April 5.
https://www.renesas.com/cs+_download

3.2 For CubeSuite+ V2.00.00 to V2.02.00

Update your program in the same way as is described in 3.1 above.

3.3 For CubeSuite+ V1.03.00 or Earlier

Download and install the evaluation edition of CS+ for CC V5.00.00 from the web site at the URL below, then update your product in the same way as is described in 3.1 above. The program will be available from April 5.

https://www.renesas.com/cs+_download

Revision History

| Rev. | Date | Description | |
|------|--------------|-------------|----------------------|
| | | Page | Summary |
| 1.00 | Apr. 1, 2017 | - | First edition issued |
| | | | |

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan
Renesas Electronics Corporation

■Inquiry

<https://www.renesas.com/contact/>

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication.

Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.