# [Upgrade to revision]

# License Manager

R20TS0349EJ0100 Rev.1.00 Sep. 16, 2018

#### Outline

License Manager has been revised from V2.02.00 to V2.02.01.

V2.02.01 has fixed the error in the V2.02.00 regarding license authentication.

#### 1. Products Versions to Update

License Manager V1.00.00 to V2.02.00

# 2. Items Revised

This update has fixed the issue in the following note.

- RENESAS TOOL NEWS, Document No. R20TS0346EJ0100
  - 1. License Authentication of License Manager

For details regarding this issue, refer to the URL below. https://www.renesas.com/search/keyword-search.html#genre=document&q= r20ts0346

#### 3. Updating Your Product

# 3.1 Download the Installer from the Website

Download the installer from one of the following URLs to install the product. The update will be available for download on September 20.

https://www.renesas.com/cs+ download

https://www.renesas.com/e2studio\_download

#### 3.2 Online Update (for CS+ for CC)

Open the Start menu  $\rightarrow$  Programs and select Renesas Electronics CS+ and start the Update Manager to update the program. Online updating service will be available on September 20.

#### **Revision History**

		Description	
Rev.	Date	Page	Summary
1.00	Sep. 16, 2018	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

### ■Inquiry

https://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2018 Renesas Electronics Corporation. All rights reserved.

TS Colophon 2.1