



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

Errata Notification

EN #: IEN02-11 Errata Revision #: 2/28/02
Issue Date: March 13, 2002 Effective Date: February 28, 2002
Product Affected: IDT79RC32T351

ERRATA DETAILS:

ATTACHMENT Yes No

- Data Sheet Errata
- Device Errata
- Device Manual Errata
- Application Notes Errata
- Other (Please Specify)

Added new Item describing Handling of Odd Number of 4-bit Nibbles in Ethernet Packet by DMA Controller

IDT Web Site Location:

http://www.idt.com/products/pages/Integrated_Processors-RC32351.html

CUSTOMER NOTIFICATION:

As a result of Errata listed above, IDT has decided to notify you through this Errata Notification. We recommend you to review this notification in details prior to the use of affected product in your application. Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____ E-Mail Address: _____
Name/Date: _____ Phone #: _____
Title: _____ Fax #: _____

CUSTOMER COMMENTS: _____