Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200 PRODUCT DISCONTINUANCE NOTICE (PDN)									
PDN #: 1	FS-15-02	Last Buy Deadline for Submission of Order: 22-Nov-2015							
Issue Date: 2	22-May-2015	Last Eligible Ship Date: 22-May-2016							
Title:MarPhone #:1-40	l May keting Director - Standard Product )8-284-2718 <mark>1.May@idt.com</mark>	s							
	<b>PRODUCT(S) AFFECTED:ATTACHMENT</b> YesNo(List Replacement Part #(s), if any)If any)If anyIf any								
Selective parts as listed in attachment will be discontinued.									
REASON FOR D	DISCONTINUANCE:								
-	speed with faster speed offerings	Other:							
Obsolete Fab Technology / Process									
	nbly Technology / Process		Manufacturing Discontinuance of non RoHS						
Obsolete Packa	-		compliant lead finish and Subcontractor Package						
Declined Market	et		Discontinuance						
<ul> <li>CUSTOMER NOTIFICATION:</li> <li>As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.</li> <li>Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.</li> <li><i>If you have any questions, please feel free to contact your local IDT distributor or sales representative.</i></li> </ul>									
Customer:		E-Mail Addres	ss:						
Name/Date:		Phone#:							
Title:	Fax# :								
CUSTOMER COMMENTS:									
IDT ACKNOWLEDGEMENT:									
Received By: Date:									

Г



D00.D77PD0.D75PD0.D75PD0.D75PD0.D75December of and a final set instanceD00.D77PD0.D77<	Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group	Reason for Discontinuance
TADELUPYNo.4.Asiab forFORDecomposed for definition of the sectorTADELUPY1248.117No.4.Asiab forCOSectorAsiab forTADELUPY1248.117No.4.Asiab forCOSectorAsiab forTADELUPY1248.117No.4.Asiab forCOSectorSectorTADELUPY1248.117No.4.Asiab forCOSectorSectorTADELUPY1248.117No.4.A						
DRAID         Desc.         Name         Adds for         Open setting of an interpret of an interp						
DRAIL DECADENon-Alabi Non-Non-Non-Non-Non-Non-Non-Non-Non-Non-Non-Non-Non-						
ZURADYPURALPURALNumber of PURALPURALNumber of PURALPURALNumber of PURALPURALNumber of PURAL						
Disk         Disk         Name         Name <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td></th<>						
TRUMPTRUMPNorthAnalysis forRestand of the description o						
TADDURYTADUERYNote: A paint from the paint of the paint base has not one of constraint of an of constraint of a	72220L25TP	72220L10TPG	None		SPO	Discontinuance of non RoHS compliant lead finish
DiskleyDiskleyNoneAddata howDiskDiskley <thd< td=""><td></td><td></td><td></td><td></td><td></td><td></td></thd<>						
TAUMORYTAUMORYNon-Anders forDecompany of point or optical sections.TAUMORYTAUMORYTAUMORYPODecompany of point or optical sections.TAUMORYTAUMORYTAUMORYPODecompany of point or optical sections.TAUMORYTAUMORYNameAnabies forPODecompany of point or optical sections.TAUMORYTAUMORYNameAnabies forPODeco						
D2005/07D2014/070Non-Audiab houD20Non-minuter data data data data data data data dat						
DDALLSPY         Non         Analla New         Sol         Solutions of an loss couples are down.           DDALLSPY         DDALLSPY         DDALLSPY         Non-         Analla New         O         Recommand of an loss couples are down.           DDALLSPY         DDALLSPY         Non-         Analla New         O         Recommand of an loss couples are down.           DDALLSPY         DDALLSPY         Non-         Analla New         O         Recommand of an loss couples are down.           DDALLSPY         DDALLSPY         Non-         Analla New         O         Recommand of an loss couples are down.           DDALLSPY         DDALLSPY         Non-         Analla New         O         Recommand of an loss couples are down.           DDALLSPY         DDALLSPY         Non-         Analla New         O         Recommand of an loss couples are down.           DDALLSPY         DDALLSPY         Non-         Analla New         O         Recommand of an loss couples are down.           DDALLSPY         DDALLSPY         Non-         Analla New         O         Recommand of an loss couples are down.           DDALLSPY         DDALLSPY         Non-         Analla New         O         Recommand of an loss couples are down.           DDALSPY         DDALLSPY         Non-						
TABLERYNoc.Aduble NormPORecommund of an UAG sequence and fram.TABLERYTABLERYNo.Adube NormOCNormaline and non-Normaline and non-Norm						Discontinuance of non RoHS compliant lead finish
DisplayInternational and final						
DRALENCYDescriptionNeuronAndlet NovPOSectional of an Noti Singular lat fundionDRALENCYDRA	72125L25TP	72125L25TPG		Available Now	SPO	Discontinuance of non RoHS compliant lead finish
TABLATYNORLATYNon-Analas howPODecompany of an Analas makes and set and s						
ZABATYKoreAnalab NovNovDiscription of non- constraints of main sectorZABATYZABATYZABATYNovAnalab NovNovDiscription of non- constraints of main sectorZABATYZABATYNovAnalab NovSODiscription of non- constraints of main sectorZABATYZABATYNovAnalab NovSODiscription of non- constraints of main sectorZABATYZABATYNovAnalab NovSODiscription of non- constraints of non- co						
726.157NoneAnalate None(90Decompany of an Index company back index726.157726.157726.157NoneAnalate None90Decompany of an Index company back index726.157726.157NoneAnalate None90Decompany of an Index company back index726						
758.577758.577Nor.Analak how.670Recommany of an Index complex took from758.577720.577720.577Nor.Analak how.970Recommany of an Index complex took from759.577720.577720.577Nor.Analak how.970Recommany of an Index complex took from759.577720.577720.577Nor.Analak how.970Recommany of an Index complex took from750.577720.1776Nor.Analak how.970Recommany of an Index complex took from720.577720.1776Nor.Analak how.970Recommany of an Index complex took from720.577720.1776Nor.Nor.Analak how.970Recommany of an Index complex took from720.577720.1776<						
ZixXXVIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII						
ZPGG277ZPGG177UseNumeAnalake trouSPODecominance af non test compaint set finishZPGG277ZPGG177ZPGG177NumeAnalake trouSPODecominance of non test compaint set finishZPGG177ZPGG177ZPGG177NumeAnalake trouSPODecominance of non test compaint set finishZPGG177ZPGG177NumeAnalake trouSPODecominance of non test compaint set finishZPGG177ZPGG177NumeAnalake trouSPODecominance of non test compaint set finishZPGG177ZPGG177NumeAnalake trouSPODecominance of non test compaint set finishZPGG177ZPGG177ZPGG177NumeAnalake trouSPODecominance of non test compaint set finishZPGG177ZPGG1776NumeAnalake trouSPODecominance of non test compaint set finishZPGG1777ZPGG1776NumeAnalake trouSPOD						
ZIGG.21PP         ZIGG.21PC         Nome         Available from         SP O         Decominance drom bdx computer lard from           ZIGG.21P         ZIGG.21PC         Nome         Available from         SP O         Decominance drom bdx computer lard from           ZIGG.21PC         ZIGG.21PC         Nome         Available from         SP O         Decominance drom bdx computer lard from           ZIGG.22PC         ZIGG.22PC         ZIGG.22PC         Decominance drom bdx computer lard from           ZIGG.22PC         ZIGG.22PC         SIGG.22PC         Decominance drom bdx computer lard from           ZIGG.22PC         ZIGG.22PC         Nome         Available from         SP O         Decominance drom bdx computer lard from           ZIGG.22PC         ZIGG.22PC         Nome         Available from         SP O         Decominance drom bdx computer lard from           ZIGG.22PC         ZIGG.22PC         Nome         Available from         SP O         Decominance drom bdx computer lard from           ZIGG.22PC         ZIGG.22PC         Nome         Available from         SP O         Decominance drom bdx computer lard from           ZIGG.22PC         ZIGG.22PC         Nome         Available from         SP O         Decominance drom bdx computer lard from           ZIGG.22PC         ZIGG.2PCC         Nome <td>7205L25TPI</td> <td>7205L15TPGI</td> <td></td> <td>Available Now</td> <td>SPO</td> <td>Discontinuance of non RoHS compliant lead finish</td>	7205L25TPI	7205L15TPGI		Available Now	SPO	Discontinuance of non RoHS compliant lead finish
ZBS.1379         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL077         ZDSL1776         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL277         ZDSL1776         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL277         ZDSL1776         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL277         ZDSL1776         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL277         ZDSL1776         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL277         ZDSL2776         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL277         ZDSL2776         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL277         ZDSL2776         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL277         ZDSL2776         None         Analable Nov         GPO         Decembance of no Notic complant and Minish           ZDSL2777						
ZNALSTP         None         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP         ZNALSTP         Nova         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP         ZNALSTP         Nova         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP         ZNALSTP         Nova         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP         ZNALSTP         Nova         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP         ZNALSTPG         Nova         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP         ZNALSTPG         Nova         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP         ZNALSTPG         Nova         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP         ZNALSTPG         Nova         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP         ZNALSTPG         Nova         Analysis Nova         SPO         Decembance of an Notis Complex test final           ZNALSTP <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td></t<>						
Dist.219*         Dist.219*         None         Availabe Nove         SPO         Discriminance of no bird's complaint test fields           Dist.219*         7.044.217*6         None         Availabe Nove         SPO         Discriminance of no bird's complaint test fields           Dist.219*         7.044.217*6         None         Availabe Nove         SPO         Discriminance of no bird's complaint test fields           ZD04.219*         7.044.217*6         None         Availabe Nove         SPO         Discriminance of no bird's complaint test fields           ZD04.219*         7.044.217*6         None         Availabe Nove         SPO         Discriminance of no bird's complaint test fields           ZD04.219*         7.044.217*6         None         Availabe Nove         SPO         Discriminance of no bird's complaint test fields           ZD04.219*         7.034.217*6         None         Availabe Nove         SPO         Discriminance of no bird's complaint test fields           ZD04.219*         7.034.217*6         None         Availabe Nove         SPO         Discriminance of no bird's complaint test fields           ZD04.219*         7.034.217*6         None         Availabe Nove         SPO         Discriminance of no bird's complaint test fields           ZD04.219*         7.034.217*6         None         Availabe Nov		7204L12TPG		Available Now		Discontinuance of non RoHS compliant lead finish
ZDAL37PZDAL37PNoneAnalyse NormSPCDecembance of no Hold complant kal filmsZDAL37PZDAL37PNoneAnalyse NormSPCDecembance of no Hold complant kal filmsZDAL37PZDAL37PZDAL37PNoneAnalyse NormSPCDecembance of no Hold complant						
7204.137P7204.137PGNoneAvailab Now90Discontinuance of not Rolfs compliant lead finith7204.137P7204.137PGNoneAvailab Now90Discontinuance of not Rolfs compliant lead finith7204.137P7204.137PGNoneAvailab Now90Discontinuance of not Rolfs compliant lead finith7204.137P7201.137PGNoneAvailab Now90Discontinuance of not Rolfs compliant lead finith7201.137P7201.137PGNoneAvailab Now90Discontinuance of not Rolfs compliant lead finith7201.137PG7201.137PGNoneAvailab Now90Discontinuance of not Rolfs compliant lead finith7201.137PG7201.137PGNoneAvailab Now90Discontinuance of not R	7204L25TPI	7204L15TPGI			SPO	Discontinuance of non RoHS compliant lead finish
ZPAL15PTZPAL15PTNoneAvailable NorwUP 00Discontinuance of non Relis compliant lead frokingZPAL12PTZPAL12PTNoneAvailable NorwUP 00Discontinuance of non Relis compliant lead frokingZPAL12PTZPAL12PTNoneAvailab						
TOBUSTPP         TOBUSTPP         None         Valable Now         SPO         Discontinuance of non Reids compliant lead fields           ZOBLSTP         ZOBLSTP         None         Valable Now         SPO         Discontinuance of non Reids compliant lead fields           ZOBLSTP         ZOBLSTPG         None         Valable Now         SPO         Discontinuance of non Reids compliant lead fields           ZOBLSTP         ZOBLSTPG         None         Valable Now         SPO         Discontinuance of non Reids compliant lead fields           ZOBLSTP         ZOBLSTPG         None         Valable Now         SPO         Discontinuance of non Reids compliant lead fields           ZOBLSTP         ZOBLSTPG         None         Valable Now         SPO         Discontinuance of non Reids compliant lead fields           ZOBLSTP         ZOBLSTPG         None         Valable Now         SPO         Discontinuance of non Reids compliant lead fields           ZOBLSTP         ZOBLSTPG         None         Valable Now         SPO         Discontinuance of non Reids compliant lead fields           ZOBLSTP         ZOBLSTPG         None         Valable Now         SPO         Discontinuance of non Reids compliant lead fields           ZOBLSTP         ZOBLSTPG         None         Valable Now         SPO         Discontinuance of n						
TOBUSTP         TOBUSTPG         None         Analable Now         Spon         Discontinuance of non Reiss compliant ked finish           TOBUSTP         ZOBLSTPG         None         Analable Now         Spon         Discontinuance of non Reiss compliant ked finish           ZOBLSTP         ZOBLSTPG         None         Analable Now         Spon         Discontinuance of non Reiss compliant ked finish           ZOBLSTP         ZOBLSTPG         None         Analable Now         Spon         Discontinuance of non Reiss compliant ked finish           ZOBLSTPT         ZOBLSTPG         None         Analable Now         Spon         Discontinuance of non Reiss compliant ked finish           ZOBLSTPT         ZOBLSTPG         None         Analable Now         Spon         Discontinuance of non Reiss compliant ked finish           ZOBLSTPT         ZOBLSTPG         None         Analable Now         Spon         Discontinuance of non Reiss compliant ked finish           ZOBLSTPT         ZOBLSTPG         None         Analable Now         Spon         Discontinuance of non Reiss compliant ked finish           ZOBLSTPT         ZOBLSTPG         None         Analable Now         Spon         Discontinuance of non Reiss compliant ked finish           ZOBLSTPT         ZOBLSTPG         None         Analable Now         Spon         Di	7204L12TP	7204L12TPG	None	Available Now	SPO	
Z01157PT         Z01157PT         None         Available Now         Sign         Inscriptional and finish           Z01157PT         Z01157PG         None         Available Now         SO         Discontinuance of no Relds compilant lead finish           Z01157P         Z01157PG         None         Available Now         SO         Discontinuance of no Relds compilant lead finish           Z01157P         Z01127PG         None         Available Now         SO         Discontinuance of no Relds compilant lead finish           Z01157P         Z01127PG         None         Available Now         SO         Discontinuance of no Relds compilant lead finish           Z01157P         Z01127PG         None         Available Now         SO         Discontinuance of no Relds compilant lead finish           Z01157P         Z01127PG         None         Available Now         SO         Discontinuance of no Relds compilant lead finish           Z01157P         Z01127PG         None         Available Now         SO         Discontinuance of no Relds compilant lead finish           Z01157P         Z01127PG         None         Available Now         SO         Discontinuance of no Relds compilant lead finish           Z01157P         Z01127PG         None         Available Now         SO         Discontinuance of no Relds compilant l						
2010.00/P         2020.00/P         None         Available Now         SPO         Discontinuance of non Reds complant lead finich.           2033.157P         2031.157P         2	7203L25TP	7203L20TPG	None	Available Now	SPO	Discontinuance of non RoHS compliant lead finish
7203.157P7203.157PNoneAvailable NoveSPODiscontinuance of non Rols compliant lead finabil7203.157P7203.157PNoneAvailable NoveSPODiscontinuance of non Rols compliant lead finabil7203.157P7203.127PCNoneAvailable NoveSPODiscontinuance of non Rols compliant lead finabil7203.157P7203.127PCNoneAvailable NoveSPODiscontinuance of non Rols compliant lead finabil7203.157P7203.157PCNoneAvailable NoveSPODiscontinuance of non Rols compliant lead finabil7203.157P7203.157P7203.157PCNoneAvailable NoveSPODiscontinuance of non Rols compliant lead finabil7203.157P7203.157P7203.157PCNoneAvailable NoveSPODiscontinuance of non Rols compliant lead finabil7203.157P72						
PD31217P						
Z020A30TPZ020A31TPNoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ020A35TPZ020A31TPRoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ020A32TPZ020A31TPGNoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ020A31TPZ020A31TPGNoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ020A31TPZ020A31TPRoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ020A31TPZ020A31TPRoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ020A31TPZ020A31TPRoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ030A30TPZ020A31TPRoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ030A30TPZ010A32TPNoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ010A32TPZ010A32TPRoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ010A32TPZ010A32TPRoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ010A3TPZ010A3TPRoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ010A3TPZ010A3TPRoneAvailable NowSPGDiscontinuance of non Rots Complaint Led finishZ010A3TPZ010A3TPRoneAvailable NowSPGDiscontinuance of non Rots						
7202.A3STP7202.A1STPGNoneAvailable NowSPGDiscontinuance of non NetS compliant tead finish7202.A3STP7202.A1STPGNoneAvailable NowSPGDiscontinuance of non NetS compliant tead finish7202.A3STP7202.A1STPGNoneAvailable NowSPGDiscontinuance of non NetS compliant tead finish7202.A1STPG702.A1STPGNoneAvailable NowSPGDiscontinuance of non NetS compliant tead finish7203.A1STPG702.A1STPGNoneAvailable NowSPGDiscontinuance of non NetS compliant tead finish7203.A1STP702.A1STPGNoneAvailable NowSPGDiscontinuance of non NetS compliant tead finish7203.A1STP702.A1STPGNoneAvailable NowSPGDiscontinuance of non NetS compliant tead finish7203.A1STP702.01.ATSTGNoneAva						
7202.0.257P7202.0.257PGNoneAvailable NovSPCDiscontinance of no Robits compliant ted finish7202.0.207P7202.0.127PGNoneAvailable NovSPCDiscontinance of no Robits compliant ted finish7202.0.127PGNoneAvailable NovSPCDiscontinance of no Robits compliant ted finish7202.0.127PGNoneAvailable NovSPCDiscontinance of no Robits compliant ted finish7202.0.127PGNoneAvailable NovSPCDiscontinance of no Robits compliant ted finish7201.0.127PGNoneAvailable NovSPCDiscontinance of no Robits compliant ted finish7200.0.127PGNoneAvailable NovSPCDiscontinance of no Robits compliant ted finish7200.0.127PGNoneAvailable NovSPCDiscontinance of no Robits compliant ted finish7200.0.127PGNoneAvailable NovSPCDiscontinance of no Robits compliant ted finish <tr< td=""><td>7202LA35TP</td><td>7202LA12TPG</td><td>None</td><td>Available Now</td><td>SPO</td><td>Discontinuance of non RoHS compliant lead finish</td></tr<>	7202LA35TP	7202LA12TPG	None	Available Now	SPO	Discontinuance of non RoHS compliant lead finish
7202.A3D7P         7202.A3D7FQ         None         Available Now         SPO         Discontinuance of non Rolds compliant lead finish           7202.A1STFP         202.A1STFPG         None         Available Now         SPO         Discontinuance of non Rolds compliant lead finish           7202.A1STFPG         202.A1STFPG         None         Available Now         SPO         Discontinuance of non Rolds compliant lead finish           7201.A1STFPG         7201.A12TFG         None         Available Now         SPO         Discontinuance of non Rolds compliant lead finish           7201.A2STFP         7201.A12TFG         None         Available Now         SPO         Discontinuance of non Rolds compliant lead finish           7201.A2STFP         7201.A2TFG         None         Available Now         SPO         Discontinuance of non Rolds compliant lead finish           7201.A2STFP         7201.A2TFG         None         Available Now         SPO         Discontinuance of non Rolds compliant lead finish           7201.A2STFP         7201.A2TFG         None         Available Now         SPO         Discontinuance of non Rolds compliant lead finish           7201.A2STFP         7201.A2TFG         None         Available Now         SPO         Discontinuance of non Rolds compliant lead finish           7201.A2TFG         None         Available Now<						
2020A1STP         2020A1STPG         None         Available Now         SPO         Discontinuance of non Rols complant lead finich           2020A1STP         2020A1STPG         None         Available Now         SPO         Discontinuance of non Rols complant lead finich           2011ASTP         2011ASTPG         None         Available Now         SPO         Discontinuance of non Rols Complant lead finich           2011ASTP         2011ASTPG         None         Available Now         SPO         Discontinuance of non Rols Complant lead finich           2011ASTP         2011ASTPG         None         Available Now         SPO         Discontinuance of non Rols Complant lead finich           2011ASTP         2011ASTPG         None         Available Now         SPO         Discontinuance of non Rols Complant lead finich           2011ASTP         2011ASTPG         None         Available Now         SPO         Discontinuance of non Rols Complant lead finich           2011ASTP         2011ASTPG         None         Available Now         SPO         Discontinuance of non Rols Complant lead finich           2011ASTP         2010LSTPG         None         Available Now         SPO         Discontinuance of non Rols Complant lead finich           2010LSTP         200LSTPG         None         Available Now         SPO						
2020.1327P         2020.1327FG         None         Available Now         SPO         Discontinuance of non Rols complant lead finish           2020.1A37FP         2010.127FG         None         Available Now         SPO         Discontinuance of non Rols complant lead finish           2011.A37FP         2010.127FG         None         Available Now         SPO         Discontinuance of non Rols complant lead finish           2011.A37FP         2010.127FG         None         Available Now         SPO         Discontinuance of non Rols complant lead finish           2011.A37FP         2010.127FG         None         Available Now         SPO         Discontinuance of non Rols complant lead finish           2011.A37FP         2010.137FG         None         Available Now         SPO         Discontinuance of non Rols complant lead finish           2011.A37FP         2010.137FG         None         Available Now         SPO         Discontinuance of non Rols complant lead finish           2001.517F         2001.217FG         None         Available Now         SPO         Discontinuance of non Rols complant lead finish           2001.517F         2001.217FG         None         Available Now         SPO         Discontinuance of non Rols complant lead finish           2001.517F         2001.217FG         None         Available Now						
Z01LASTP         Z01LAI2TPG         None         Available Now         SPO         Discontinuance of non RMS compliant ked finish           Z01LASTP         Z01LASTPG         None         Available Now         SPO         Discontinuance of non RMS compliant ked finish           Z01LASTP         Z01LASTPG         None         Available Now         SPO         Discontinuance of non RMS compliant ked finish           Z01LASTP         Z01LASTPG         None         Available Now         SPO         Discontinuance of non RMS compliant ked finish           Z01LASTP         Z01LASTPG         None         Available Now         SPO         Discontinuance of non RMS compliant ked finish           Z01LASTP         Z01LASTPG         None         Available Now         SPO         Discontinuance of non RMS compliant ked finish           Z00LSTP         Z00LIZTRG         None         Available Now         SPO         Discontinuance of non RMS compliant ked finish           Z00LSTP         Z00LIZTRG         None         Available Now         SPO         Discontinuance of non RMS compliant ked finish           Z00LSTP         Z00LIZTRG         None         Available Now         SPO         Discontinuance of non RMS compliant ked finish           Z00LSTP         Z00LIZTRG         None         Available Now         SPO         Discontin						
Z2014257P         Z2014.127FG         None         Available Now         SPO         Discontinuance of non Rolts compilant lead finish           Z2014.257FD         Z2014.127FG         None         Available Now         SPO         Discontinuance of non Rolts compilant lead finish           Z2014.127FD         Z2014.127FG         None         Available Now         SPO         Discontinuance of non Rolts compilant lead finish           Z2014.137FP         Z2014.137FG         None         Available Now         SPO         Discontinuance of non Rolts compilant lead finish           Z2014.137FP         Z2014.137FG         None         Available Now         SPO         Discontinuance of non Rolts compilant lead finish           Z2004.37FP         Z2001.27FG         None         Available Now         SPO         Discontinuance of non Rolts compilant lead finish           Z2002.37FP         Z2001.27FG         None         Available Now         SPO         Discontinuance of non Rolts compilant lead finish           Z2001.27F1         Z2001.27FG         None         Available Now         SPO         Discontinuance of non Rolts compilant lead finish           Z2001.27F1         Z2001.27FG         None         Available Now         SPO         Discontinuance of non Rolts compilant lead finish           Z2001.27F1         Z2001.27FG         None						
2011A27FP         2201LA327F0         Variable Now         SPO         Discontinuance of non Rotts compliant tead finish           2011A27F0         7201LA327F6         None         Available Now         SPO         Discontinuance of non Rotts compliant tead finish           2011A37F7         7201LA327F6         None         Available Now         SPO         Discontinuance of non Rotts compliant tead finish           2011A37F7         7201LA37F6         None         Available Now         SPO         Discontinuance of non Rotts compliant tead finish           2001A37F7         7200L37F6         None         Available Now         SPO         Discontinuance of non Rotts compliant tead finish           2000.37F         7200L37F6         None         Available Now         SPO         Discontinuance of non Rotts compliant tead finish           2002.37F         7200L32F6         None         Available Now         SPO         Discontinuance of non Rotts compliant tead finish           2002.37F         7200L32F6         None         Available Now         SPO         Discontinuance of non Rotts compliant tead finish           2002.37F         7200L37F6         None         Available Now         SPO         Discontinuance of non Rotts compliant tead finish           2003.37F         7200L37F6         None         Available Now         SPO						
Z011A157P         Z010A157F6         None         Available Now         SPO         Discontinuance of non Reh3 complant lead finish           Z011A157P         Z010A157F6         None         Available Now         SPO         Discontinuance of non Reh3 complant lead finish           Z010A157P         Z00L217F6         None         Available Now         SPO         Discontinuance of non Reh3 complant lead finish           Z00L357P         Z00L217F6         None         Available Now         SPO         Discontinuance of non Reh3 complant lead finish           Z00L357P         Z00L217F6         None         Available Now         SPO         Discontinuance of non Reh3 complant lead finish           Z00L357P         Z00L217F6         None         Available Now         SPO         Discontinuance of non Reh3 complant lead finish           Z00L357P         Z00L127F6         None         Available Now         SPO         Discontinuance of non Reh3 complant lead finish           Z00L37P         Z00L127F6         None         Available Now         SPO         Discontinuance of non Reh3 complant lead finish           Z00L37P         Z00L127F6         None         Available Now         SPO         Discontinuance of non Reh3 complant lead finish           Z00L37P         Z00L127F6         None         Available Now         SPO	7201LA25TPI	7201LA15TPGI	None	Available Now	SPO	Discontinuance of non RoHS compliant lead finish
Z011AISTPI         Z011AISTPG         None         Available Now         SPO         Discontinuance of non RMS compliant lead flinkh           Z011AISTP         Z011AISTPG         None         Available Now         SPO         Discontinuance of non RMS compliant lead flinkh           Z001ASTP         Z001JITPG         None         Available Now         SPO         Discontinuance of non RMS compliant lead flinkh           Z001JSTP         Z001JITPG         None         Available Now         SPO         Discontinuance of non RMS compliant lead flinkh           Z001JSTP         Z001JITPG         None         Available Now         SPO         Discontinuance of non RMS compliant lead flinkh           Z001JSTP         Z001JITPG         None         Available Now         SPO         Discontinuance of non RMS compliant lead flinkh           Z001JSTP         Z001JITPG         None         Available Now         SPO         Discontinuance of non RMS compliant lead flinkh           Z001JSTP         Z000JITPG         None         Available Now         SPO         Discontinuance of non RMS compliant lead flinkh           Z001JSTP         Z001JITPG         None         Available Now         SPO         Discontinuance of non RMS compliant lead flinkh           Z001JSTP         Z001JITPG         None         Available Now         SPO						
2200132FP200123FPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200132FP2200123FPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200125FP7200123FPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200125FP7200123FPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200125FP7200127FGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200125FP17200127FGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200125FP17200127FGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200127FP7200127FGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200127FP720127FGNoneAvailable NowSPOSubcontractor Package Discontinuance220135F1720127FGNone227361051588Available NowSPO <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>						
2200.13TP2200.12TPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200.25TP7200.12TPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200.25TP7200.12TPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200.15TP7200.12TPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200.15TP7200.15TPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200.15TP7200.15TPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2200.12TP7200.12TPGNoneAvailable NowSPODiscontinuance of non RoHS compliant lead finish2201.12TP7200.12TPGNoneAvailable NowSPOSubcontractor Package Discontinuance22136451.488None721361051.688Available NowSPOSubcontractor Package Discontinuance2213654.5488None721361051.688Available NowSPOSubcontractor Package Discontinuance22136551.488None721361051.688Available NowSPOSubcontractor Package Discontinuance22136551.488None721361051.688Available NowSPOSubcontractor Package Discontinuance22136551.488None721361051.678Available NowSPOSubcontractor Package Discontinuance22136551.6788None721361051.6788Available NowSPOSubcontractor Package Disconti						
Z200L32FP         Z200L32FPG         None         Available Now         SPO         Discontinuance of non R04S compliant lead finish           Z200L32FP         Z200L32FPG         None         Available Now         SPO         Discontinuance of non R04S compliant lead finish           Z200L32FP         Z200L32FPG         None         Available Now         SPO         Discontinuance of non R04S compliant lead finish           Z200L3FP         Z200L3FPG         None         Available Now         SPO         Discontinuance of non R04S compliant lead finish           Z200L3FP         Z200L3FPG         None         Available Now         SPO         Discontinuance of non R04S compliant lead finish           Z200L3FP         Z200L3FPG         None         Available Now         SPO         Discontinuance of non R04S compliant lead finish           Z200L3FP         Z200L3FPG         None         Z21363L48         Available Now         SPO         Subcontractor Package Discontinuance           Z213645L48B         None         Z213605L54B         Available Now         SPO         Subcontractor Package Discontinuance           Z21365L54B         None         Z213605L54B         Available Now         SPO         Subcontractor Package Discontinuance           Z213655L54B         None         Z213605L57B8         Available Now         <						
Z200L2TPZ200L12TPGNoneAvailable NowSPODiscontinuance of no RoHS compliant lead finishZ200L15TPZ200L15TPGNoneAvailable NowSPODiscontinuance of no RoHS compliant lead finishZ200L15TP1Z200L12TPZ200L12TPGNoneAvailable NowSPODiscontinuance of no RoHS compliant lead finishZ200L12TPZ200L12TPGNoneAvailable NowSPODiscontinuance of no RoHS compliant lead finishZ201L3TPGNoneZ71361051448BAvailable NowSPOSubcontractor Package DiscontinuanceZ213645144B8NoneZ7136105158BAvailable NowSPOSubcontractor Package DiscontinuanceZ213645158BNoneZ71361051678BAvailable NowSPOSubcontractor Package DiscontinuanceZ213651678BNoneZ71361051678BAvailable NowSPOSubcontractor Package DiscontinuanceZ2136551678BNoneZ7136105144BAvailable NowSPOSubcontractor Package DiscontinuanceZ2136551678BNoneZ7136105158BAvailable NowSPOSubcontractor Package DiscontinuanceZ2136551678BNoneZ71361051678BAvailable NowSPOSubcontractor Package DiscontinuanceZ2136551678BNoneZ71361051678BAvailable NowSPOSubcontractor Package DiscontinuanceZ2136551678BNoneZ71361051678BAvailable NowSPOSubcontractor Package DiscontinuanceZ2136551678BNoneZ736105158BAvailable NowSPOSubcontractor Package Discontinuance <td>7200L25TP</td> <td></td> <td>None</td> <td>Available Now</td> <td>SPO</td> <td>Discontinuance of non RoHS compliant lead finish</td>	7200L25TP		None	Available Now	SPO	Discontinuance of non RoHS compliant lead finish
Z200L15TP         Z200L12TPG         None         Available Now         SPO         Discontinuance of non RoHS compliant lead finish           Z200L1STP         Z200L12TPG         None         Available Now         SPO         Discontinuance of no RoHS compliant lead finish           Z200L12TP         Z200L12TPG         None         Available Now         SPO         Discontinuance of no RoHS compliant lead finish           Z200L12TP         Z200L12TPG         None         Z7136105L44BB         Available Now         SPO         Subcontractor Package Discontinuance           Z213645L5B8         None         Z7136105L588         Available Now         SPO         Subcontractor Package Discontinuance           Z213645L67B8         None         Z7136105L588         Available Now         SPO         Subcontractor Package Discontinuance           Z213655L67B8         None         Z7136105L588         Available Now         SPO         Subcontractor Package Discontinuance           Z213655L67B8         None         Z7136105L588         Available Now         SPO         Subcontractor Package Discontinuance           Z213655L67B8         None         Z7136105L588         Available Now         SPO         Subcontractor Package Discontinuance           Z213655L67B8         None         Z7136105L588         Available Now         SPO						
Z200L12TP         Z200L12TPG         None         Available Now         SPO         Discontinuance of non RoHS compliant lead finish           Z213645L4-48B         None         Z2136105L448B         Available Now         SPO         Subcontractor Package Discontinuance           Z213645L5B8I         None         Z2136105L58B         Available Now         SPO         Subcontractor Package Discontinuance           Z213645L5B8         None         Z2136105L57B8         Available Now         SPO         Subcontractor Package Discontinuance           Z213645L57B8         None         Z2136105L67B8         Available Now         SPO         Subcontractor Package Discontinuance           Z213655L57B8         None         Z2136105L57B8         Available Now         SPO         Subcontractor Package Discontinuance           Z213655L57B8         None         Z2136105L58B         Available Now         SPO         Subcontractor Package Discontinuance           Z213655L57B8         None         Z2136105L57B8         Available Now         SPO         Subcontractor Package Discontinuance           Z213655L57B8         None         Z2136105L57B8         Available Now         SPO         Subcontractor Package Discontinuance           Z213695L57B8         None         Z2136105L57B8         Available Now         SPO         Subcontracto						
721364514.488         None         7213610514.488         Available Now         SPO         Subcontractor Package Discontinuance           721364515881         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           72136451588         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           7213655168         None         7213610516788         Available Now         SPO         Subcontractor Package Discontinuance           7213655168         None         7213610516788         Available Now         SPO         Subcontractor Package Discontinuance           72136551581         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           72136551588         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           72136551588         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           72136551588         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           72136551588         None         721361051588         Available Now         SPO         Subcontractor Package Discontin	7200L15TPI	7200L15TPGI				Discontinuance of non RoHS compliant lead finish
P27364SL58BI         None         P2736105L58BI         Available Now         SPO         Subcontractor Package Discontinuance           P27364SL58B         None         P2736105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P27364SL58B         None         P2736105L57B         Available Now         SPO         Subcontractor Package Discontinuance           P27365SL544B8         None         P2735105L44B8         Available Now         SPO         Subcontractor Package Discontinuance           P27365SL58B         None         P2736105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P27365SL58B         None         P2736105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P27365SL567B8         None         P2736105L67B8         Available Now         SPO         Subcontractor Package Discontinuance           P27369SL567B8         None         P2736105L67B8         Available Now         SPO         Subcontractor Package Discontinuance           P27369SL567B8         None         P2736105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P27369SL567B8         None         P2736105L58B         Available Now         SPO         Subcontractor Package						
721364516-788         None         7213610516-788         Available Now         SPO         Subcontractor Package Discontinuance           721365514-488         None         7213610514-488         Available Now         SPO         Subcontractor Package Discontinuance           721365515881         None         7213610515881         Available Now         SPO         Subcontractor Package Discontinuance           72136551588         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           721365515788         None         7213610516-788         Available Now         SPO         Subcontractor Package Discontinuance           721365515788         None         7213610516-788         Available Now         SPO         Subcontractor Package Discontinuance           72136551588         None         7213610515788         Available Now         SPO         Subcontractor Package Discontinuance           72136551588         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           72136551588         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           72136551588         None         721361051588         Available Now         SPO         Subcontractor Packa	72T3645L5BBI	None	72T36105L5BBI	Available Now	SPO	Subcontractor Package Discontinuance
P27365S14-48B         None         P27361DS14-48B         Available Now         SPO         Subcontractor Package Discontinuance           P27365S154B1         None         727361DS158B1         Available Now         SPO         Subcontractor Package Discontinuance           P27365S154B1         None         727361DS158B         Available Now         SPO         Subcontractor Package Discontinuance           P27365S16-78B         None         727361DS16-78B         Available Now         SPO         Subcontractor Package Discontinuance           P27369S15B8         None         727361DS16-78B         Available Now         SPO         Subcontractor Package Discontinuance           P27369S15B8         None         727361DS16-78B         Available Now         SPO         Subcontractor Package Discontinuance           P27369S15B8         None         727361DS15B8         Available Now         SPO         Subcontractor Package Discontinuance           P27369S15448B         None         727361DS15B8         Available Now         SPO         Subcontractor Package Discontinuance           P27369S15448B         None         727361DS15B8         Available Now         SPO         Subcontractor Package Discontinuance           P27369S1548B         None         727361DS15B8         Available Now         SPO         Subcontractor Pa						
7213655L58B         None         72136105L58B         Available Now         SPO         Subcontractor Package Discontinuance           7213655L67B8         None         72136105L67B8         Available Now         SPO         Subcontractor Package Discontinuance           7213655L67B8         None         72136105L67B8         Available Now         SPO         Subcontractor Package Discontinuance           7213695L57B8         None         72136105L67B8         Available Now         SPO         Subcontractor Package Discontinuance           7213695L58B         None         72136105L58B         Available Now         SPO         Subcontractor Package Discontinuance           7213695L448B         None         72136105L58B         Available Now         SPO         Subcontractor Package Discontinuance           7213695L448B         None         72136105L67B8         Available Now         SPO         Subcontractor Package Discontinuance           7213695L54B         None         72136105L67B8         Available Now         SPO         Subcontractor Package Discontinuance           7213695L54B         None         72136105L54B8         Available Now         SPO         Subcontractor Package Discontinuance           7213695L54B         None         72136105L54B8         Available Now         SPO         Subcontractor Package Di	72T3655L4-4BB		72T36105L4-4BB	Available Now	SPO	Subcontractor Package Discontinuance
None         27360516-78B         Available Now         SPO         Subcontractor Package Discontinuance           27369516-78B         None         27360516-78B         Available Now         SPO         Subcontractor Package Discontinuance           27369515-678B         None         273610516-78B         Available Now         SPO         Subcontractor Package Discontinuance           27369515-678B         None         273610516-78B         Available Now         SPO         Subcontractor Package Discontinuance           27369515-681         None         273610516-88         Available Now         SPO         Subcontractor Package Discontinuance           27369514-48B         None         273610516-78B         Available Now         SPO         Subcontractor Package Discontinuance           27369514-48B         None         273610516-78B         Available Now         SPO         Subcontractor Package Discontinuance           27369514-48B         None         273610516-78B         Available Now         SPO         Subcontractor Package Discontinuance           27369514-48B         None         273610514-88B         Available Now         SPO         Subcontractor Package Discontinuance           27369514-48B         None         273610514-88B         Available Now         SPO         Subcontractor Package Discontinuance     <						
P2T3695L578B         None         P2T36105L578B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3695L58B         None         P2T36105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3695L58B         None         P2T36105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3695L54BB         None         P2T36105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3695L74BB         None         P2T36105L44BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3695L74BB         None         P2T36105L74BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3695L74BB         None         P2T36105L74BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3695L74BB         None         P2T36105L78B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3695L74BB         None         P2T36105L48B6         Available Now         SPO         Subcontractor Package Discontinuance           P2T3695L67BB         None         P2T36105L44B8         Available Now         SPO         Subcontractor Package				Available Now		
721369515881         None         7213610515881         Available Now         SPO         Subcontractor Package Discontinuance           721369514-48B         None         7213610516-78B         Available Now         SPO         Subcontractor Package Discontinuance           721369516-78B         None         7213610516-78B         Available Now         SPO         Subcontractor Package Discontinuance           721369516-78B         None         7213610516-78B         Available Now         SPO         Subcontractor Package Discontinuance           721369516-78B         None         7213610516-78B         Available Now         SPO         Subcontractor Package Discontinuance           721369514-48BG         None         721361051588         Available Now         SPO         Subcontractor Package Discontinuance           721369514-48BG         None         721361051448B         Available Now         SPO         Subcontractor Package Discontinuance           72136514-48BG         None         721361051448B         Available Now         SPO         Subcontractor Package Discontinuance           721367516-78B         None         721361051448B         Available Now         SPO         Subcontractor Package Discontinuance           721367516-78B         None         72136105148B         Available Now         SPO         Sub	72T3695L6-7BB					Subcontractor Package Discontinuance
P2T3659L4-48B         None         P2T36105L4-48B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3685L6-7BB         None         72T36105L6-7BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3685L6-7BB         None         72T36105L6-7BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3685L58B         None         72T36105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3685L54B1         None         72T36105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3685L448B6         None         72T36105L448B6         Available Now         SPO         Subcontractor Package Discontinuance           P2T3655L6-7B8         None         72T36105L448B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3655L6-7B8         None         72T36105L448B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3655L6-7B8         None         72T36105L67B8         Available Now         SPO         Subcontractor Package Discontinuance           P2T3675L6-7B8         None         72T36105L5B8         Available Now         SPO         Subcontr						
V21365/L588         None         72136105/L588         Available Now         SPO         Subcontractor Package Discontinuance           7213651/L48BG         None         72136105/L58B         Available Now         SPO         Subcontractor Package Discontinuance           7213651/L48BG         None         72136105/L48BG         Available Now         SPO         Subcontractor Package Discontinuance           7213651/L48BG         None         72136105/L44BB         Available Now         SPO         Subcontractor Package Discontinuance           7213651/L47BB         None         72136105/L44BB         Available Now         SPO         Subcontractor Package Discontinuance           72136751/L67BB         None         72136105/L67BB         Available Now         SPO         Subcontractor Package Discontinuance           72136751/L67BB         None         72136105/L67BB         Available Now         SPO         Subcontractor Package Discontinuance           72136751/L67BB         None         72136105/L67BB         Available Now         SPO         Subcontractor Package Discontinuance           72136751/L67BB         None         72136105/L58B         Available Now         SPO         Subcontractor Package Discontinuance           72136751/L48B         None         72136105/L58B         Available Now         SPO <t< td=""><td>72T3695L4-4BB</td><td>None</td><td>72T36105L4-4BB</td><td>Available Now</td><td>SPO</td><td>Subcontractor Package Discontinuance</td></t<>	72T3695L4-4BB	None	72T36105L4-4BB	Available Now	SPO	Subcontractor Package Discontinuance
Variable         None         72136105L58B         Available Now         SPO         Subcontractor Package Discontinuance           72136451-44B6G         None         72136105L44B6         Available Now         SPO         Subcontractor Package Discontinuance           72136451-44B6G         None         72136105L44B6         Available Now         SPO         Subcontractor Package Discontinuance           72136512-67B6         None         72136105L44B6         Available Now         SPO         Subcontractor Package Discontinuance           7213675L6-7B8         None         72136105L6-7B8         Available Now         SPO         Subcontractor Package Discontinuance           7213675L57B8         None         72136105L5B8         Available Now         SPO         Subcontractor Package Discontinuance           7213675L54         None         72136105L5B8         Available Now         SPO         Subcontractor Package Discontinuance           7213675L44B8         None         72136105L5B8         Available Now         SPO         Subcontractor Package Discontinuance           7213675L44B8         None         72136105L44B8         Available Now         SPO         Subcontractor Package Discontinuance           7213675L4-7B8         None         72136105L44B8         Available Now         SPO         Subcontractor Pack						
P2T3645L4-4BBG         None         72T36105L4-4BBG         Available Now         SPO         Subcontractor Package Discontinuance           P2T3654SL4-4BB         None         72T36105L4-4BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3675L75B         None         72T36105L6-7BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3675L57BB         None         72T36105L6-7BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3675L58B         None         72T36105L57BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3675L54B         None         72T36105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3675L44B         None         72T36105L58B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3675L44B         None         72T36105L44B         Available Now         SPO         Subcontractor Package Discontinuance           P2T3675L44B         None         72T36105L44BB         Available Now         SPO         Subcontractor Package Discontinuance           P2T3655L6-7BB         None         72T36105L6-7BB         Available Now         SPO         Subcontractor						
7213675L6-7B8         None         72136105L6-7B8         Available Now         SPO         Subcontractor Package Discontinuance           7213675L5B8         None         72136105L5B8         Available Now         SPO         Subcontractor Package Discontinuance           7213675L5B8         None         72136105L5B8         Available Now         SPO         Subcontractor Package Discontinuance           7213675L5B8         None         72136105L5B8         Available Now         SPO         Subcontractor Package Discontinuance           7213675L5B8         None         72136105L64B8         Available Now         SPO         Subcontractor Package Discontinuance           7213665L6-7B8         None         72136105L6-7B8         Available Now         SPO         Subcontractor Package Discontinuance	72T3645L4-4BBG	None	72T36105L4-4BBG		SPO	Subcontractor Package Discontinuance
7213675L58B         None         72136105L58B         Available Now         SPO         Subcontractor Package Discontinuance           7213675L58B1         None         72136105L58B1         Available Now         SPO         Subcontractor Package Discontinuance           7213675L44B8         None         72136105L44BB         Available Now         SPO         Subcontractor Package Discontinuance           7213655L6-7B8         None         72136105L6-7B8         Available Now         SPO         Subcontractor Package Discontinuance						
72T3675L4-4BB         None         72T36105L4-4BB         Available Now         SPO         Subcontractor Package Discontinuance           72T3665L6-7BB         None         72T36105L6-7BB         Available Now         SPO         Subcontractor Package Discontinuance	72T3675L5BB	None	72T36105L5BB	Available Now	SPO	Subcontractor Package Discontinuance
72T3665L6-7BB None 72T36105L6-7BB Available Now SPO Subcontractor Package Discontinuance						Subcontractor Package Discontinuance
	72T3665L6-7BB		72T36105L6-7BB		SPO	
	72T3665L5BB	None	72T36105L5BB	Available Now	SPO	Subcontractor Package Discontinuance
72T3665L58BI         None         72T36105L58BI         Available Now         SPO         Subcontractor Package Discontinuance           72T3665L4-4BB         None         72T36105L4-4BB         Available Now         SPO         Subcontractor Package Discontinuance						
72T3665L4-4BBG None 72T36105L4-4BBG Available Now SPO Subcontractor Package Discontinuance						