



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: N-16-02 **Last Time Buy Date:** September 7, 2016
Issue Date: March 7, 2016 **Last Time Ship Date:** March 7, 2017
Contact: Pete Jenkins (peter.jenkins@idt.com)

Refer to the attached Affected parts list with drop in or functional part replacement #

Samples of the replacement parts are available now.

REASON FOR DISCONTINUANCE:

- ☐ Replace slower speed with faster speed offerings
- ☐ Obsolete Fab Technology / Process
- ☐ Obsolete Assembly Technology / Process
- ☐ Obsolete Package / Material
- ☒ Declined Market
- ☐ Other:

PDN N-16-02 Affected Parts List

Device to be Discontinued	Direct Replacement	Functional Replacement	Reason for Discontinuance
5T9070PAGI		8T39S11ANLGI	Market Decline
5T9070PAGI8		8T39S11ANLGI8	Market Decline
5T907PAGI		8T39S11ANLGI	Market Decline
5T907PAGI8		8T39S11ANLGI8	Market Decline
5T9302EJGI		8SLVP1102ANLGI	Market Decline
5T9302EJGI8		8SLVP1102ANLGI8	Market Decline
5T93GL02PGGI		8SLVP1102ANLGI	Market Decline
5T93GL02PGGI8		8SLVP1102ANLGI8	Market Decline
5T93GL04PGGI		8SLVD1204NLGI	Market Decline
5T93GL04PGGI8		8SLVD1204NLGI8	Market Decline
5T93GL061PFGI		8SLVD1208NBGI	Market Decline
5T93GL061PFGI8		8SLVD1208NBGI8	Market Decline
5T93GL06NLGI		8SLVD1208NBGI	Market Decline
5T93GL06NLGI8		8SLVD1208NBGI8	Market Decline
5V925BQGI		8T49N242NLGI	Market Decline
5V925BQGI8		8T49N242NLGI8	Market Decline
74FCT388915TBJG		8T49N286A-dddNLGI	Market Decline
74FCT388915TBJG8		8T49N286A-dddNLGI8	Market Decline
74FCT388915TBPYG		8T49N286A-dddNLGI	Market Decline
74FCT388915TBPYG8		8T49N286A-dddNLGI8	Market Decline
74FCT388915TCJG		8T49N286A-dddNLGI	Market Decline
74FCT388915TCJG8		8T49N286A-dddNLGI8	Market Decline
74FCT388915TCPYG		8T49N286A-dddNLGI	Market Decline
74FCT388915TCPYG8		8T49N286A-dddNLGI8	Market Decline
74FCT388915TDJG		8T49N286A-dddNLGI	Market Decline
74FCT388915TDJG8		8T49N286A-dddNLGI8	Market Decline
74FCT388915TDPYG		8T49N286A-dddNLGI	Market Decline
74FCT388915TDPYG8		8T49N286A-dddNLGI8	Market Decline
74FCT388915TEJG		8T49N286A-dddNLGI	Market Decline
74FCT388915TEJG8		8T49N286A-dddNLGI8	Market Decline
74FCT388915TEPYG		8T49N286A-dddNLGI	Market Decline
74FCT388915TEPYG8		8T49N286A-dddNLGI8	Market Decline
841N151BY-01LF		8V41N351Y-01LF	Market Decline
841N151BY-01LFT		8V41N351Y-01LFT	Market Decline
85211AMI-01LF		8523CGLF	Market Decline
85211AMI-01LFT		8523CGLFT	Market Decline
85211BMI-03LN		8523CGLF	Market Decline
85211BMI-03LNT		8523CGLFT	Market Decline
874003DG-02LF	874003AG-02LF		Market Decline
874003DG-02LFT	874003AG-02LFT		Market Decline
874003DGI-02LF	874003AGI-02LF		Market Decline
874003DGI-02LFT	874003AGI-02LFT		Market Decline
9DB202CFLF		8714004DKILF	Market Decline
9DB202CFLFT		8714004DKILF	Market Decline
9DB202CGLF		8714004DKILF	Market Decline
9DB202CGLFT		8714004DKILF	Market Decline

PDN N-16-02 Affected Parts List

Device to be Discontinued	Direct Replacement	Functional Replacement	Reason for Discontinuance
9DB202CK-01LF		8714004DKILF	Market Decline
9DB202CK-01LFT		8714004DKILF	Market Decline
9DB206CFLF		8714008DKILF	Market Decline
9DB206CFLFT		8714008DKILF	Market Decline
9DB206CLLF		8714008DKILF	Market Decline
9DB206CLLFT		8714008DKILF	Market Decline
MPC9330AC		8T49N285A-dddNLGI	Market Decline
MPC9330ACR2		8T49N285A-dddNLGI8	Market Decline
MPC9331AC		8T49N285A-dddNLGI	Market Decline
MPC9331ACR2		8T49N285A-dddNLGI8	Market Decline
MPC9350AC		87973DYILF	Market Decline
MPC9350ACR2		87973DYILFT	Market Decline
MPC9351AC		8T49N285A-dddNLGI	Market Decline
MPC9351ACR2		8T49N285A-dddNLGI8	Market Decline
MPC9352AC		8T49N285A-dddNLGI	Market Decline
MPC9352ACR2		8T49N285A-dddNLGI8	Market Decline
MPC93H51AC		8T49N285A-dddNLGI	Market Decline
MPC93H51ACR2		8T49N285A-dddNLGI8	Market Decline
MPC93H52AC		8T49N285A-dddNLGI	Market Decline
MPC93H52ACR2		8T49N285A-dddNLGI8	Market Decline
MPC93R51AC		8T49N285A-dddNLGI	Market Decline
MPC93R51ACR2		8T49N285A-dddNLGI8	Market Decline
MPC93R52AC		8T49N285A-dddNLGI	Market Decline
MPC93R52ACR2		8T49N285A-dddNLGI8	Market Decline
MPC9443AE		87016AYILF	Market Decline
MPC9443AER2		87016AYILFT	Market Decline
MPC9446AC	87946AYI-147LF		Market Decline
MPC9446ACR2	87946AYI-147LFT		Market Decline
MPC9447AC	83947AYILN		Market Decline
MPC9447ACR2	83947AYILNT		Market Decline
MPC9448AC	83948AYI-147LF		Market Decline
MPC9448ACR2	83948AYI-147LFT		Market Decline
MPC9449AE		8T49N285A-dddNLGI	Market Decline
MPC9449AER2		8T49N285A-dddNLGI8	Market Decline
MPC94551EF	551MILF		Market Decline
MPC94551EFR2	551MILFT		Market Decline
MPC9456AC		87946AYI-147LF	Market Decline
MPC9456ACR2		87946AYI-147LFT	Market Decline
MPC9600AE		8761CYILF	Market Decline
MPC9600AER2		8761CYILFT	Market Decline
MPC9608AC		2308-2HDCG	Market Decline
MPC9608ACR2		2308-2HDCG8	Market Decline
MPC962305EF-1	2305-1DCG		Market Decline
MPC962305EF-1H	2305-1HDCG		Market Decline
MPC962305EF-1HR2	2305-1HDCG8		Market Decline
MPC962305EF-1R2	2305-1DCG8		Market Decline

PDN N-16-02 Affected Parts List

Device to be Discontinued	Direct Replacement	Functional Replacement	Reason for Discontinuance
MPC962305EJ-1H	2305-1PGG		Market Decline
MPC962305EJ-1HR2	2305-1PGG8		Market Decline
MPC962308EF-1H	2308-1HDCG		Market Decline
MPC962308EF-1HR2	2308-1HDCG8		Market Decline
MPC962308EJ-1H	2308-1HPGG		Market Decline
MPC962308EJ-1HR2	2308-1HPGG8		Market Decline
MPC962309EF-1H	2309-1HDCG		Market Decline
MPC962309EF-1HR2	2309-1HDCG8		Market Decline
MPC962309EJ-1H	2309-1HPPG		Market Decline
MPC962309EJ-1HR2	2309-1HPPG8		Market Decline
MPC9772AE	87972DYI-147LF		Market Decline
MPC9772AER2	87972DYI-147LFT		Market Decline
MPC9773AE	87973DYILF		Market Decline
MPC9773AER2	87973DYILFT		Market Decline
MPC9774AE	87974CYILF		Market Decline
MPC9774AER2	87974CYILFT		Market Decline
MPC97H73AE	87973DYILF		Market Decline
MPC97H73AER2	87973DYILFT		Market Decline
MPC97H74AE	87974CYILF		Market Decline
MPC97H74AER2	87974CYILFT		Market Decline
MPC9824AC		8T49N285A-dddNLGI	Market Decline
MPC9824ACR2		8T49N285A-dddNLGI8	Market Decline
MPC9893AE		87973DYILF	Market Decline
MPC9893AER2		87973DYILFT	Market Decline
Note: ddd indicates programmable part			