

End-Of-Life Notice
(Notification – PLC210007)
[Issue Date – 7/6/2021]

To: Our Valued Customers

Overview: The purpose of this notification is to communicate that Renesas Electronics has begun the End-of-Life (EOL) Process on select part numbers.

Affected Products: Attached is a list of products affected by this notification. Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

Key Dates:	Final Last Time Buy (LTB) Orders placed after this date will not be processed.	1/6/2022
	Last Shipment (LTS)	7/6/2022

Response: Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Renesas Electronics America Inc. will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Any order resulting from this notice shall be governed by Renesas’s General Terms and Conditions Available at: [General Term and Conditions](#) or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.

Please contact your local sales representative for any questions or comments.

Thank you for your attention.

Sincerely,
Renesas Electronics

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
280G-57LF	7/6/2021	1/6/2022	7/6/2022	None
280G-57LFT	7/6/2021	1/6/2022	7/6/2022	None
290GI-34LF	7/6/2021	1/6/2022	7/6/2022	None
290GI-34LFT	7/6/2021	1/6/2022	7/6/2022	None
307G-03LF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
307G-03LFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
307GI-03LF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
307GI-03LFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
342MPLF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
342MPLFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
343M-53LF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
343M-53LFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
343M-62LF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
343M-62LFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
345R-62LF	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
345R-62LFT	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
345R-65LF	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
345R-65LFT	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
345RI-02LF	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
345RI-02LFT	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
345RI-13LF	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
345RI-13LFT	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
4DB0226KA3AVG	7/6/2021	1/6/2022	7/6/2022	4DB0232KC2AVG
4DB0226KA3AVG8	7/6/2021	1/6/2022	7/6/2022	4DB0232KC2AVG8
512MILF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
512MILFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
512MLF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
512MLFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
525R-02ILF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
525R-02ILFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
558G-01LF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
558G-01LFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
580M-01ILF	7/6/2021	1/6/2022	7/6/2022	None
580M-01ILFT	7/6/2021	1/6/2022	7/6/2022	None
580M-01LF	7/6/2021	1/6/2022	7/6/2022	None
580M-01LFT	7/6/2021	1/6/2022	7/6/2022	None
581G-01ILF	7/6/2021	1/6/2022	7/6/2022	None
581G-01ILFT	7/6/2021	1/6/2022	7/6/2022	None
581G-01LF	7/6/2021	1/6/2022	7/6/2022	None
581G-01LFT	7/6/2021	1/6/2022	7/6/2022	None
5P49EE502-013NDGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5P49EE502-013NDGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5P49EE502-015NDGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5P49EE502-015NDGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5P49EE502-128NDG	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5P49EE502-128NDG8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5P49EE502-166NDGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5P49EE502-166NDGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5P49EE802NDGI	7/6/2021	1/6/2022	7/6/2022	5P49V6967A000NDGI
5P49EE802NDGI8	7/6/2021	1/6/2022	7/6/2022	5P49V6967A000NDGI8
5V19EE403-003NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V19EE403-003NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V19EE902NLGI	7/6/2021	1/6/2022	7/6/2022	None
5V19EE902NLGI8	7/6/2021	1/6/2022	7/6/2022	None
5V49EE501-094NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE501-094NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE501-098NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE501-098NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE501-125NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE501-125NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE503-027NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE503-027NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
5V49EE503-046NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE503-046NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE503-055NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE503-055NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE503-068NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE503-068NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE503-099NLG	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE503-099NLG8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE503-128NLG	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE503-128NLG8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE702-198NDGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE901-078NLG	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE901-078NLG8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE901-113NLG	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE901-113NLG8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE901-124NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE901-124NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE901-128NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE901-128NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE901-158NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE901-158NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE902-024NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE902-024NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE902-061NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE902-061NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE902-211NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE902-211NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE902-252NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE902-252NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE902-254NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE902-254NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE903-003PGGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE903-003PGGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE903-111NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE903-111NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE904-074NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE904-074NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE904-164NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE904-164NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE904-168NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE904-168NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V49EE904-172NLGI	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG2
5V49EE904-172NLGI8	7/6/2021	1/6/2022	7/6/2022	5P35023-000NLG28
5V9885T-003PFGI	7/6/2021	1/6/2022	7/6/2022	None
5V9885T-003PFGI8	7/6/2021	1/6/2022	7/6/2022	None
5V9885T-006NLGI	7/6/2021	1/6/2022	7/6/2022	None
5V9885T-006NLGI8	7/6/2021	1/6/2022	7/6/2022	None
5V9885T-007NLGI	7/6/2021	1/6/2022	7/6/2022	None
5V9885T-007NLGI8	7/6/2021	1/6/2022	7/6/2022	None
5V9885T-020NLGI	7/6/2021	1/6/2022	7/6/2022	None
5V9885T-020NLGI8	7/6/2021	1/6/2022	7/6/2022	None
5V9885TNLGI	7/6/2021	1/6/2022	7/6/2022	None
5V9885TNLGI8	7/6/2021	1/6/2022	7/6/2022	None
5V9888T-020NLGI	7/6/2021	1/6/2022	7/6/2022	None
5V9888T-020NLGI8	7/6/2021	1/6/2022	7/6/2022	None
6116LA20TPG	7/6/2021	1/6/2022	7/6/2022	None
6116LA20TPGI	7/6/2021	1/6/2022	7/6/2022	None
6116LA25TPG	7/6/2021	1/6/2022	7/6/2022	None
6116LA25TPGI	7/6/2021	1/6/2022	7/6/2022	None
6116SA15TPG	7/6/2021	1/6/2022	7/6/2022	None
6116SA20TPG	7/6/2021	1/6/2022	7/6/2022	None
6116SA20TPGI	7/6/2021	1/6/2022	7/6/2022	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
6116SA25TPG	7/6/2021	1/6/2022	7/6/2022	None
6116SA25TPGI	7/6/2021	1/6/2022	7/6/2022	None
650R-27ILF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
650R-27ILFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
661GILF	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG2
661GILFT	7/6/2021	1/6/2022	7/6/2022	5P35021-000NDG28
6P40089NTGI	7/6/2021	1/6/2022	7/6/2022	5L1503S-000NVGI
6P40089NTGI8	7/6/2021	1/6/2022	7/6/2022	5L1503S-000NVGI8
6P40367NDGI	7/6/2021	1/6/2022	7/6/2022	None
6P40367NDGI8	7/6/2021	1/6/2022	7/6/2022	None
6V49004BPAGI	7/6/2021	1/6/2022	7/6/2022	None
6V49004BPAGI8	7/6/2021	1/6/2022	7/6/2022	None
6V49206NLGI	7/6/2021	1/6/2022	7/6/2022	None
6V49206NLGI8	7/6/2021	1/6/2022	7/6/2022	None
6V49239BNLGI	7/6/2021	1/6/2022	7/6/2022	None
6V49239BNLGI8	7/6/2021	1/6/2022	7/6/2022	None
7130LA100PDG	7/6/2021	1/6/2022	7/6/2022	None
7130LA35PDG	7/6/2021	1/6/2022	7/6/2022	None
7130LA55PDGI	7/6/2021	1/6/2022	7/6/2022	None
7132LA100PDG	7/6/2021	1/6/2022	7/6/2022	None
7132LA35PDG	7/6/2021	1/6/2022	7/6/2022	None
7132LA35PDGI	7/6/2021	1/6/2022	7/6/2022	None
7132LA55PDGI	7/6/2021	1/6/2022	7/6/2022	None
7132SA55PDG	7/6/2021	1/6/2022	7/6/2022	None
7134LA20PDG	7/6/2021	1/6/2022	7/6/2022	None
7134LA25PDG	7/6/2021	1/6/2022	7/6/2022	None
7134LA25PDGI	7/6/2021	1/6/2022	7/6/2022	None
7140LA100PDG	7/6/2021	1/6/2022	7/6/2022	None
7140LA35PDG	7/6/2021	1/6/2022	7/6/2022	None
7142LA100PDG	7/6/2021	1/6/2022	7/6/2022	None
7142LA35PDG	7/6/2021	1/6/2022	7/6/2022	None
7152AMI-11LF	7/6/2021	1/6/2022	7/6/2022	None
7152AMI-11LFT	7/6/2021	1/6/2022	7/6/2022	None
7152M-01LF	7/6/2021	1/6/2022	7/6/2022	5P50912NBGI
7152M-01LFT	7/6/2021	1/6/2022	7/6/2022	5P50912NBGI8
7152MI-01LF	7/6/2021	1/6/2022	7/6/2022	5P50912NBGI
7152MI-01LFT	7/6/2021	1/6/2022	7/6/2022	5P50912NBGI8
7201LA12PDG	7/6/2021	1/6/2022	7/6/2022	None
7201LA35PDG	7/6/2021	1/6/2022	7/6/2022	None
7201LA50PDG	7/6/2021	1/6/2022	7/6/2022	None
7202LA12PDG	7/6/2021	1/6/2022	7/6/2022	None
7202LA15PDGI	7/6/2021	1/6/2022	7/6/2022	None
7203L12PDG	7/6/2021	1/6/2022	7/6/2022	None
7204L12PDG	7/6/2021	1/6/2022	7/6/2022	None
7204L15PDGI	7/6/2021	1/6/2022	7/6/2022	None
7205L12PDG	7/6/2021	1/6/2022	7/6/2022	None
7206L15PDG	7/6/2021	1/6/2022	7/6/2022	None
7207L15PDG	7/6/2021	1/6/2022	7/6/2022	None
74ALVCHS162830DF	7/6/2021	1/6/2022	7/6/2022	None
74ALVCHS162830DF/	7/6/2021	1/6/2022	7/6/2022	None
74ALVCHS162830DF8	7/6/2021	1/6/2022	7/6/2022	None
82V3255EDG	7/6/2021	1/6/2022	7/6/2022	8A34004E-000NBG
82V3255EDG8	7/6/2021	1/6/2022	7/6/2022	8A34004E-000NBG8
82V3255TFG	7/6/2021	1/6/2022	7/6/2022	8A34004E-000NBG
82V3255TFG8	7/6/2021	1/6/2022	7/6/2022	8A34004E-000NBG8
82V3255TFG8-ECI	7/6/2021	1/6/2022	7/6/2022	8A34004E-000NBG8
82V3255TFG-ECI	7/6/2021	1/6/2022	7/6/2022	8A34004E-000NBG
82V3380AEQG	7/6/2021	1/6/2022	7/6/2022	82P33810ABAG
82V3380AEQG8	7/6/2021	1/6/2022	7/6/2022	82P33810ABAG8
853S310CVILF	7/6/2021	1/6/2022	7/6/2022	None
853S310CVILFT	7/6/2021	1/6/2022	7/6/2022	None
872S06AYLF	7/6/2021	1/6/2022	7/6/2022	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
872506AYLFT	7/6/2021	1/6/2022	7/6/2022	None
872533CYLF	7/6/2021	1/6/2022	7/6/2022	None
872533CYLFT	7/6/2021	1/6/2022	7/6/2022	None
8T79S838-08NLGI	7/6/2021	1/6/2022	7/6/2022	None
9173B-01CS08LF	7/6/2021	1/6/2022	7/6/2022	5P49V6967A000NDGI
9173B-01CS08LFT	7/6/2021	1/6/2022	7/6/2022	5P49V6967A000NDGI8
9173B-15CS08LF	7/6/2021	1/6/2022	7/6/2022	5P49V6967A000NDGI
9173B-15CS08LFT	7/6/2021	1/6/2022	7/6/2022	5P49V6967A000NDGI8
952926CGLF	7/6/2021	1/6/2022	7/6/2022	None
952926CGLFT	7/6/2021	1/6/2022	7/6/2022	None
954201BGLF	7/6/2021	1/6/2022	7/6/2022	None
954201BGLFT	7/6/2021	1/6/2022	7/6/2022	None
95V857AGLFT/B	7/6/2021	1/6/2022	7/6/2022	None
97ULP845AHILF	7/6/2021	1/6/2022	7/6/2022	None
97ULP845AHILFT	7/6/2021	1/6/2022	7/6/2022	None
97ULP845AHLF	7/6/2021	1/6/2022	7/6/2022	None
97ULP845AHLFT	7/6/2021	1/6/2022	7/6/2022	None
9LVRS720BKLF	7/6/2021	1/6/2022	7/6/2022	None
9LVRS720BKLFT	7/6/2021	1/6/2022	7/6/2022	None
9UM709BGLF	7/6/2021	1/6/2022	7/6/2022	None
9UM709BGLFT	7/6/2021	1/6/2022	7/6/2022	None
9UMS9610CKLF	7/6/2021	1/6/2022	7/6/2022	None
9UMS9610CKLFT	7/6/2021	1/6/2022	7/6/2022	None
9VRS4883BKLF	7/6/2021	1/6/2022	7/6/2022	None
9VRS4883BKLFT	7/6/2021	1/6/2022	7/6/2022	None
CSPF2510CPGG	7/6/2021	1/6/2022	7/6/2022	None
CSPF2510CPGG8	7/6/2021	1/6/2022	7/6/2022	None
HXC42200-BFI	7/6/2021	1/6/2022	7/6/2022	None
HXC42200-EVB	7/6/2021	1/6/2022	7/6/2022	None
HXC42400-BFI	7/6/2021	1/6/2022	7/6/2022	None
HXC42400-EVB	7/6/2021	1/6/2022	7/6/2022	None
HXC44200-BFI	7/6/2021	1/6/2022	7/6/2022	None
HXR14450-DNU/C	7/6/2021	1/6/2022	7/6/2022	HXR14450-DNU
HXR42100-DNT	7/6/2021	1/6/2022	7/6/2022	HXR8201-DNG
HXR5004B-DNT	7/6/2021	1/6/2022	7/6/2022	None
HXR5104A-DNT	7/6/2021	1/6/2022	7/6/2022	None
HXR5104A-EVB	7/6/2021	1/6/2022	7/6/2022	None
HXR8204-QUAL	7/6/2021	1/6/2022	7/6/2022	HXR8204-DNG
HXR8212-QUAL	7/6/2021	1/6/2022	7/6/2022	HXR8212-DNG
HXT14100-TNU	7/6/2021	1/6/2022	7/6/2022	HXT14100-DNU
HXT14450-DNU/C	7/6/2021	1/6/2022	7/6/2022	HXT14450-DNU
HXT42400-DNU	7/6/2021	1/6/2022	7/6/2022	HXT8204-DNG
HXT44100-DNU/C	7/6/2021	1/6/2022	7/6/2022	HXT44120-DNG
HXT44101-CLU-TR	7/6/2021	1/6/2022	7/6/2022	None
HXT44400-DNU/C	7/6/2021	1/6/2022	7/6/2022	HXT44420-DNG
HXT5104A-EVB	7/6/2021	1/6/2022	7/6/2022	None
HXT6104-DNT/D	7/6/2021	1/6/2022	7/6/2022	HXT6104-DNT
HXT8204-QUAL	7/6/2021	1/6/2022	7/6/2022	HXT8204-DNG
HXT8212-QUAL	7/6/2021	1/6/2022	7/6/2022	HXT8212-DNG
LV810RILF	7/6/2021	1/6/2022	7/6/2022	None
LV810RILFT	7/6/2021	1/6/2022	7/6/2022	None
MK2703BSLF	7/6/2021	1/6/2022	7/6/2022	5P50912NBGI
MK2703BSLFTR	7/6/2021	1/6/2022	7/6/2022	5P50912NBGI8
MK2703SILF	7/6/2021	1/6/2022	7/6/2022	None
MK2703SILFTR	7/6/2021	1/6/2022	7/6/2022	None
MK2716SLF	7/6/2021	1/6/2022	7/6/2022	None
MK2716SLFTR	7/6/2021	1/6/2022	7/6/2022	None
MK74CB218RLF	7/6/2021	1/6/2022	7/6/2022	None
MK74CB218RLFTR	7/6/2021	1/6/2022	7/6/2022	None
P8800-001NDG	7/6/2021	1/6/2022	7/6/2022	None
P8800-001NDG8	7/6/2021	1/6/2022	7/6/2022	None
P8800-001NDGI	7/6/2021	1/6/2022	7/6/2022	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
P8800-001NDGI8	7/6/2021	1/6/2022	7/6/2022	None
P8800-002NDG	7/6/2021	1/6/2022	7/6/2022	None
P8800-002NDG8	7/6/2021	1/6/2022	7/6/2022	None
P8800-003NDG	7/6/2021	1/6/2022	7/6/2022	None
P8800-003NDG8	7/6/2021	1/6/2022	7/6/2022	None
P8800-004NDG	7/6/2021	1/6/2022	7/6/2022	None
P8800-004NDG8	7/6/2021	1/6/2022	7/6/2022	None
P8800-A01NDGI	7/6/2021	1/6/2022	7/6/2022	None
P8800-A01NDGI8	7/6/2021	1/6/2022	7/6/2022	None
P9025AC-0AWGI	7/6/2021	1/6/2022	7/6/2022	None
P9025AC-0AWGI8	7/6/2021	1/6/2022	7/6/2022	None
P9025AC-0NBGI	7/6/2021	1/6/2022	7/6/2022	P9025AC-RNBGI
P9025AC-0NBGI8	7/6/2021	1/6/2022	7/6/2022	P9025AC-RNBGI8
P9025AC-EVK	7/6/2021	1/6/2022	7/6/2022	P9025AC-R-EVK
P9221S-0AHGI	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-0AHGI8	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-2AHGI	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-2AHGI8	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-3AHGI	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-3AHGI8	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-4AHGI	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-4AHGI8	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-5AHGI	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-5AHGI8	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-JAHGI	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9221S-JAHGI8	7/6/2021	1/6/2022	7/6/2022	P9221-0AHGI8
P9222-1AZGI	7/6/2021	1/6/2022	7/6/2022	P9222-0AZGI8
P9222-1AZGI8	7/6/2021	1/6/2022	7/6/2022	P9222-0AZGI8
P9222-2AZGI	7/6/2021	1/6/2022	7/6/2022	P9222-0AZGI8
P9222-2AZGI8	7/6/2021	1/6/2022	7/6/2022	P9222-0AZGI8
P9222-3AZGI	7/6/2021	1/6/2022	7/6/2022	P9222-0AZGI8
P9222-3AZGI8	7/6/2021	1/6/2022	7/6/2022	P9222-0AZGI8
P9260-0NLG2	7/6/2021	1/6/2022	7/6/2022	P9260-BNLG2
P9260-0NLG28	7/6/2021	1/6/2022	7/6/2022	P9260-BNLG28
P9261-0NLG2	7/6/2021	1/6/2022	7/6/2022	P9261-3CNLG2
P9261-0NLG28	7/6/2021	1/6/2022	7/6/2022	P9261-3CNLG28
P9261-2C-EVK	7/6/2021	1/6/2022	7/6/2022	P9261-3C-CRB
P9261-2CNLG2	7/6/2021	1/6/2022	7/6/2022	P9261-3CNLG2
P9261-2CNLG28	7/6/2021	1/6/2022	7/6/2022	P9261-3CNLG28
P9261-BNLG2	7/6/2021	1/6/2022	7/6/2022	P9261-3CNLG2
P9261-BNLG28	7/6/2021	1/6/2022	7/6/2022	P9261-3CNLG28
P9382A-2AHGI	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9382A-2AHGI8	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9382A-3AHGI	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9382A-3AHGI8	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9382A-4AHGI	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9382A-4AHGI8	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9382A-7AHGI	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9382A-7AHGI8	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9382A-8AHGI	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9382A-8AHGI8	7/6/2021	1/6/2022	7/6/2022	P9382A-0AHGI8
P9415-2AWQI	7/6/2021	1/6/2022	7/6/2022	P9415-0AWQI8
P9415-2AWQI8	7/6/2021	1/6/2022	7/6/2022	P9415-0AWQI8
P9415-4AWQI	7/6/2021	1/6/2022	7/6/2022	P9415-0AWQI8
P9415-4AWQI8	7/6/2021	1/6/2022	7/6/2022	P9415-0AWQI8
QS32X2384Q1G	7/6/2021	1/6/2022	7/6/2022	None
QS32X2384Q1G8	7/6/2021	1/6/2022	7/6/2022	None
QS32X384Q1G	7/6/2021	1/6/2022	7/6/2022	None
QS32X384Q1G5	7/6/2021	1/6/2022	7/6/2022	None
QS32X384Q1G8	7/6/2021	1/6/2022	7/6/2022	None
QS32X861Q1G	7/6/2021	1/6/2022	7/6/2022	None
QS32X861Q1G8	7/6/2021	1/6/2022	7/6/2022	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
QS32XVH384Q1G	7/6/2021	1/6/2022	7/6/2022	None
QS32XVH384Q1G8	7/6/2021	1/6/2022	7/6/2022	None
QS33X257Q1G	7/6/2021	1/6/2022	7/6/2022	None
QS33X257Q1G8	7/6/2021	1/6/2022	7/6/2022	None
QS34X2245Q3G	7/6/2021	1/6/2022	7/6/2022	None
QS34X2245Q3G8	7/6/2021	1/6/2022	7/6/2022	None
QS34X245Q3G	7/6/2021	1/6/2022	7/6/2022	None
QS34X245Q3G8	7/6/2021	1/6/2022	7/6/2022	None
QS34X383Q3G	7/6/2021	1/6/2022	7/6/2022	None
QS34X383Q3G8	7/6/2021	1/6/2022	7/6/2022	None
QS34XVH2245Q3G	7/6/2021	1/6/2022	7/6/2022	None
QS34XVH2245Q3G8	7/6/2021	1/6/2022	7/6/2022	None
QS34XVH245Q3G	7/6/2021	1/6/2022	7/6/2022	None
QS34XVH245Q3G8	7/6/2021	1/6/2022	7/6/2022	None
SSTUA32864BHLF_	7/6/2021	1/6/2022	7/6/2022	None
SSTUA32864BHLFT_	7/6/2021	1/6/2022	7/6/2022	None
SSTVA16859CGLF	7/6/2021	1/6/2022	7/6/2022	None
SSTVA16859CGLFT	7/6/2021	1/6/2022	7/6/2022	None
SSTVA16859CKLF	7/6/2021	1/6/2022	7/6/2022	None
SSTVA16859CKLF/W	7/6/2021	1/6/2022	7/6/2022	None
SSTVA16859CKLFT	7/6/2021	1/6/2022	7/6/2022	None
SSTVF16859BKLF/W	7/6/2021	1/6/2022	7/6/2022	None
ZWIR4512AC1RA	7/6/2021	1/6/2022	7/6/2022	None
ZWIR4512AC1RC001	7/6/2021	1/6/2022	7/6/2022	None
ZWIR4512AC1WI	7/6/2021	1/6/2022	7/6/2022	None
ZWIR4532-U	7/6/2021	1/6/2022	7/6/2022	ZWIR4512