E10A-USB Emulator Software Component List for H8SX device group

		E10A-USB		components		E10AUSB	elf-				
Status	Release d date	Emulator Software	High- performance Embedded Workshop	H8SX	Firmware for H8SX Device Group	Self- diagnosing program	E1usb .sys	HMSEUsb .sys	E1usbdrv .dll	usbdrv .dll	Related <u>Tool News</u>
Latest version	13/06/16	V.3.06 Release00	V4.09.01 *	V.3.02.00			V.4.0.0.1		V.3.1.2.0		June 16, 2013 issue (TN8) (Target devices added.)
	12/10/01	V.3.05 Release00		V.3.01.01				V1.18 (32bit)			October 01, 2012 issue (TN4)
	12/02/16	V.3.04 Release01	V4.09.00	V.3.01.00		V2.01 **		V1.19 (64bit)			February 16, 2012 issue (TN10)
	11/11/16	V.3.04 Release00	V4.03.00	V.3.01.00							November 16, 2011 issue (TN8)
	10/12/01	V.3.03 Release00	V4.07.01	V.3.00.01							December 01, 2010 issue (TN3)
	10/04/01	V.3.02 Release01							V.3.1.0.0		April 01, 2010 issue (TN4)
	-	V.3.02 Release00	V4.07.00								-
	10/01/20	V.3.01 Release00		V.3.00.00	V.2.1.00.000	V2.00					-
	09/11/01	V.3.00 Release01	V4.05.01								November 01, 2009 issue (TN2)
	09/07/17	V.3.00 Release00					V.3.0.0.0				July 17, 2009 issue (TN1)
	09/02/16	V.2.14 Release01		V.2.11.00			10.0.0.0				February 16, 2009 issue (TN4)
	08/12/16	V.2.14 Release00									December 16, 2008 issue (TN2) (Target devices added.)
	08/09/01	V.2.13 Release00	V.4.04.01	V.2.10.00	-						September 01, 2008 issue (TN6) (Target devices added.)
	08/05/16	V.2.12 Release00		V.2.09.00					V.3.0.0.0		May 16, 2008 issue (TN2)
	08/03/01	V.2.11 Release00									March 01, 2008 issue (TN3) (Target devices added.)
	07/12/16	V.2.10 Release01		V.2.08.00							December 16, 2007 issue (TN8)
	07/11/06	V.2.10 Release00	V.4.03.00							V2.0.0.5	November 06, 2007 issue (TN1) (Target devices added.)
	07/08/16	V.2.09 Release00		V.2.07.00	V.2.0.00.000						August 16, 2007 issue (TN1) (Target devices added.)
	07/06/01	V.2.08 Release01	V.4.02.00	V.2.06.00			\/1 40			June 01, 2007 issue (TN5)	
	07/04/24	V.2.08 Release00						V1.18			April 24, 2007 issue (TN1)
	06/12/01	V.2.07 Release00	V.4.01.01	V.2.05.00		/ 2 ページ					December 01, 2006 issue (TN5)

06/08/01	V.2.06 Release00		V.2.04.00	V1.4.00.000	V1.00		V2.2.0.0	August 01, 2006 issue (TN8) (Target devices added.)
06/07/01	V.2.05 Release00	V.4.00.03	V.2.03.00		V1.00	V2.1.0.0		July 01, 2006 issue (TN4)
06/05/16	V.2.04 Release00	1.4.00.00	V.2.00.00					May 16, 2006 issue (TN4) (Target devices added.)
06/02/16	V.2.03 Release00		V.2.02.00	V1.3.00.000				February 16, 2006 issue (TN1) (Target devices added.)
05/12/01	V.2.02 Release00	V.4.00.02	V.2.01.00	V1.1.00.000			V2.0.1.0	December 01, 2005 issue (TN2)
05/10/16	V.2.01 Release00	1.4.00.02	V.2.01.00	1.1.00.000			V2.0.1.C	October 16, 2005 issue (TN3) (Target devices added.)
_	V.2.00 Release04							-
05/08/01	V.2.00 Release03							August 01, 2005 issue (TN6)
_	V.2.00 Release 02	V.4.00.01	V.2.00.00			V2.0.0.0	V2.0.0.0	
05/06/01	V.2.00 Release01			V1.0.00				June 01, 2005 issue (TN4)
05/05/16	V.2.00 Release 00							June 01, 2005 issue (TN4)
05/03/16	V.1.11 Release 01	V.3.01.08	V.1.00.00			V1.2.0.0	V1.3.1.0	March 16, 2005 issue (TN2)
05/03/01	V.1.11 Release 00	1.0.01.00				V1.2.0.0	V 1.0.1.C	, March 01, 2005 issue (TN3)

*: When a High-performance Embedded Workshop with the latest version has already been installed by other

products, that one is adopted. Upgrading High-performance Embedded Workshop individually is available on the download site. **: Be sure to install the E10A-USB emulator software before performing an E10A-USB self-diagnosing test.program. This program is available on the download site.

When upgrading E10A-USB emulator software on this page, the previous versions of software has to have been installed in your PC before, or the previous versions of the set-up disc has to have been in a CD drive on your PC.

Before installation of the E10A-USB emylator software, a confirmation dialog box which asks places of the previous one or the setup disc may be displayed.

The update program expands a set-up program under a temporaly directory in Windows® to perform an upgrade. Files expanded under the folder is deleted automatically.

Therefore, Be sure to back up files you need before an execution of the update program.

E10A-USB Emulator Software Component List for H8S device group

		E10A-USB	Main Com	ponents	Firmware for H8S Group	Device	E10AUSB		USB	driver		
Status	Released date	Emulator Software	High- performance Embedded Workshop	H8S	H8S/2339EF H8S H8S/2329EF H8S/2319EF	H8S_2427, H8S_2425 Device Group	Self- diagnosing program	E1usb .sys	HMSEUsb .sys	E1usbdrv .dll	usbdrv .dll	Related <u>Tool News</u>
Latest version	13/06/16	V.3.06 Release00	V4.09.01 *	V.3.04.00		V.2.2.00.000		V.4.0.0.1		V.3.1.2.0		June 16, 2013 issue (TN8) (Target devices added.)
	12/10/01	V.3.05 Release00		V.3.03.01					V1.18 (32bit)	***		October 01, 2012 issue (TN4)
	12/02/16	V.3.04 Release01	V4.09.00	V.3.03.00		V.2.1.00.000	V2.01 **		V1.19 (64bit)			February 16, 2012 issue (TN10)
	11/11/16	V.3.04 Release00	V4.03.00	v.3.03.00		v.z.1.00.000						November 16, 2011 issue (TN8)
	10/12/01	V.3.03 Release00	V4.07.01	V.3.02.00								December 01, 2010 issue (TN3) (Target devices added.)
	10/04/01	V.3.02 Release01		V.3.01.00						V.3.1.0.0		April 01, 2010 issue (TN4)
	-	V.3.02 Release00	V4.07.00							***		- (Target devices added.)
	10/01/20	V.3.01 Release00					V2.00					-
	09/11/01	V.3.00 Release01	V4.05.01	V.3.00.00								November 01, 2009 issue (TN2)
	09/07/17	V.3.00 Release00			2.0.00.000			V.3.0.0.0				July 17, 2009 issue (TN1) (Target devices added.)
	09/02/16	V.2.14 Release01		V.2.11.00								February 16, 2009 issue (TN4)
	08/12/16	V.2.14 Release00		V.2.10.00								December 16, 2008 issue (TN2) (Target devices added.)
	08/09/01	V.2.13 Release00	V.4.04.01	V.2.09.00								September 01, 2008 issue (TN6)
	08/05/16	V.2.12 Release00		1.2.00.00						V.3.0.0.0		May 16, 2008 issue (TN2) (Target devices added.)
	08/03/01	V.2.11 Release00		V.2.08.00								March 01, 2008 issue (TN3) (Target devices added.)
	07/12/16	V.2.10 Release01		V.2.07.00								December 16, 2007 issue (TN8)
	07/11/06	V.2.10 Release00	V.4.03.00									November 06, 2007 issue (TN1) (Target devices added.)
	07/08/16	V.2.09 Release00		V.2.06.00								August 16, 2007 issue (TN1) (Target devices added.)
	07/06/01	V.2.08 Release01	V.4.02.00	V.2.05.00								June 01, 2007 issue (TN5)
	07/04/24	V.2.08 Release00		V.2.05.00								April 24, 2007 issue (TN1) (Target devices added.)
	06/12/01	V.2.07 Release00	V.4.01.01	V.2.04.00								December 01, 2006 issue (TN5)

06/08/01	V.2.06 Release00									V2.2.0.0	V2.0.0.5	August 01, 2006 issue (TN8)
06/07/01	V.2.05 Release00	V 4 00 02	V.2.03.00	V1.4	.00.002			V2.1.0.0			V2.0.0.3	July 01, 2006 issue (TN4)
06/05/16	V.2.04 Release00	V.4.00.03										May 16, 2006 issue (TN4)
06/02/16	V.2.03 Release00		V.2.02.00			-			V1.18			February 16, 2006 issue (TN1) (Target devices added.)
05/12/01	V.2.02 Release00	V/ A 00 00	V.2.01.01		00.000							December 01, 2005 issue (TN2)
05/10/16	V.2.01 Release00	V.4.00.02	V.2.01.00	V 1.3	.00.002		V1.00			V2.0.1.0		October 16, 2005 issue (TN3) (Target devices added.)
_	V.2.00 Release04						V1.00					-
05/08/01	V.2.00 Release03											August 01, 2005 issue (TN6)
_	V.2.00 Release 02	V.4.00.01	V.2.00.00					V2.0.0.0		V2.0.0.0		-
05/06/01	V.2.00 Release01											June 01, 2005 issue (TN4)
05/05/16	V.2.00 Release 00			V1	.2.00							June 01, 2005 issue (TN4)
05/03/16	V.1.11 Release 01											March 16, 2005 issue (TN2)
05/03/01	V.1.11 Release 00	V.3.01.08	V.1.06.01									March 01, 2005 issue (TN3)
_	V.1.10 Release 00											-
04/12/07	V.1.09 Release 00	V.3.01.06	V.1.06.00							V1.3.1.0		- (Target devices added.)
04/10/14	V.1.08 Releas 00	1.0.01.00	V.1.05.01		V.1.1.00					V1.5.1.0		-
04/09/09	V.1.07 Release 00	V.3.01.04	V.1.05.00					V1.2.0.0				- (Target devices added.)
04/08/06	V.1.06 Release 00	1.0.01.01	V.1.04.00					1.2.0.0				- (Target devices added.)
04/06/11	V1.5.00	V3.0.06	V1.3.00	V1.0.00								- (Target devices added.)
04/04/20	V1.4.01/ 1.4.02		V1.2.00		_					V1.3.0.0		- (Target devices added.)
04/04/14	V1.4.00	V3.0.05	V1.1.00	/1.1.00								-
04/03/08	V1.3.00									V1.2.0.0		- (Target devices added.)
04/01/30	V1.2.00		V1.0.00									-

- : When a High-performance Embedded Workshop with the latest version has already been installed by other
- : When a High-performance Embedded Workshop with the latest version has already been installed by other products, that one is adopted. Upgrading High-performance Embedded Workshop individually is available on the download site. : Be sure to install the E10A-USB emulator software before performing an E10A-USB self-diagnosing test.program. This program ** is available on the download site.
- ***: When using H8S/2437, H8S/2114, H8S/2172, H8S/2158, H8S/2189R, H8S/2116, or H8S/2125, the software version is V3.0.0.0.

When upgrading E10A-USB emulator software on this page, the previous versions of software has to have been installed in your PC before, or the previous versions of the set-up disc has to have been in a CD drive on your PC. Before installation of the E10A-USB emylator software, a confirmation dialog box which asks places of the previous one or the setup

disc may be displayed. The update program expands a set-up program under a temporaly directory in Windows® to perform an upgrade. Files expanded under the folder is deleted automatically.

Therefore, Be sure to back up files you need before an execution of the update program.

E10A-USB Emulator Software Component List for SH-2 device group

				Mai	n Components				E10AUSB		USB	driver		Juli 20, 2013
Status	Release d date	E10A-USB Emulator Software	High- performance Embedded Workshop	SH-2	SH2-DSP	SH7618	SH7080 Series	Firmware for SH-2 Device Group	Self- diagnosing program	E1usb .sys			usbdrv .dll	Related <u>Tool News</u>
Latest version	13/06/16	V.3.06 Release00	V.4.09.01 *		V.3.03	2.01				V.4.0.0.1		V3.1.2.0		June 16, 2013 issue (TN8)
	12/10/01	V.3.05 Release00	. 9.4.09.01		V.3.00	5.01				V.4.0.0.1	V1.18 (32bit)	***		October 01, 2012 issue (TN4)
	12/02/16	V.3.04 Release01	· V.4.09.00		V.3.03	3.00			V2.01 **		V1.19 (64bit)			February 16, 2012 issue (TN10)
	11/11/16	V.3.04 Release00	1.00.00		1.0.00							V3.1.1.1 ***		November 16, 2011 issue (TN8)
	10/12/01	V.3.03 Release00	V.4.07.01		V.3.02.00			-				December 01, 2010 issue (TN3)		
	10/04/01	V.3.02 Release01			V.3.01	V.3.01.01							April 01, 2010 issue (TN4)	
	-	V.3.02 Release00	V.4.07.00					_						-
	10/01/20	V.3.01 Release00			V.3.01	1.00		_	V2.00			V3.1.0.0 ***		January 20, 2010 issue (TN1) (Target devices added.)
	09/11/01	V.3.00 Release01	1 V.3.00.01						November 01, 2009 issue (TN2)					
	09/07/17	V.3.00 Release00			V.3.00	0.00		V.2.0.00.000		V.3.0.0.0				July 17, 2009 issue (TN1)
	09/02/16	V.2.14 Release01												February 16, 2009 issue (TN4)
	08/12/16	V.2.14 Release00			V.2.11	1.00								December 16, 2008 issue (TN2)
	08/09/01	V.2.13 Release00	V.4.04.01											September 01, 2008 issue (TN6)
	08/05/16	V.2.12 Release00						-				V.3.0.0.0		May 16, 2008 issue (TN2)
	08/03/01	V.2.11 Release00			V.2.10).00		_						March 01, 2008 issue (TN3) (Target devices added.)
	07/12/16	V.2.10 Release01			V.2.09	9.00								December 16, 2007 issue (TN8)
	07/11/06	V.2.10 Release00	V.4.03.00											November 06, 2007 issue (TN1) (Target devices added.)
	07/08/16	V.2.09 Release00			V.2.08	3.00		-						August 16, 2007 issue (TN1) (Target devices added.)
	07/06/01	V.2.08 Release01	V.4.02.00	0 V.2.07.00								June 01, 2007 issue (TN5)		
	07/04/24	V.2.08 Release00											April 24, 2007 issue (TN1)	
	06/12/01	V.2.07 Release00	V.4.01.01		V.2.06	5.00								December 01, 2006 issue (TN5)

·		-	1				. .		1	1		
06/08	8/01 V.2.06 Release0	0		V.2.0	5.00					V1.18	V.2.2.0.0	August 01, 2006 issue (TN8) (Target devices added.)
06/07	7/01 V.2.05 Release0			V.2.04	4.00		∨.1.5.00.000		V2.1.0.0	V1.10		July 01, 2006 issue (TN4) (Target devices added.)
06/05	5/16 V.2.04 Release0	V.4.00.03		V.2.03	3.00							May 16, 2006 issue (TN4)
06/02	2/16 V.2.03 Release0	0		V.2.02	2.00							February 16, 2006 issue (TN1) (Target devices added.)
05/12	2/01 V.2.02 Release0							V1.00				December 01, 2005 issue (TN2)
05/10	0/16 V.2.01 Release0	V.4.00.02		V.2.01.00		-	V.1.4.00.000				V2.0.1.0	October 16, 2005 issue (TN3) (Target devices added.)
-	- V.2.00 Release0	4										-
05/08	8/01 V.2.00 Release0	3										August 01, 2005 issue (TN6)
-	V.2.00 Release 0	2 V.4.00.01		V.2.00.00		-			V2.0.0.0		V2.0.0.0	-
05/06	6/01 V.2.00 Release0	1										June 01, 2005 issue (TN4)
05/05	5/16 V.2.00 Release 0	0					V1.3.00					June 01, 2005 issue (TN4)
05/03	3/16 V.1.11 Release 0	1										March 16, 2005 issue (TN2)
05/03	3/01 V.1.11 Release 0	0 V.3.01.08	V.1.00.00r2	V.1.0.000r3	V.1.01.00	-						March 01, 2005 issue (TN3)
	V.1.10 Release 0	0										- (Target devices added.)
04/12	2/07 V.1.09 Release 0						V/4 0 00					-
04/10	0/14 V.1.08 Releas 00	V.3.01.06	3.01.06 V.1.00.00r1 V	V.1.0.00r2	V.1.00.00	-	V1.2.00		V1.2.0.0		V1.3.1.0	- (Target devices added.)
04/09	9/09 V.1.07 Release 0											-
04/08	8/06 V.1.06 Release 0	V.3.01.04	V.1.00.00	V.1.0.00r1	-	-	V1.1.00					- (Target devices added.)
04/06	6/11 V1.5.00	V3.0.06	-	V1.0.00	-	-	V1.0.00					-

- * : When a High-performance Embedded Workshop with the latest version has already been installed by other products, that one is adopted. Upgrading High-performance Embedded Workshop individually is available on the download site.
- ** : Be sure to install the E10A-USB emulator software before performing an E10A-USB self-diagnosing test.program. This program is available on the download site.

***: When using SH7615, SH7616, SH7047F, SH7144F, SH7145F, SH7618, SH7619, SH7606, or SH7618A; the software version is V3.0.0.0.

When upgrading E10A-USB emulator software on this page, the previous versions of software has to have been installed in your PC before, or the previous versions of the set-up disc has to have been in a CD drive on your PC.

Before installation of the E10A-USB emylator software, a confirmation dialog box which asks places of the previous one or the setup disc may be displayed.

The update program expands a set-up program under a temporaly directory in Windows® to perform an upgrade. Files expanded under the folder is deleted automatically.

Therefore, Be sure to back up files you need before an execution of the update program.

E10A-USB Emulator Software Component List for SH-3 device group

				n Components		E10AUSB		USB	driver		
Status	Release d date	E10A-USB Emulator Software	High- performance Embedded Workshop	SH- 3(Core) SH-3	Firmware for SH-3 Device Group	Self- diagnosing program	E1usb.sys	HMSEUsb .sys	E1usbdrv .dll	usbdrv .dll	Related <u>Tool News</u>
Latest version	13/06/16	V.3.06 Release00	V.4.09.01 *								June 16, 2013 issue (TN8)
	12/10/01	V.3.05 Release00	1.1.00.01								October 01, 2012 issue (TN4)
	12/02/16	V.3.04 Release01	• V.4.09.00	V.2.07.04		V2.01 **					February 16, 2012 issue (TN10)
	11/11/16	V.3.04 Release00	1.4.09.00								November 16, 2011 issue (TN8)
	10/12/01	V.3.03 Release00	V.4.07.01								December 01, 2010 issue (TN3)
	10/04/01	V.3.02 Release01		V.2.07.03							April 01, 2010 issue (TN4)
	-	V.3.02 Release00	V.4.07.00	0.2.07.00							-
	10/01/20	V.3.01 Release00		V.2.07.02		V2.00					January 20, 2010 issue (TN1)
	09/11/01	V.3.00 Release01	· V.4.05.01	V.2.07.01			V.3.0.0.0		V.3.0.0.0		November 01, 2009 issue (TN2)
	09/07/17	V.3.00 Release00	1.4.00.01	0.2.07.01	V2.0.00.000						July 17, 2009 issue (TN1)
	09/02/16	V.2.14 Release01									February 16, 2009 issue (TN4)
	08/12/16	V.2.14 Release00									December 16, 2008 issue (TN2)
	08/09/01	V.2.13 Release00	V.4.04.01								September 01, 2008 issue (TN6)
	08/05/16	V.2.12 Release00		V.2.07.00							May 16, 2008 issue (TN2)
	08/03/01	V.2.11 Release00									March 01, 2008 issue (TN3)
	07/12/16	V.2.10 Release01									December 16, 2007 issue (TN8)



06/08/01	V.2.06 Release00		V.2.0	04.00					V2.2.0.0		August 01, 2006 issue (TN8)
06/07/01	V.2.05 Release00						V2.1.0.0	V1.18		V2.0.0.5	July 01, 2006 issue (TN4)
06/05/16	V.2.04 Release00	V.4.00.03	V.2.(03.00	V.1.3.00.000						May 16, 2006 issue (TN4)
06/02/16	V.2.03 Release00		V.2.(02.00							February 16, 2006 issue (TN1)
05/12/01	V.2.02 Release00	V.4.00.02	V.2.0	01.01					V2.0.1.0		December 01, 2005 issue (TN2)
05/10/16	V.2.01 Release00	V.4.00.02	V.2.0	01.00					V2.0.1.0		October 16, 2005 issue (TN3)
_	V.2.00 Release04					V1.00					-
05/08/01	V.2.00 Release03										August 01, 2005 issue (TN6)
_	V.2.00 Release 02	V.4.00.01	V.2.0	00.00			V2.0.0.0		V2.0.0.0		-
05/06/01	V.2.00 Release01				V/1 2 00						June 01, 2005 issue (TN4)
05/05/16	V.2.00 Release 00				V1.2.00						June 01, 2005 issue (TN4)
05/03/16	V.1.11 Release 01										March 16, 2005 issue (TN2)
05/03/01	V.1.11 Release 00	V.3.01.08	V.1.06.00	V1.2.00r1							March 01, 2005 issue (TN3)
_	V.1.10 Release 00										-
04/12/07	V.1.09 Release	N 0.01.00	V.1.05.00								- (Target devices added.)
04/10/14	V.1.08 Release 00	V.3.01.06	V.1.04.00						V1.3.1.0		-
04/09/09	V.1.07 Release 00	N 2 01 01		V1.2.00							-
04/08/06	V.1.06 Release 00	V.3.01.04	V1.3.00				V1.2.0.0				-
04/06/11	V1.5.00	V3.0.06			V1.1.00						-
04/04/20	V1.4.01/ 1.4.02		V1.2.00r1	V1.1.00r1							-
04/04/14	V1.4.00								V1.3.0.0		-
04/03/08	V1.3.00	V3.0.05	V1.2.00	V1.1.00							-
04/01/30	V1.2.00		V1.1.00 V	V1.0.00		ページ			V1.2.0.0		- (Target devices added.)

	_	V1.1.00	V3.0.01	V1.0.00	-	V1.0.00		V1.1.0.0	-

```
Notes:
```

* : When a High-performance Embedded Workshop with the latest version has already been installed by other

products, that one is adopted. Upgrading High-performance Embedded Workshop individually is available on the download site. **: Be sure to install the E10A-USB emulator software before performing an E10A-USB self-diagnosing test.program. This program is available on the download site.

When upgrading E10A-USB emulator software on this page, the previous versions of software has to have been installed in your PC before, or the previous versions of the set-up disc has to have been in a CD drive on your PC.

Before installation of the E10A-USB emylator software, a confirmation dialog box which asks places of the previous one or the setup disc may be displayed.

The update program expands a set-up program under a temporaly directory in Windows® to perform an upgrade. Files expanded under the folder is deleted automatically.

Therefore, Be sure to back up files you need before an execution of the update program.

E10A-USB Emulator Software Component List for SH-Mobile device group

	Del	E10A-USB	Main Corr High-	nponents	Firmware for	E10AUSB		USB	driver		
Status	Release d date	Emulator Software	erformance Embedded Workshop	SH-Mobile	SH-Mobile Device Group	Self-diagnosing program	E1usb .sys	HMSEUsb .sys	E1usbdrv .dll	usbdrv .dll	Related <u>Tool News</u>
Latest version	13/06/16	V.3.06 Release00	V.4.09.01 *								June 16, 2013 issue (TN
	12/10/01	V.3.05 Release00									October 01, 2012 issu (TN4)
	12/02/16	V.3.04 Release01	V.4.09.00	V.2.07.02		V2.01 **					February 16, 2012 issu (TN10)
	11/11/16	V.3.04 Release00	v.4.09.00								November 16, 2011 iss (TN8)
	10/12/01	V.3.03 Release00	V.4.07.01								December 01, 2010 iss (TN3)
	10/04/01	V.3.02 Release01			1						April 01, 2010 issue (TN
	-	V.3.02 Release00	V.4.07.00								-
	10/01/20	V.3.01 Release00		V.2.07.01		V2.00					January 20, 2010 issu (TN1)
	09/11/01	V.3.00 Release01	V.4.05.01				V.3.0.0.0		V.3.0.0.0		November 01, 2009 iss (TN2)
	09/07/17	V.3.00 Release00			2.0.00.000						July 17, 2009 issue (TN
	09/02/16	V.2.14 Release01									February 16, 2009 issu (TN4)
	08/12/16	V.2.14 Release00									December 16, 2008 iss (TN2)
	08/09/01	V.2.13 Release00	V.4.04.01								September 01, 2008 iss (TN6)
	08/05/16	V.2.12 Release00		V.2.07.00							May 16, 2008 issue (TN
	08/03/01	V.2.11 Release00									March 01, 2008 issue (TN3)
	07/12/16	V.2.10 Release01									December 16, 2007 iss (TN8)
	07/11/06	V.2.10 Release00	V.4.03.00								November 06, 2007 iss (TN1)
	07/08/16	V.2.09 Release00		V.2.06.01	.2.06.01						August 16, 2007 issu (TN1)
	07/06/01	V.2.08 Release01							June 01, 2007 issue (TI		
	07/04/24	V.2.08 Release00	v. 4 .02.00	v.2.00.00							April 24, 2007 issue (TI
	06/12/01	V.2.07 Release00	V.4.01.01	V.2.05.00							December 01, 2006 iss (TN5) (Target devices addec

06/08/01	V.2.06 Release00		V.2.04.00					V2.2.0.0		August 01, 2006 issue
06/07/01	V.2.05					V2.1.0.0	V1.18			(TN8) July 01, 2006 issue (TN4)
	Release00 V.2.04	V.4.00.03	V.2.03.00						V2.0.0.5	
06/05/16	Release00 V.2.03			V.1.4.00.000						May 16, 2006 issue (TN4) February 16, 2006 issue
06/02/16	Release00		V.2.02.00							(TN1) (Target devices added.)
05/12/01	V.2.02 Release00	V.4.00.02	V.2.01.00					V2.0.1.0		December 01, 2005 issue (TN2)
05/10/16	V.2.01 Release00	1.1.00.02	1.2.01.00					V2.0.1.0		October 16, 2005 issue (TN3)
_	V.2.00 Release04									-
05/08/01	V.2.00 Release 03				V1.00					August 01, 2005 issue (TN6)
_	V.2.00 Release 02	V.4.00.01	V.2.00.00			V2.0.0.0		V2.0.0.0		
05/06/01	V.2.00 Release01									June 01, 2005 issue (TN4
05/05/16	V.2.00 Release 00			V1.3.00						June 01, 2005 issue (TN4 (Target devices added.)
05/03/16	V.1.11 Release 01									March 16, 2005 issue (TN2)
05/03/01	V.1.11 Release 00	V.3.01.08	V.1.07.00							March 01, 2005 issue (TN3)
_	V.1.10 Release 00									- (Target devices added.)
04/12/07	V.1.09 Release 00		V.1.06.00							- (Target devices added.)
04/10/14	V.1.08 Release 00	V.3.01.06	V.1.05.00					V1.3.1.0		- (Target devices added.)
04/09/09	V.1.07 Release 00									-
04/08/06	V.1.06 Release 00	V.3.01.04	V1.4.00			V1.2.0.0				-
04/06/11	V1.5.00	V3.0.06		V1.2.00						-
04/04/20	V1.4.01/ 1.4.02		V1.3.00r1							
04/04/14	V1.4.00							V1.3.0.0		-
 04/03/08	V1.3.00	V3.0.05	V1.3.00							- (Target devices added.)
04/01/30	V1.2.00		V1.2.00					V1.2.0.0		-

_	V1.1.00	V3.0.01	V1.1.00	V1.1.00			V1.1.0.0	- (Target devices added.)
_	V1.0.00	V3.0.01	V1.0.00	V1.0.00	V1.1.0.0	V1.05	V1.1.0.0	-

* : When a High-performance Embedded Workshop with the latest version has already been installed by other

products, that one is adopted. Upgrading High-performance Embedded Workshop individually is available on the download site. **: Be sure to install the E10A-USB emulator software before performing an E10A-USB self-diagnosing test.program. This program is available on the download site.

When upgrading E10A-USB emulator software on this page, the previous versions of software has to have been installed in your PC before, or the previous versions of the set-up disc has to have been in a CD drive on your PC.

Before installation of the E10A-USB emylator software, a confirmation dialog box which asks places of the previous one or the setup disc may be displayed.

The update program expands a set-up program under a temporaly directory in Windows® to perform an upgrade. Files expanded under the folder is deleted automatically.

Therefore, Be sure to back up files you need before an execution of the update program.

E10A-USB Emulator Software Component List for SH-4 device group

	E10A USB driver										
Status	Release d date	E10A-USB Emulator Software	High- performance Embedded Workshop	SH-4 SH7750	Firmware for SH-4 Device Group	Self- diagnosing program	E1usb .sys	HMSEUsb .sys	E1usbdrv .dll	usbdrv .dll	Related <u>Tool News</u>
Latest version	13/06/16	V.3.06 Release00	V.4.09.01 *								June 16, 2013 issue (TN8)
	12/10/01	V.3.05 Release00				V.2.01 **					October 01, 2012 issue (TN4)
	12/02/16	V.3.04 Release01	V.4.09.00	V.2.05.02							February 16, 2012 issue (TN10)
	11/11/16	V.3.04 Release00	V. 1 .00.00								November 16, 2011 issue (TN8)
	10/12/01	V.3.03 Release00	V.4.07.01								December 01, 2010 issue (TN3)
	10/04/05	V.3.02 Release01									April 01, 2010 issue (TN4)
	-	V.3.02 Release00	V.4.07.00								-
	10/01/20	V.3.01 Release00		V.2.05.01		V.2.00					January 20, 2010 issue (TN1)
	09/11/01	V.3.00 Release01	V.4.05.01				V.3.0.0.0		V.3.0.0.0		November 01, 2009 issue (TN2)
	09/07/17	V.3.00 Release00			V.2.0.00.000						July 17, 2009 issue (TN1)
	09/02/16	V.2.14 Release01									February 16, 2009 issue (TN4)
	08/12/16	V.2.14 Release00									December 16, 2008 issue (TN2)
	08/09/01	V.2.13 Release00	V.4.04.01								September 01, 2008 issue (TN6)
	08/05/16	V.2.12 Release00		V.2.05.00							May 16, 2008 issue (TN2)
	08/03/01	V.2.11 Release00									March 01, 2008 issue (TN3)
	07/12/16	V.2.10 Release01									December 16, 2007 issue (TN8)
	07/11/06	V.2.10 Release00	V.4.03.00								November 06, 2007 issue (TN1)
	07/08/16	V.2.09 Release00		V.2.04.01						August 16, 2007 issue (TN1)	

]			ľ		I	
0 0 V2.08 V2.08 V4.010 V2.020 0 V2.020 0<	07/06/0		V.4.02.00	V.2.0	04.00							June 01, 2007 issue (TN5)
 00(120) v.2.05 00000	07/04/2											April 24, 2007 issue (TN1)
Course Relationship V2.05 (P1.000) Relationship V2.02.00 (P1.000) V2.05 (V2.02.00) V2.05 (V2.02.00) V2.05 (V2.02.00) V2.05 (V2.02.00) V2.05 (V2.01.00) V2.05 (V2.00.00) V2	06/12/0		V.4.01.01	V.2.0)3.00							(TN5)
$ \begin{array}{ c c c c } \hline odd/N Release 0 Value 0 Va$	06/08/0								V1.18	V2.2.0.0	V2.0.0.5	August 01, 2006 issue (TN8)
060641	06/07/0		V 4 00 02	V.2.(02.00			V2.1.0.0				July 01, 2006 issue (TN4)
0 0000 0 Release00 (111)	06/05/1		· v.4.00.03			V.1.2.00.000						May 16, 2006 issue (TN4)
0/12/01 Release00 ∨4.00.02 ∨4.00.02 ∨4.00.02 ∨1.00 ∨2.01 ∨2.01 √2.01 ○Ccluber 16, 2005 issue (TN3) 0 - V2.00 V2.00 ×4.00.02	06/02/1										-	
051016 $Verture 0.0000$ $Verture 0.00000$ $Verture 0.00000000000000000000000000000000000$	05/12/0		V 4 00 02	V.2.0 ⁴	01.00					V2 0 1 0		
Image: Construction of the selence	05/10/1		vt.00.0Z				V1.00			•2.0.1.0		October 16, 2005 issue (TN3)
0.00001 Release03 V.4.00.01 V.2.00.00 V.2.00.00 V.2.00.00 V.2.00.00 V.2.00.00 V.2.00.00 V.2.00.00 June 01. 2005 issue (TN4) 0.5/06/07 Release00 V.2.00 V.1.100 V.1.00 V.1.00 June 01. 2005 issue (TN4) 0.5/05/16 Release00 V.1.01 V.1.00 V.1.00 March 16, 2005 issue (TN4) 0.5/03/16 Release00 V.1.11 V.1.03.00 V1.03.00 V1.03.00 0.5/03/16 Release00 V.3.01.08 V1.03.00 V1.03.00 V1.03.00 0.5/03/07 Release00 V.3.01.08 V1.03.00 V1.03.00 V1.03.00 V1.03.00 0.6/172/07 Release00 V.3.01.08 V1.2.00 V1.2.00 V1.3.10 March 16, 2005 issue (TN4) 0.6/172/07 Release00 V.3.01.06 V1.3.00 V1.2.00 V1.3.10 V1.3.10 Image: Comparison of Comparison	_										-	
- Release 02 V4.00.01 V2.00.00 V2.0	05/08/0											August 01, 2005 issue (TN6)
05/06/0 Release 01 V1.100 V1.100 V1.100 June 01, 2005 issue (1N4) 05/05/16 V2.00 Release 00 V.1.01 Release 01 V.1.00 V1.100 June 01, 2005 issue (TN4) 05/03/16 V.1.11 Release 01 V.3.01.08 V1.03.00 V1.03.00<	_		V.4.00.01	V.2.0	00.00	V1 1 00		V2.0.0.0		V2.0.0.0		-
05/05/16 V.2.00 Release 00 V.2.00 Release 01 June 01, 2005 issue (TN4) 05/03/16 V.1.11 Release 01 V.3.01.08 V1.03.00 V1.03.0	05/06/0	1 V.2.00 Release01										June 01, 2005 issue (TN4)
03/03/10 Release 01 V.1.01 V.3.01.08 V1.03.00 V1.03.00 <t< td=""><td>05/05/1</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>June 01, 2005 issue (TN4)</td></t<>	05/05/1											June 01, 2005 issue (TN4)
03/03/01 Release 00 V.0.010 V1.000 V1.000 (TN3) - V.1.10 V.1.00 V.1.00 - - 04/12/07 V.1.09 V.0.0106 V.3.01.06 V.3.01.06 V1.2.00 V1.3.1.0 04/10/14 V.1.08 V.1.07 V.1.07 V1.2.00 V1.2.00 V1.2.00 04/08/06 V.1.06 V.1.06 V1.2.00 V1.2.00 V1.2.00 V1.2.00 04/08/06 V.1.06 V.1.06 V1.2.00 V1.2.00 V1.2.00 V1.2.00	05/03/1	6 V.1.11 Release 01										
Image: Constraint of the lease 00 Image:	05/03/0		V.3.01.08	V1.03.00	V1.03.00							March 01, 2005 issue (TN3)
04/12/07 Release 00 V.3.01.06 04/10/14 V.1.08 V.1.08 Release 00 V.1.07 04/09/09 V.1.07 V.3.01.04 V1.2.00 V1.2.00 V1.2.00 V1.2.00 V1.2.00 V1.2.00 V1.2.00 V1.2.00 V1.2.00	_											-
04/10/14 V.1.08 V.1.08 V.1.07 V.1.07 V.1.07 V.1.00 V.1.2.00 V1.2.00	04/12/0		V 3 01 06							V1310		-
04/09/09 Release 00 V1.2.00	04/10/1		0.0.01.00							• 1.0.1.0		-
04/08/06 V.1.06 Release 00 V1.0.00 -	04/09/0	9 V.1.07 Release 00	V 3 01 04	V1.2.00	V1.2.00			V1.2.0.0				-
	04/08/0		v.3.01.04			V1 0 00						-
	04/06/1	1 V1.5.00	V3.0.06			v 1.0.00						-

04/04/20	V1.4.01/ 1.4.02	V3.0.05	V1.1.00r1	V1.1.00r1		V1.3.0.0		-
04/04/14	V1.4.00		V1.2.00	V1.1.00				-
04/03/08	V1.3.00		V1.0.00	V1.0.00		V1.2.0.0		-

* : When a High-performance Embedded Workshop with the latest version has already been installed by other

products, that one is adopted. Upgrading High-performance Embedded Workshop individually is available on the download site. **: Be sure to install the E10A-USB emulator software before performing an E10A-USB self-diagnosing test program. This program is available on the download site.

When upgrading E10A-USB emulator software on this page, the previous versions of software has to have been installed in your

PC before, or the previous versions of the set-up disc has to have been in a CD drive on your PC.

Before installation of the E10A-USB emylator software, a confirmation dialog box which asks places of the previous one or the setup disc may be displayed.

The update program expands a set-up program under a temporally directory in Windows® to perform an upgrade. Files expanded under the folder is deleted automatically.

Therefore, Be sure to back up files you need before an execution of the update program.

E10A-USB Emulator Software Component List for New SH-Mobile device group

Jun 20, 2013

		E10A-USB	Main Com	ponents	Firmware for	E10AUSB	USB driver				
Status	Release d date	Emulator Software	High- performance Embedded Workshop	New_SH- Mobile	New_SH- Mobile Device Group	Self- diagnosing program	E1usb .sys	HMSEUsb .sys	E1usbdrv .dll	usbdrv .dll	Related <u>Tool News</u>
Latest version	13/06/16	V.3.06 Release00	V.4.09.01 *	V.3.04.00			V.4.0.0.1		V3.1.2.0		June 16, 2013 issue (TN8)
	12/10/01	V.3.05 Release00		1.0.0 1.00				V1.18 (32bit)	V0.112.0		October 01, 2012 issue (TN4)
	12/02/16	V.3.04 Release01	· V.4.09.00	V.3.03.00		V2.01 **		V1.19 (64bit)			February 16, 2012 issue (TN10)
	11/11/16	V.3.04 Release00	V.4.09.00	V.3.03.00	V.2.2.00.000				V3.1.1.1		November 16, 2011 issue (TN8)
	10/12/01	V.3.03 Release00	V.4.07.01	V.3.02.00							December 01, 2010 issue (TN3)
	10/04/01	V.3.02 Release01		V.3.01.02							April 01, 2010 issue (TN4)
	-	V.3.02 Release00	V.4.07.00	V.3.01.01							-
	10/01/20	V.3.01 Release00		V.3.01.00		V2.00			V3.1.0.0		January 20, 2010 issue (TN1)
	09/11/01	V.3.00 Release01	• V.4.05.1	V.3.00.00							November 01, 2009 issue (TN2)
	09/07/17	V.3.00 Release00	V. 4 .00.1				• V.3.0.0.0				July 17, 2009 issue (TN1)
	09/02/16	V.2.14 Release01		V.2.12.00							February 16, 2009 issue (TN4)
	08/12/16	V.2.14 Release00			V.2.1.01.000						December 16, 2008 issue (TN2)
	08/09/01	V.2.13 Release00	V.4.04.01	V.2.11.01							September 01, 2008 issue (TN6)
	08/05/16	V.2.12 Release00		V.2.11.00					V.3.0.0.0		May 16, 2008 issue (TN2)
	08/03/01	V.2.11 Release00		V.2.10.00							March 01, 2008 issue (TN3) (Target devices added.)
	07/12/16	V.2.10 Release01		V.2.09.01							December 16, 2007 issue (TN8)
	07/11/06	V.2.10 Release00	V.4.03.00	V.2.09.00	V.2.1.00.000						November 06, 2007 issue (TN1)
	07/08/16	V.2.09 Release00		V.2.08.00							August 16, 2007 issue (TN1) (Target devices added.)
	07/06/01	V.2.08 Release01	V.4 02 00	V.2.07.00	V.2.0.00.000						June 01, 2007 issue (TN5)
	07/04/24	V.2.08 Release00	V.4.02.00	.2.01.00	1.2.0.00.000						April 24, 2007 issue (TN1)
	06/12/01	V.2.07 Release00	V.4.01.01	V.2.06.00		1 / 3 ページ					December 01, 2006 issue (TN5) (Target devices added.)



· · ·		<u> </u>		1				I			
06/0		V.2.06 elease00		V.2.05.00					V2.2.0.0	V2.0.0.5	August 01, 2006 issue (TN8)
06/0		V.2.05 elease00	V.4.00.03	V.2.04.01			V2.1.0.0				July 01, 2006 issue (TN4)
06/0		V.2.04 elease00		V.2.04.00	V.1.3.00.000			V1.18			May 16, 2006 issue (TN4)
06/0		V.2.03 elease00		V.2.03.00							February 16, 2006 issue (TN1)
05/1		V.2.02 elease00	V.4.00.02	V.2.02.00					V2.0.1.0		December 01, 2005 issue (TN2)
05/1		V.2.01 elease00	V.4.00.02	V.2.01.00		V1.00			V2.0.1.0		October 16, 2005 issue (TN3) (Target devices added.)
-		V.2.00 elease04									-
05/0		V.2.00 elease03									August 01, 2005 issue (TN6)
-		V.2.00 elease 02	V.4.00.01	V.2.00.00			V2.0.0.0		V2.0.0.0		-
05/0		V.2.00 elease01									June 01, 2005 issue (TN4)
05/0		V.2.00 elease 00			V1.2.00						June 01, 2005 issue (TN4) (Target devices added.)
05/0		V.1.11 elease 01		V.1.05.00							March 16, 2005 issue (TN2)
05/0		V.1.11 elease 00	V.3.01.08								March 01, 2005 issue (TN3)
-		V.1.10 elease 00									-
04/1		V.1.09 elease 00	N 0 04 00	V.1.04.00							-
04/1		V.1.08 elease 00	V.3.01.06	V.1.03.00	V1.1.00				V1.3.1.0		-
04/0		V.1.07 elease 00					V1.2.0.0				-
04/0		V.1.06 elease 00	V.3.01.04	V1.2.00							-
04/0	6/11 \	/1.5.00	V3.0.06								- (Target devices added.)
04/0		/1.4.01/ 1.4.02		V1.1.00r1	V1.0.00						-
04/0	4/14	/1.4.00	V3.0.05	V1.1.00					V1.3.0.0		-
04/0	3/08	/1.3.00		V1.0.00					V1.2.0.0		-

*: When a High-performance Embedded Workshop with the latest version has already been installed by other products, that one is adopted. Upgrading High-performance Embedded Workshop individually is available on the download site.
 **: Be sure to install the E10A-USB emulator software before performing an E10A-USB self-diagnosing test.program. This program

is available on the download site. 2 / 3 ページ When upgrading E10A-USB emulator software on this page, the previous versions of software has to have been installed in your PC before, or the previous versions of the set-up disc has to have been in a CD drive on your PC.

Before installation of the E10A-USB emylator software, a confirmation dialog box which asks places of the previous one or the setup disc may be displayed.

The update program expands a set-up program under a temporally directory in Windows® to perform an upgrade. Files expanded under the folder is deleted automatically.

Therefore, Be sure to back up files you need before an execution of the update program.

E10A-USB Emulator Software Component List for SH-4A device group

Jun 20, 2013

			Main Com	oonents			USB driver					
Status	Released date	E10A-USB Emulator Software	High- performance Embedded Workshop	SH-4A	Firmware for SH-4A Device Group	E10AUSB Self-diagnosing program	E1usb .sys	HMSEUsb .sys	E1usbdrv .dll	usbdrv .dll	Related <u>Tool News</u>	
Latest version	13/06/16	V.3.06 Release00	V.4.09.01 *	V.3.05.00			V.4.0.0.1		V.3.1.2.0		June 16, 2013 issue (TN (Target devices added.)	
	12/10/01	V.3.05 Release00	V. 4 .00.01	V.3.04.00			V.4.0.0.1	V1.18 (32bit)	V.0.1.2.0		October 01, 2012 issue (TN4) (Target devices added.	
	12/02/16	V.3.04 Release01	V.4.09.00	V.3.03.00		V.2.01 **		V1.19 (64bit)			February 16, 2012 issu (TN10)	
	11/11/16	V.3.04 Release00	1.4.00.00	V.2.2.00.000				V.3.1.1.1		November 16, 2011 issu (TN8) (Target devices added.		
	10/12/01	V.3.03 Release00	V.4.07.01	V.3.02.00							December 01, 2010 issu (TN3) (Target devices added.	
	10/04/01	V.3.02 Release01		V.3.01.02							April 01, 2010 issue (TN	
	-	V.3.02 Release00	V.4.07.00	V.3.01.01							-	
	10/01/20	V.3.01 Release00		V.3.01.00		V.2.00			V.3.1.0.0		January 20, 2010 issue (TN1) (Target devices added.	
	09/11/01	V.3.00 Release01	V.4.05.01	V.3.00.00							November 01, 2009 issu (TN2)	
	09/07/17	V.3.00 Release00					• V.3.0.0.0				July 17, 2009 issue (TN	
	09/02/16	V.2.14 Release01		V.2.12.00	- V.2.1.01.000						February 16, 2009 iss (TN4) December 16, 2008 iss	
	08/12/16	V.2.14 Release00									December 16, 2008 issu (TN2) (Target devices added.	
	08/09/01	V.2.13 Release00	V.4.04.01	V.2.11.01							September 01, 2008 issu (TN6)	
	08/05/16	V.2.12 Release00		V.2.11.00					V.3.0.0.0		May 16, 2008 issue (TN	
	08/03/01	V.2.11 Release00		V.2.10.00							March 01, 2008 issue (TN3) (Target devices added.)	
	07/12/16	V.2.10 Release01		V.2.09.01							December 16, 2007 issu (TN8)	
	07/11/06	V.2.10 Release00	V.4.03.00	V.2.09.00	V.2.1.00.000						November 06, 2007 issu (TN1) (Target devices added.)	
	07/08/16	V.2.09 Release00		V.2.08.00							August 16, 2007 issue (TN1) (Target devices added.	
	07/06/01	V.2.08 Release01	V.4.02.00	V.2.07.00	V.2.0.00.000						June 01, 2007 issue (TN	
	07/04/24	V.2.08 Release00									April 24, 2007 issue (TN	
	06/12/01	V.2.07 Release00	V.4.01.01	V.2.06.00						V2.0.0.5	December 01, 2006 issu (TN5)	

r				. .		1	1	1		
06/08,	01 V.2.06 Release00		V.2.05.00					V.2.2.0.0		August 01, 2006 issue (TN8)
06/07/	01 V.2.05 Release00	V.4.00.03	V.2.04.01			V2.1.0.0	V1.18			July 01, 2006 issue (TN4)
06/05	V.2.04 Release00		V.2.04.00	V.1.3.00.000			V1.10			May 16, 2006 issue (TN4)
06/02	V.2.03 Release00		V.2.03.00							February 16, 2006 issue (TN1)
05/12	01 V.2.02 Release00		V.2.02.00		N/4 00					December 01, 2005 issue (TN2)
05/10	V.2.01 Release00	V.4.00.02	V.2.01.00		V1.00			V2.0.1.0		October 16, 2005 issue (TN3) (Target devices added.)
-	V.2.00 Release04									-
05/08	01 V.2.00 Release03									August 01, 2005 issue (TN6)
-	V.2.00 Release 02	V.4.00.01	V.2.00.00			V2.0.0.0		V2.0.0.0		-
05/06	01 V.2.00 Release01			V1.2.00						June 01, 2005 issue (TN4)
05/05,	V.2.00 Release 00									June 01, 2005 issue (TN4)
05/03,	V.1.11 Release 01		V.1.04.00						 March 16, 2	March 16, 2005 issue (TN2)
05/03,	01 V.1.11 Release 00	V.3.01.08								March 01, 2005 issue (TN3)
_	V.1.10 Release 00									-
04/12	07 V.1.09 Release 00		V.1.03.00							- (Target devices added.)
04/10	V.1.08 Release 00	- V.3.01.06	V.1.02.00	V1.1.00		V4 2 0 0		V1.3.1.0	-	-
04/09	/09 V.1.07 Release 00					V1.2.0.0				-
04/08	/06 V.1.06 Release 00	- V.3.01.04	1/4 4 00							-
04/06	(11 V1.5.00	V3.0.06	V1.1.00	V1.0.00						-
04/04	/20 V1.4.01/ 1.4.02									-
04/04	/14 V1.4.00	- V3.0.05	V1.0.00					V1.3.0.0		-

 *: When a High-performance Embedded Workshop with the latest version has already been installed by other products, that one is adopted. Upgrading High-performance Embedded Workshop individually is available on the download site.
 **: Be sure to install the E10A-USB emulator software before performing an E10A-USB self-diagnosing test.program. This program is available on the download site.

When upgrading E10A-USB emulator software on this page, the previous versions of software has to have been installed in your PC before, or the previous versions of the set-up disc has to have been in a CD drive on your PC.

Before installation of the E10A-USB emylator software, a confirmation dialog box which asks places of the previous one or the setup disc may be displayed.

The update program expands a set-up program under a temporaly directory in Windows® to perform an upgrade. Files expanded under the folder is deleted automatically.

Therefore, Be sure to back up files you need before an execution of the update program.

E10A-USB Emulator Software Component List for SH-2A device group

			Main Corr	ponents	Firmware for			USB	driver		
Status	Release d date	E10A-USB Emulator Software	High- performance Embedded Workshop	SH-2A	SH-2A Device Group	E10AUSB Self-diagnosing program	E1usb .sys	HMSEUsb .sys	E1usbdrv .dll	usbdrv .dll	Related <u>Tool News</u>
Latest version	13/06/16	V.3.06 Release00	V.4.09.01 *	V.3.05.00			V.4.0.0.1		V3.1.2.0		June 16, 2013 issue (TN8)
	12/10/01	V.3.05 Release00	V. 1 .03.01	V.3.00.00			V. 4 .0.0.1	V1.18 (32bit)	V3.1.2.0		October 01, 2012 issue (TN4) (Target devices added.)
	12/02/16	V.3.04 Release01	V 4 00 00	V.3.04.01		V2.01 **		V1.19 (64bit)			February 16, 2012 issue (TN10)
	11/11/16	V.3.04 Release00	V.4.09.00	V.3.04.00					V3.1.1.1		November 16, 2011 issue (TN8) (Target devices added.)
	10/12/01	V.3.03 Release00	V.4.07.01	V.3.03.00	3.0.00.000						December 01, 2010 issue (TN3) (Target devices added.)
	10/04/01	V.3.02 Release01		V.3.02.01							April 01, 2010 issue (TN4)
	-	V.3.02 Release00	V.4.07.00	V.3.02.00							-
	10/01/20	V.3.01 Release00		V.3.01.00		V2.00			V3.1.0.0		January 20, 2010 issue (TN1) (Target devices added.)
	09/11/01	V.3.00 Release01		V.3.00.01	-						November 01, 2009 issue (TN2)
	09/07/17	V.3.00 Release00	V.4.05.01	V.3.00.00			V.3.0.0.0				July 17, 2009 issue (TN1) (Target devices added.)
	09/02/16	V.2.14 Release01		V.2.13.00			v. <u>3.0.0</u> .0				February 16, 2009 issue (TN4)
	08/12/16	V.2.14 Release00								December 16, 2008 issue (TN2) (Target devices added.)	
	08/09/01	V.2.13 Release00	V.4.04.01	V.2.12.00	2.1.00.000						September 01, 2008 issue (TN6)
	08/05/16	V.2.12 Release00		V.2.11.00					V.3.0.0.0		May 16, 2008 issue (TN2)
	08/03/01	V.2.11 Release00		V.2.10.00					1.0.0.0.0		March 01, 2008 issue (TN3) (Target devices added.)
	07/12/16	V.2.10 Release01		V.2.09.00							December 16, 2007 issue (TN8)
	07/11/06	V.2.10 Release00	V.4.03.00		2.0.00.000						November 06, 2007 issue (TN1)
	07/08/16	V.2.09 Release00		V.2.08.00							August 16, 2007 issue (TN1)
	07/06/01	V.2.08 Release01	V.4.02.00	V.2.07.00						V2.0.0.5	June 01, 2007 issue (TN5)
	07/04/24	V.2.08 Release00									April 24, 2007 issue (TN1) (Target devices added.)

r	1	1	1	1	1	1	1	1	1	
06/12/01	V.2.07 Release00	V.4.01.01	V.2.06.00				V1.18			December 01, 2006 issue (TN5) (Target devices added.)
06/08/01	V.2.06 Release00		V.2.05.00			V0400		V2.2.0.0		August 01, 2006 issue (TN8)
06/07/01	V.2.05 Release00		V.2.04.00			V2.1.0.0				July 01, 2006 issue (TN4)
06/05/16	V.2.04 Release00	V.4.00.03		1.0.02.000	V1.00					May 16, 2006 issue (TN4)
06/02/16	V.2.03 Release00		V.2.00.03							February 16, 2006 issue (TN1) (Target devices added.)
05/12/01	V.2.02 Release00							V2.0.1.0		December 01, 2005 issue (TN2)
05/10/16	V.2.01 Release00	V.4.00.02								October 16, 2005 issue (TN3)
_	V.2.00 Release04					V2.0.0.0				-
05/08/01	V.2.00 Release03		V.2.00.02	-						August 01, 2005 issue (TN6)
_	V.2.00 Release 02	V.4.00.01				V2.0.0.0		V2.0.0.0		August 01, 2005 issue (TN6)
05/06/01	V.2.00 Release01		V 0 00 00							June 01, 2005 issue (TN4)
05/05/16	V.2.00 Release 00		V.2.00.00	V1.0.00.000						June 01, 2005 issue (TN4)
05/03/16	V.1.11 Release 01		V.1.00.02							March 16, 2005 issue (TN2)
05/03/01	V.1.11 Release 00	V.3.01.08	V.1.00.01							March 01, 2005 issue (TN3)
_	V.1.10 Release 00					V1.2.0.0		V1.3.1.0		-
04/12/07	V.1.09 Release 00	V 2 01 00	V.1.00.00							-
04/10/14	V.1.08 Release 00	V.3.01.06								-

* : When a High-performance Embedded Workshop with the latest version has already been installed by other

products, that one is adopted. Upgrading High-performance Embedded Workshop individually is available on the download site. **: Be sure to install the E10A-USB emulator software before performing an E10A-USB self-diagnosing test.program. This program

is available on the download site.

When upgrading E10A-USB emulator software on this page, the previous versions of software has to have been installed in your PC before, or the previous versions of the set-up disc has to have been in a CD drive on your PC. Before installation of the E10A-USB emylator software, a confirmation dialog box which asks places of the previous one or the setup

disc may be displayed.

The update program expands a set-up program under a temporally directory in Windows® to perform an upgrade. Files expanded under the folder is deleted automatically.

Therefore, Be sure to back up files you need before an execution of the update program.