

## Product Alert Notification (PAN)

**Subject:** Product Alert - ISL95810WIU8Z-T

**Publication Date:** 6/1/2016

**Effective Date:** 6/1/2016

### Revision Description:

Initial Release – Change of Moisture Sensitivity Level Rating from MSL 1 to MSL 2 for ISL95810WIU8Z-T, 8 Leads MSOP

This notification is to advise our customers that Intersil will change the Moisture Sensitivity Level (MSL) rating from MSL 1 to MSL 2 for ISL95810WIU8Z-T in the 8 Leads Mini Small Outline Plastic Package (MSOP). The labeling and packaging of the listed device will be changed accordingly.

### Reason for Change:

This is to standardize the packaging for 8 leads MSOP

### Impact on fit, form, function, quality & reliability:

The change will have no impact on the form, fit, function, quality, reliability and environmental compliance of the devices.

### Product Identification:

Product affected by this change is identifiable via Intersil's internal traceability system.

**Qualification status:** Not Applicable

**Sample availability:** 6/1/2016

**Device material declaration:** Available upon request

*Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Intersil within 30 days of the publication date.*

**For additional information regarding this notice, please contact your regional change coordinator (below)**

Americas: <a href="mailto:PCN-US@INTERSIL.COM">PCN-US@INTERSIL.COM</a>	Europe: <a href="mailto:PCN-EU@INTERSIL.COM">PCN-EU@INTERSIL.COM</a>	Japan: <a href="mailto:PCN-JP@INTERSIL.COM">PCN-JP@INTERSIL.COM</a>	Asia Pac: <a href="mailto:PCN-APAC@INTERSIL.COM">PCN-APAC@INTERSIL.COM</a>
--	--	---	--