
PRODUCT CHANGE NOTICE

**Alternate Manufacturing Site
for Intersil Product 5962-
9054901MQA**

**Refer to:
PCN12040**

Date: June 11, 2012

June 11, 2012

To: Our Valued Intersil Customer

Subject: **Alternate Manufacturing Site for Intersil Product 5962-9054901MQA – Intersil (ISP) Palm Bay, Florida**

This notice is to inform you that Intersil is using its facility located in Palm Bay, Florida as an alternate site for performing final electrical test, packing, and shipping of the 5962-9054901MQA product. This action will expand current capabilities and capacities to optimize Intersil's ability to meet customer's delivery requirements. As of this notice, all site-specific verification activities are complete.

The Intersil (ISP) facility is ISO 9001:2008, TS 16949:2009, ISO 14001:2004, and MIL-PRF-38535 QML Class Q and V certified for manufacturing of packaged products. The following summarizes the activities that were conducted prior to production release to confirm there is no impact to form, fit, function, or interchangeability of the product.

- Intersil supplied test software and product specific hardware is used at ISP.
- The test equipment validation involved the processing of ~600 units from three lots through the MIL-PRF-38535 Table IA screening operations and TCI (Technology Conformance Inspection) Groups A and C lot acceptance testing at the IPS facility.
- Continuous monitoring and comparison of the data from lots processed at multiple sites are an ongoing function of the responsible product engineers.
- The visual/mechanical inspection and packing operations are compliant to QML and JEDEC industry standards used by all Intersil subcontractors and facilities.

Product affected by this change is identifiable via Intersil's internal traceability system

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to receive product manufactured at either the current or ISP site beginning immediately.

If you have concerns with this notice, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jon Brewster
Intersil Corporation

PCN12040

CC: J. Touvell M. Carmody D. Turner J. Broline