

Product Advisory (PA)

Subject: Product Advisory for 8A34004E-000

Publication Date: 4/30/2025

Effective Date: 4/30/2025

Revision Description:

Initial Release

Description of Change:

This notice is to inform our customers that Renesas is offering the below two special part numbers to make both firmware FW4.8.7 and FW4.8.8 available to the customers with part 8A34004E-000. 8A34004E-000 will be available for customers who do not have any requirement for a specific firmware version.

Special part numbers:

- 1) 8A34004E-487 (denotes 8A34004E-000 with firmware FW4.8.7).
- 2) 8A34004E-488 (denotes 8A34004E-000 with firmware FW4.8.8)

New topmarks will be assigned to distinguish the new part numbers. There is no other change.

Affected Product List:

Current Part number	New part number for 8A34004E-000 with FW4.8.7	New part number for 8A34004E-000 with FW4.8.8
8A34004E-000NBG	8A34004E-487NBG	8A34004E-488NBG
8A34004E-000NBG#	8A34004E-487NBG#	8A34004E-488NBG#
8A34004E-000NBG8	8A34004E-487NBG8	8A34004E-488NBG8

Reason for Change:

Special part numbers are being offered so customers can use either FW4.8.7 or FW4.8.8 with part 8A34004E-000.

Impact on Fit, Form, Function, Quality & Reliability:

No impact to fit, form, function, quality and reliability.

Product Identification:

New orderable part number and new top mark to distinguish the new part numbers.

Qualification Status: Not Applicable

Sample Availability Date: 4/30/2025

Device Material Declaration: Available upon request

Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Renesas within 30 days of the publication date.

For additional information regarding this notice, please contact idt-pcn@lm.renesas.com