

# **PRODUCT ADVISORY**

## **Bar Code Label Change for Intersil's UL Recognized Components**

**Refer to:  
PA12047**

**Date: June 21, 2012**

June 21, 2012

To: Our Valued Intersil Customers

Subject: **Bar Code Label Change for Intersil's UL Recognized Components**

This advisory is to inform you that Intersil has implemented the use of a new inner/intermediate bar code label for the packing/shipping of its UL (Underwriters Laboratory) recognized components. The inner/intermediate bar code label has been updated to include the electrical rating and UL recognized component mark. Examples of the current and new bar code labels are included on the next page for reference. Implementation of the new bar code label for packing/shipping began in May 2012.

Products affected:

ISL61851ACBZ	ISL61851DCBZ	ISL61851GCBZ	ISL61851JCBZ
ISL61851ACBZ-T	ISL61851DCBZ-T	ISL61851GCBZ-T	ISL61851JCBZ-T
ISL61851AIBZ	ISL61851DIBZ	ISL61851GIBZ	ISL61851JIBZ
ISL61851AIBZ-T	ISL61851DIBZ-T	ISL61851GIBZ-T	ISL61851JIBZ-T
ISL61851BCBZ	ISL61851ECBZ	ISL61851HCBZ	ISL61851KCBZ
ISL61851BCBZ-T	ISL61851ECBZ-T	ISL61851HCBZ-T	ISL61851KCBZ-T
ISL61851BIBZ	ISL61851EIBZ	ISL61851HIBZ	ISL61851KIBZ
ISL61851BIBZ-T	ISL61851EIBZ-T	ISL61851HIBZ-T	ISL61851KIBZ-T
ISL61851CCBZ	ISL61851FCBZ	ISL61851ICBZ	ISL61851LCBZ
ISL61851CCBZ-T	ISL61851FCBZ-T	ISL61851ICBZ-T	ISL61851LCBZ-T
ISL61851CIBZ	ISL61851FIBZ	ISL61851IIBZ	ISL61851LIBZ
ISL61851CIBZ-T	ISL61851FIBZ-T	ISL61851IIBZ-T	ISL61851LIBZ-T

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products. Customers may expect to receive shipments of product using either the current or new bar code labels until the depletion of existing inventory.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,





Jon Brewster  
Intersil Corporation

PA12047

CC: J. Touvell G. Liang

## PA12047 – Inner/Intermediate Bar Code Label

### Current – Standard Label

(P) CUST P/N 12345678901234567890  

(1P) INTERSIL P/N 12345678901234567890

(1T) LOT NBR 123456789012345678




(D) 0890 (D) 0751 COUNTRY OF ORIGIN  
MALAYSIA

(Q) QTY 12345 (V) SUPPLIER INTERSIL

MSL 3 PBT:260 Deg C LLQ:1000 27S6BA

### New – Label (changed areas circled in red)

**Electrical Rating**  
Vin: 5.5Vdc; OCP: 2.5A

(1P) INTERSIL P/N ISL61853NCRZ-T   

(1T) LOT NBR VP1913.9E

(D) 1118 (D) COUNTRY OF ORIGIN  
MALAYSIA

(Q) QTY 6000 (V) SUPPLIER INTERSIL

MSL 2 PBT: 260 Deg C LLQ: 6000 27S6UL