# PRODUCT ADVISORY

# Data Sheet Specification Change for Intersil Products ICL7660A\* and ICL7660S\*

Refer to: PA13006

Date: January 23, 2013



#### January 23, 2013

### To: Our Valued Intersil Customer

## Subject: Data Sheet Specification Change for Intersil Products ICL7660A\* and ICL7660S\*

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ICL7660A\* and ICL7660S\* products. The updates require the use of an external Schottky diode from the VOUT to CAP- pins in some applications in order to guarantee latch-up free operation. Details regarding the use of the Schottky diode are contained in item 6 of the *Do's and Don'ts* section located on page 8 of the data sheet. The updated data sheet is available on the Intersil web site at <a href="http://www.intersil.com/content/dam/Intersil/documents/fn31/fn3179.pdf">http://www.intersil.com/content/dam/Intersil/documents/fn31/fn3179.pdf</a>.

Products affected:

ICL7660ACBA	ICL7660AIBA	ICL7660SCBAZ	ICL7660SIBAT
ICL7660ACBA-T	ICL7660AIBA-T	ICL7660SCBAZ-T	ICL7660SIBAZ
ICL7660ACBAZA	ICL7660AIBAZA	ICL7660SCBAZ-TS2568	ICL7660SIBAZT
ICL7660ACBAZA-T	ICL7660AIBAZA-T	ICL7660SCPA	ICL7660SIPA
ICL7660ACPA	ICL7660SCBA	ICL7660SCPAZ	ICL7660SIPAZ
ICL7660ACPAZ	ICL7660SCBA-T	ICL7660SIBA	

There have been no changes made to the die/silicon or device itself. There will be no change in external marking of the packaged parts.

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for manufacturing of material supplied today.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,

fon Brewster

Jon Brewster Intersil Corporation

PA13006

CC: J. Touvell D. Bruss C. Brazil P. Orfanu

