

# RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan  
Renesas Electronics Corporation

Product Category	Photocoupler		Document No.	TN-DIO-A0086A/E	Rev.	1.00
Title	Isolation Distance Correction of errors		Information Category	Technical Notification		
Applicable Product	RV1S2451ACCSP-10YC#KC0	Lot No.	Reference Document	Data Sheet RV1S2451A R08DS0290EJ0200		
	RV1S2451ACCSP-10YC#SC0	ALL Lot				
	RV1S2451ACCSP-10YV#KC0					
	RV1S2451ACCSP-10YV#SC0					

1. Reason for change : Correction of errors

2. Details of change : Corrected the Isolation Distance MIN. from 0.4 mm to 0.15 mm in the data sheet

< Before >

Parameter	MIN.
Isolation Distance	0.4 mm

< After >

Parameter	MIN.
Isolation Distance	0.15 mm