

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
RenesasTechnology Corp.

Product Category	User Development Environment		Document No.	TN-EML-A134A/E	Rev.	1.00
Title	Problem with Conditional Trace in the H8 300H Tiny E6000 Emulator		Information Category	Technical Notification		
Applicable Product	H8/3664 E6000 Emulator (HS3664EPI62H)	Lot No.	Reference Document	H8 Family / H8/300H Tiny Series Emulator User 's Manual HS3664EPI62HE-U2 (REJ10J1133-0500 Rev.5.00)		
		Serial No. 0001 to 0077				

Thank you for using our product.

There is a problem with the H8/3664 E6000 emulator having any of the serial numbers defined above. Please read this document carefully before using the emulator.

[Problem]

If a conditional trace is executed using eventpoints, trace information will not be acquired or displayed correctly.

[Solution]

For customers intending to execute a conditional trace, we will update the emulator hardware. Please contact the Renesas sales office, where you have purchased the product. After the update, the revision of the emulator hardware will be 'C' or later.

Note: The serial number is written on the label on the back of the E6000 emulator.

