

RENESAS TECHNICAL UPDATE

1753, Shimonumabe, Nakahara-ku, Kawasaki-shi, Kanagawa 211-8668 Japan
 Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RX-A016A/E	Rev.	1.00
Title	Restriction on 5V Tolerant Port in RX210 Group		Information Category	Technical Notification		
Applicable Product	64-pin LQFP of RX210 Group	Lot No.	Reference Document	RX210 Group User's Manual: Hardware Rev.1.10 (R01UH0037EJ0110)		
		All				

1. Restriction

Port P17 in the following products in the RX210 Group is not 5V tolerant (only port P16 is 5V tolerant):

R5F52108ADFM, R5F52107ADFM, R5F52106ADFM, R5F52105ADFM

R5F52108AGFM, R5F52107AGFM, R5F52106AGFM, R5F52105AGFM