

[Notes]

R20TS0924EJ0100

Rev.1.00

Feb. 16, 2023

CS+ Update Manager

Outline

When using the CS+ integrated development environment, note the following points.

1. Using the CS+ Update Manager

1. Using the CS+ Update Manager

1.1 Applicable Products

CS+ Integrated Development Environment for CC V3.00.00 and later versions

CS+ Integrated Development Environment for CA,CX V3.00.00 and later versions

CS+ Update Manager V2.02.00 and later versions

1.2 Applicable Devices

All MCUs that support CS+ for CC and CS+ for CA,CX

1.3 Details

The CS+ Update Manager may crash while installing updates without displaying the Finish page.

1.4 Conditions

This may occur if you have selected and installed multiple updates after January 20, 2023.

1.5 Workaround

Please update CS+ by one of the following methods.

- ① Download and execute the latest installer from the web page
 - CS+
<https://www.renesas.com/software-tool/cs>
 - Smart Configurator
<https://www.renesas.com/software-tool/smart-configurator>
 - PG-FP6
<https://www.renesas.com/software-tool/pg-fp6>
- ② Launch CS+ Update Manager again after a crash to install updates any incomplete updates
The installation history of updates that had been installed before the abnormal termination is not displayed in the update history, but if it is not displayed in the update list after restarting CS+ Update Manager, the installation has been completed successfully.

1.6 Schedule for Fixing the Problem

This problem will be fixed in the next version update of CS+ Update Manager, which is schedule to be released in April 2023.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Feb.16.23	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/