

RENESAS TOOL NEWS on September 1, 2005: RSO-E7_1-050901D

The E7 Emulator Software Revised to V.3.00 Release 01

The emulator software for the E7 on-chip debugging emulator has been revised from V.3.00 Release 00 to V.3.00 Release 01

1. Description of Revision

The following known problems have been fixed:

- (1) On debugging programs for the H8/38347F and H8/38327F MCUs, H8/300L Super Low Power series
For details, see RENESAS TOOL NEWS "A Note on Using the E7 Emulator Software V.3.00 Release 00" (No. RSO-E7-050812D), issued on August 12, 2005.
- (2) On debugging programs for the H8/300H Tiny, H8/300H Super Low Power, and H8/300L Super Low Power series of MCUs
For details, see RENESAS TOOL NEWS "A Note on Using an E7 Emulator Software V.3.00 Release 00" (No. RSO-E7_2-050901D), issued on September 1, 2005.

2. How to Update Your Product

Free-of-charge online update is available.

The procedure is as follows:

- (1) Download the update program (.EXE file) from **HERE**.
- (2) Execute the downloaded executable file to invoke the installer. Then follow its instructions.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.