

Outline

CS+ Device Information for RX Family has been updated from V3.15.00 to V3.16.00.

1. Products to Be Updated

- CS+ Device Information for RX V1.04.00 or later
- CubeSuite+ Device Information for RX (CubeSuite+ DevInfo_RX) V1.03.00 or earlier

To check the version of "CS+ Device Information for RX" or "CubeSuite+ DevInfo_RX", follow the instructions under [Components] at the URL below.

<https://www.renesas.com/cs+ ver>

2. Description

The main changes are as follows. Refer to the link below for details.

(Information will be uploaded on April 21.)

https://www.renesas.com/cs+/eng/CSPlus_DevInfo_RX.html

2.1 Issues Fixed

The following issues have been fixed.

2.1.1 The problem listed in the RENESAS TOOLNEWS Document No. R20TS1085EJ0100 has been fixed.

Note on the I/O Header File for the RX66N, RX72M and RX72N Groups.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts1085>

2.1.2 When generating a project for RX13T, the following incorrect statement in the generated I/O header file (iodefine.h) has been corrected.

Wrong	Right
<pre>union { unsigned short WORD; union { struct { unsigned short DIAGST:2; unsigned short :2; unsigned short AD:12; } RIGHT; struct { unsigned short AD:12; unsigned short :2; unsigned short DIAGST:2; } LEFT; } BIT; } ADRD;</pre>	<pre>unsigned short ADRD;</pre>

3. Updating the Product

3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

- (1) On the Start menu, select Programs → Renesas Electronics CS+ to start the Update Manager.

(This service will be available on April 21.)

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

- (2) Download and install the desired software tools from the following URL:

(The program will be available on April 21.)

https://www.renesas.com/cs+_download

3.2 For CubeSuite+ V2.00.00 to 2.02.00

Update your program in the same way as described in section 3.1 above.

3.3 For CubeSuite+ V1.03.00 or Earlier

Download and install the evaluation edition of CS+ for CC V8.13.00 from the following URL. Then, update your program in the same way as described in section 3.1 above.

https://www.renesas.com/cs+_download

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Apr.20.25	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/