

[Upgrade to revision]

R20TS0629EJ0100

Rev.1.00

Oct. 16, 2020

e² studio Code Generator Plug-in V2.17.0, AP4 Coding Assistance Tool for RZ V1.10.00

Outline

The products in the title have been revised and their version numbers have been changed as follows.

- (1) e² studio Code Generator plug-in: V2.15.0 to V2.17.0
- (2) AP4 for RZ: V1.09.00 to V1.10.00

1. Versions to Be Updated

- All revisions up to 2020- 07 of e² studio (V2.15.0 of Code Generator plug-in)
- All revisions up to V1.09.00 of AP4 for RZ

2. Items Revised

The major revision points are described in section 2.1. Refer to the following release notes for details.

- e² studio Code Generator plug-in
e² studio 2020-10 Release Note
<https://www.renesas.com/search/keyword-search.html#q=R20UT4838&genre=document>
- AP4 Coding Assistance Tool for RZ
AP4 for RZ V1.10.00 Release Note
<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4676>

2.1 Description of Modification

The problems regarding the points below have been fixed.

- (1) RENESAS TOOL NEWS, Document No. R20TS0603EJ0100

1. Notes on switching register set on transfer completion of the DMA controller

Applicable devices: RZ/T1 group

For details about the problems, refer to the following URL:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0603>

3. How to Update Your Copy

The method of updating depends on the product you are using.

For details, refer to the following. The updates are available free of charge.

3.1 For e² studio Code Generator plug-in

For the method of updating e² studio, refer to section 3, "Updating Your Product" in RENESAS TOOL NEWS, Document No. R20TS0605EJ0100.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0605>

You cannot update Code Generator plug-in by itself.

3.2 For AP4 for RZ

Download the installer from the following URL, and then install the program.

https://www.renesas.com/applilet_download

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Oct.16.20	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,
Koto-ku, Tokyo 135- 0061, Japan

www.renesas.com

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.