

---

[Upgrade to revision]

R20TS0751EJ0100

Rev.1.00

Oct. 1, 2021

e<sup>2</sup> studio Smart Configurator Plug-in V2.11.0,  
RX Smart Configurator V2.11.0

---

## Overview

The products in the title will be revised and their version numbers will be changed as follows:

- (1) e<sup>2</sup> studio Smart Configurator Plug-in: V2.10.0 to V2.11.0
- (2) RX Smart Configurator: V2.10.0 to V2.11.0

## 1. Version to Be Updated

- All revisions up to 2021-07 of e<sup>2</sup> studio (V2.10.0 of Smart Configurator Plug-in)
- All revisions up to V2.10.0 of RX Smart Configurator

## 2. Items Revised

The major revision points are as follows. Refer to the following release note for details.

- RX Smart Configurator  
Smart Configurator for RX V2.11.0 Release Note. This information is already exhibited by on Sep. 29.  
<https://www.renesas.com/software-tool/smart-configurator#documents>

### 2.1 Addition of Supported MCUs

Support for the following device groups has been added.

RX family: RX140 groups

For the list of supported MCUs, refer to the URL below.

<https://www.renesas.com/smart-configurator>

### 2.2 Description of Modification

The problems regarding the points below have been fixed.

(1) RENESAS TOOL NEWS, Document No. R20TS0735ES0100

1. When using Port Output Enable (POE) component and configuring MTU pins as high impedance

Applicable devices: RX23W (56 pins), RX24T (64 pins), RX64M (100 pins), RX651 (64 pins),  
RX71M (100 pins) and RX72M (100 pins) Group

For details about the problems, refer to the following URL:

<https://www.renesas.com/us/en/document/tnn/notes-e2-studio-smart-configurator-plug-smart-configurator-rx>

## 3. How to Update Your Copy

The method of updating depends on the product you are using.

For details, refer to the following. The updates are available free of charge.

### 3.1 For e<sup>2</sup> studio

For the method of updating e<sup>2</sup> studio, refer to section 3, “Updating Your Product” in the following Tool News. This information will be released on Oct 6.

<https://www.renesas.com/software-tool/e-studio#documents>

RENESAS TOOL NEWS, Oct 1, Document No. R20TS0758EJ0100

[Upgrade to version] e<sup>2</sup> studio Integrated Development Environment 2021-10

Note that by updating e<sup>2</sup> studio, the Smart Configurator will also be updated.

### 3.2 For CS+

To update your program, use either of the following methods:

Download RX Smart Configurator from the following URL, and then install the program.

The program will be available from Sep 29.

<https://www.renesas.com/software-tool/smart-configurator#downloads>

Smart Configurator for RX V2.11.0

For details about the guidance of Smart Configurator, visit the following website:

<https://www.renesas.com/smart-configurator>

**Revision History**

Rev.	Date	Description	
		Page	Summary
1.00	Oct.1.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

**Corporate Headquarters**

TOYOSU FORESIA, 3- 2- 24 Toyosu,  
Koto-ku, Tokyo 135- 0061, Japan

[www.renesas.com](http://www.renesas.com)

**Trademarks**

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

**Contact information**

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

[www.renesas.com/contact/](http://www.renesas.com/contact/)